

WORK ORDER WO-2022-0808

Work Order No: WO-2022-0808 Type: CM Priority: P3

Equipment: P-103 Date completed: 2022-08-19

Title: P-103 booster pump seal failure

FINDINGS / WORK PERFORMED:

MS-40D seal failed after wet-season operation. Same abrasive scoring signature as P-101 history. P-103 takes suction downstream of E-201 but shares the same cooling water quality.

Parts used: MS-40D cartridge seal x1

Labor hours: 11 Equipment downtime: 6 h

Raised by: A. Deshpande (Maintenance Planner)

Closed by: S. Venkatesan (Shift Supervisor)

Reference drawing: D-CW-104 rev 3