

E	Description of Variation Requested	Specify Point of Departure from Standard / Code of Practice (List section and page number)	Justification (Why is this necessary)	Additional Counter Measures To Be Taken (Identify additional counter measures to be used to negate the lesser treatment)	Residual Risk*		
					L	C	RR
	No speed reinstatement on some Mobile Works Convoys due to lack of lead vehicle causing vehicles to be unsure of end of temporary speed zone.	AGTTM Part 4 Mobile Works Section 3.8.4 Mobile Temporary Speed Zone requires 'For works where a lead vehicle is not required, the speed zone must be placed between the work vehicle and the shadow vehicle'. <i>Page 32.</i>	There is only 20-40m between the shadow vehicle and work vehicle which is to display the temporary speed sign and termination speed sign which may cause conflicting messages to road users. Road users may increase speed between the shadow vehicle and work vehicle increasing risk to the work vehicle.	On state roads the number of repeater speed signs is frequent. For rural areas, where an on-site risk assessment identifies insufficient repeaters or significant impacts to road users, an additional lead vehicle should be implemented.	C	3	M9
	Regulatory and lane status sign within mobile convoy alternated with another sign causing conflicting messages for motorists.	AS 1742.3 Section 4.22.3 Message Screens (g) requires 'When a variable message sign displaying regulatory, or lane status signs is used to substitute a static sign the message shall not be alternated with another message'. <i>Page 77.</i>	Not alternating the messaging will require additional convoy vehicles or a lack in notification to road users approaching the convoy.	Adequate sight distance to the vehicles VMS Board to be maintained where possible. Speed and driver compliance to be monitored by the shadow vehicle driver within the mobile convoy.	D	4	M8