



GREY BANNER ALERT



mainroads
WESTERN AUSTRALIA


SHW Serious Incident (SI) – Final Notice

Date of Incident:	7 th July 2023	Time of Incident:	9.30am
Region / Directorate:	MET – Metro	Main Roads or Contractor:	Contractor
EQSafe Event Type:	Injury/ Illness	EQSafe Incident Number:	32512
Actual Consequence:	Moderate	Potential Consequence:	Catastrophic

Incident Short Description:	MOP collides with stationary Traffic Control utility, injuring Traffic Controller.
------------------------------------	--

Executive Summary:
At approximately 9.30am on Friday 7th July, a Member of Public (MoP) was travelling in a north westerly direction towards the traffic signalled intersection. An Electrical Contractor was at this location performing CCTV camera maintenance and was utilising the services of a sub-contractor to provide Traffic Management (TM). For reasons unknown, the MoP has left the road and travelled approximately 120m through the verge, missing large trees and an electrical pillar, and has collided with the stationary and unoccupied TM utility situated approximately 10-12m off the roadway. When the MoP has collided with the TM utility, the force of the collision has caused the utility to strike a Traffic Controller (TC) who was standing outside of the cab and has forced him to the ground. No other persons were injured. The on-site Foreman has contacted emergency services and their immediate Supervisor. Works were ceased. WA Police and St John Ambulance have attended the scene, where the TC was attended to immediately and transferred to a hospital. TC was released from hospital at approximately 1.30pm on the same day and did not require treatment.

Incident Photos:



Google Maps overhead view of location.



Member of Public Vehicle



Traffic Management utility

Contributing Factors:

- No consideration was made regarding a vehicle being operated in the manner observed or travelling the route taken and any other associated risks of this form of MOP behaviour.
- The MOP failed to drive his vehicle in a manner that was inconsistent with the normal understanding of a licenced motor vehicle driver.
- The risk of a vehicle entering the site in the manner it did was not recognised.
- The environment of this location did not lead the onsite team to consider that a vehicle would enter the work site in the manner encountered.

Corrective Actions:

- The MOP's unconventional driving highlights divergence from safe driving behaviour. Stakeholders aim to enhance awareness and acknowledge limited control over public actions.
- Improvement in situational awareness and reducing complacency would increase the likelihood of earlier recognition of the hazard and thus reduce the risk and potential severity.

Additional Issues/Learnings:



Critical Risk:

This serious potential incident aligns with the Main Roads Critical Risk Profile relating to Interaction with Live Traffic.

Distribution of Notice:

Main Roads Personnel and Contracting Organisations