



Document Number: SCN064639

Revision: A

Group: Scanned (Hardcopy) Item

Type: Environmental Reports - Svs Ctr

State: Released

Latest Released: YES

Implemented Date: 05/20/2019

Stamp Date: Monday, May 20, 2019 4:12:35 PM EST

viewLinc Alarm Report

Report name	ETHICON Quarterly Report
Alarm events	from 2019-01-01 12:00:00 to 2019-04-01 12:00:00
Report generated on	2019-04-01 12:11:39 (UTC-05:00) Eastern Time (US & Canada)
Include zones and locations:	System/ETHICON
Include alarm details:	No
Include system alarms:	Yes
Include device communication alarms:	Yes
Include device configuration alarms:	Yes
Include device validation alarms:	Yes
Include device calibration alarms:	Yes
Include threshold alarms:	Yes
Include threshold categories:	Alarms Only

Summary

Total active alarms:	544
Activated alarms:	544
Deactivated alarms:	544
Acknowledged alarms:	80

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-09 05:47:08	2019-01-09 06:13:18	26 minutes, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 09:27:03	2019-01-09 09:28:08	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 09:30:06	2019-01-09 12:19:53	2 hours, 49 minutes, 47 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 09:31:08	2019-01-09 09:39:11	8 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-09 10:45:52	2019-01-09 10:49:20	3 minutes, 28 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-09 12:54:09	2019-01-09 12:55:14	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-09 12:56:20	2019-01-09 12:57:24	1 minute, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-09 13:17:30	2019-01-09 13:17:30	18 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-09 13:17:41	2019-01-09 13:18:43	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-09 13:22:30	2019-01-09 13:22:31	21 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-09 13:24:52	2019-01-09 15:27:17	2 hours, 2 minutes, 25 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-09 13:31:59	2019-01-09 13:43:14	11 minutes, 15 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-09 15:27:30	2019-01-09 15:28:23	53 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 15:31:23	2019-01-09 15:33:29	2 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 15:39:30	2019-01-09 15:40:32	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 15:42:39	2019-01-09 15:43:37	58 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 15:47:30	2019-01-09 15:48:44	1 minute, 14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-09 17:30:17	2019-01-09 18:35:39	1 hour, 5 minutes, 22 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-09 17:32:19	2019-01-09 17:42:25	6 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-09 21:37:20	2019-01-09 21:44:20	7 minutes	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-09 21:39:21	2019-01-09 22:18:32	39 minutes, 11 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)
2019-01-09 22:25:35	2019-01-09 22:27:30	1 minute, 55 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-10 01:38:26	2019-01-10 01:39:30	1 minute, 4 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11922)
2019-01-10 01:39:27	2019-01-10 02:09:36	30 minutes, 9 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)

Activation	Deactivation	Duration	Source	Description	Acknowledgement:
2019-01-10 01:40:28	2019-01-10 01:43:30	3 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-10 05:40:27	2019-01-10 05:41:28	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-10 05:41:28	2019-01-10 05:42:30	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-10 05:42:30	2019-01-10 06:11:00	28 minutes, 30 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-10 05:43:32	2019-01-10 05:44:37	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-10 09:43:01	2019-01-10 09:44:09	1 minute, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-10 13:45:03	2019-01-10 14:00:10	15 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-15 06:22:16	2019-01-15 06:37:19	15 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-15 06:37:30	2019-01-15 06:38:23	53 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 02:49:36	2019-01-20 02:50:36	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-20 02:51:37	2019-01-20 03:19:44	28 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-20 03:27:30	2019-01-20 03:28:49	1 minute, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-20 06:45:25	2019-01-20 06:52:25	7 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-20 06:46:25	2019-01-20 09:57:28	3 hours, 11 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-20 10:01:48	2019-01-20 10:04:54	3 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-20 10:05:57	2019-01-20 10:08:02	2 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-20 10:09:00	2019-01-20 10:10:02	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 10:11:03	2019-01-20 10:14:08	3 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 10:16:12	2019-01-20 10:17:14	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 10:17:30	2019-01-20 10:18:18	48 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 10:22:21	2019-01-20 10:24:24	2 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 10:26:26	2019-01-20 10:30:31	4 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-20 10:31:32	2019-01-20 13:48:35	3 hours, 17 minutes, 3 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 32.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-20 10:37:38	2019-01-20 10:53:53	16 minutes, 15 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 32.9 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)
2019-01-20 14:04:57	2019-01-20 14:06:00	1 minute, 3 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-20 14:07:30	2019-01-20 14:08:04	34 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-20 14:43:16	2019-01-20 18:18:35	3 hours, 35 minutes, 19 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-20 14:44:13	2019-01-20 14:55:36	11 minutes, 23 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.1 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-20 18:21:37	2019-01-20 18:25:39	4 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing T RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 18:41:53	2019-01-20 18:55:05	13 minutes, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 32.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 19:55:38	2019-01-20 19:57:41	2 minutes, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 33.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-20 20:11:10	2019-01-20 20:20:20	9 minutes, 10 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-20 20:27:24	2019-01-20 20:37:36	10 minutes, 12 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-20 20:46:42	2019-01-20 20:59:20	38 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-20 20:53:45	2019-01-20 20:57:30	3 minutes, 45 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-20 20:59:55	2019-01-20 21:08:58	9 minutes, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-20 21:17:02	2019-01-20 22:00:09	43 minutes, 7 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-20 22:01:06	2019-01-20 22:09:19	8 minutes, 13 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-20 22:09:20	2019-01-20 22:14:31	5 minutes, 11 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-20 22:16:28	2019-01-21 09:12:47	10 hours, 56 minutes, 19 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.34 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-20 22:50:44	2019-01-20 22:55:49	5 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing RH Min value: 34.40 %RH Max value: 34.90 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-20 22:52:30	2019-01-20 23:52:06	59 minutes, 36 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.90 %RH Max value: 34.90 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 00:02:23	2019-01-21 00:04:25	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.80 %RH Max value: 34.90 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 00:05:26	2019-01-21 00:11:32	6 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.80 %RH Max value: 34.90 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 00:17:42	2019-01-21 00:18:39	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.00 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.90 %RH Max value: 34.90 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-21 02:48:52	2019-01-21 02:55:57	5 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH
2019-01-21 02:51:53	2019-01-21 04:08:31	1 hour, 16 minutes, 38 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH
2019-01-21 03:07:14	2019-01-21 03:07:30	16 seconds	System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T
2019-01-21 03:08:20	2019-01-21 08:29:08	5 hours, 20 minutes, 48 seconds	System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T
2019-01-21 04:09:33	2019-01-21 04:21:41	12 minutes, 8 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH
2019-01-21 04:27:48	2019-01-21 04:28:46	58 seconds	System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-21 06:51:51	2019-01-21 06:59:14	7 minutes, 23 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-21 08:52:30	2019-01-21 09:03:45	2 hours, 11 minutes, 15 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.1 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 08:32:30	2019-01-21 08:36:17	3 minutes, 47 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 35.0 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-01-21 09:07:11	2019-01-21 09:08:23	1 minute, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 09:11:34	2019-01-21 09:12:30	56 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 09:20:09	2019-01-21 09:24:21	4 minutes, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-21 09:25:38	2019-01-21 09:26:54	16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-21 09:52:12	2019-01-21 09:56:36	4 minutes, 24 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-21 09:57:30	2019-01-21 13:12:12	3 hours, 14 minutes, 42 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-21 10:43:10	2019-01-21 10:59:20	16 minutes, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1922)	
2019-01-21 11:02:47	2019-01-21 11:08:05	5 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-21 13:12:30	2019-01-21 13:13:17	47 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 13:17:21	2019-01-21 13:23:35	6 minutes, 14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 13:28:43	2019-01-21 13:29:44	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 14:52:58	2019-01-21 15:01:42	8 minutes, 44 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-21 15:53:17	2019-01-21 15:53:17	56 minutes, 56 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.5 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	
2019-01-21 15:03:45	2019-01-21 15:04:20	35 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-21 18:50:44	2019-01-21 19:01:04	10 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-01-21 20:53:52	2019-01-21 20:26:09	1 hour, 32 minutes, 17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-21 20:32:11	2019-01-21 20:35:12	3 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-21 20:36:13	2019-01-21 20:37:13	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-21 20:37:30	2019-01-21 20:41:15	3 minutes, 45 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-21 22:14:13	2019-01-21 22:15:17	1 minute, 4 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-21 22:41:36	2019-01-21 22:44:20	2 minutes, 44 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-21 22:56:41	2019-01-21 23:45:50	49 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing T Min value: 34.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing T (11922)	
2019-01-21 22:57:41	2019-01-21 23:01:41	4 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-21 22:58:40	2019-01-21 23:07:42	9 minutes, 2 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-21 23:08:43	2019-01-21 23:19:20	10 minutes, 37 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-21 23:19:47	2019-01-21 23:20:43	56 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-21 23:26:44	2019-01-21 23:41:50	15 minutes, 6 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)
2019-01-21 23:47:54	2019-01-21 23:53:01	5 minutes, 7 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)
2019-01-21 23:49:59	2019-01-22 00:02:18	12 minutes, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-21 23:54:00	2019-01-21 23:54:20	20 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)
2019-01-22 00:01:18	2019-01-22 00:10:23	9 minutes, 5 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)
2019-01-22 00:19:20	2019-01-22 00:27:30	8 minutes, 10 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)

Activation	Deactivation	Duration	Source	Description	Acknowledgement:
2019-01-22 00:35:33	2019-01-22 00:39:20	3 minutes, 47 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	
2019-01-22 00:41:33	2019-01-22 00:42:33	1 minute	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	
2019-01-22 00:54:40	2019-01-22 00:55:36	56 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	
2019-01-22 02:59:20	2019-01-22 03:00:38	1 minute, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2019-01-22 03:03:45	2019-01-22 03:37:50	34 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-22 03:46:05	2019-01-22 03:48:13	2 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-22 03:49:10	2019-01-22 03:51:13	2 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-22 07:07:30	2019-01-22 07:45:48	38 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-22 07:50:53	2019-01-22 07:51:52	59 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-22 07:52:30	2019-01-22 07:52:56	26 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-22 07:57:30	2019-01-22 07:58:54	1 minute, 24 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-24 09:48:57	2019-01-24 09:56:01	7 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-25 01:49:39	2019-01-25 02:23:06	33 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-25 01:50:40	2019-01-25 01:55:47	5 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-25 05:45:25	2019-01-25 08:32:30	2 hours, 47 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-01-25 05:45:25	2019-01-25 05:56:34	11 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-25 08:32:38	2019-01-25 08:33:37	59 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-25 08:38:47	2019-01-25 08:51:19	12 minutes, 32 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-25 08:52:21	2019-01-25 09:03:40	11 minutes, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-25 09:07:53	2019-01-25 09:20:04	12 minutes, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-25 09:21:05	2019-01-25 12:49:34	3 hours, 28 minutes, 29 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 30.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-25 09:39:50	2019-01-25 10:13:27	33 minutes, 37 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-25 10:25:01	2019-01-25 10:27:06	2 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-25 12:50:40	2019-01-25 12:51:42	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-25 13:42:43	2019-01-25 13:43:40	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-25 13:44:40	2019-01-25 14:48:33	1 hour, 3 minutes, 53 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-25 13:48:40	2019-01-25 13:58:47	10 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-25 14:52:39	2019-01-25 14:53:41	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	
2019-01-25 17:54:45	2019-01-25 18:00:12	5 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-25 17:57:05	2019-01-25 18:36:02	38 minutes, 57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-25 21:52:46	2019-01-25 21:56:51	4 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-25 22:00:52	2019-01-25 22:20:15	19 minutes, 23 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)
2019-01-27 10:07:10	2019-01-27 10:25:20	18 minutes, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-27 10:26:20	2019-01-27 10:27:20	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-01-27 10:27:30	2019-01-27 10:29:21	1 minute, 51 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-27 14:07:08	2019-01-27 14:18:14	11 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-27 18:12:21	2019-01-27 18:20:26	8 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-27 22:09:41	2019-01-27 22:10:38	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-27 22:13:39	2019-01-27 22:31:39	18 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-27 22:32:43	2019-01-27 22:33:40	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-28 02:12:30	2019-01-28 02:14:12	1 minute, 42 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-28 02:22:25	2019-01-28 02:24:26	2 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 02:11:35	2019-01-29 02:44:05	32 minutes, 30 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 02:12:36	2019-01-29 02:17:40	5 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 02:45:05	2019-01-29 02:49:16	4 minutes, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.4 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-29 02:50:16	2019-01-29 02:59:45	9 minutes, 29 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 06:12:06	2019-01-29 07:25:06	1 hour, 13 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-29 06:13:07	2019-01-29 06:22:14	9 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-29 07:33:17	2019-01-29 07:34:13	56 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 09:12:53	2019-01-29 09:14:52	1 minute, 59 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 09:14:20	2019-01-29 09:14:55	35 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 09:15:53	2019-01-29 09:18:00	2 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 09:18:59	2019-01-29 09:22:02	3 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-29 09:22:30	2019-01-29 09:23:08	38 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-29 09:26:09	2019-01-29 09:50:29	24 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-29 09:52:30	2019-01-29 09:53:30	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-29 09:54:31	2019-01-29 09:55:33	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-29 09:56:33	2019-01-29 09:58:35	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-29 10:00:37	2019-01-29 11:57:12	1 hour, 56 minutes, 35 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-29 10:06:43	2019-01-29 10:22:56	16 minutes, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-29 11:57:30	2019-01-29 12:00:13	2 minutes, 43 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 12:48:44	2019-01-29 12:52:30	3 minutes, 46 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.2 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 12:52:47	2019-01-29 12:53:47	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.3 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-29 12:52:50	2019-01-29 12:57:54	5 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 12:58:50	2019-01-29 13:00:50	2 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-29 13:04:53	2019-01-29 13:30:01	25 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 13:32:30	2019-01-29 13:33:05	35 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 13:41:06	2019-01-29 13:49:08	8 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 14:02:12	2019-01-29 15:46:19	1 hour, 44 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 14:10:20	2019-01-29 14:24:20	14 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 31.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 14:25:25	2019-01-29 14:26:25	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.2 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-29 14:29:20	2019-01-29 14:29:29	9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-29 14:34:20	2019-01-29 14:34:34	14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-29 18:10:38	2019-01-29 19:32:30	1 hour, 21 minutes, 52 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 18:12:38	2019-01-29 18:23:43	11 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-29 19:32:35	2019-01-29 19:39:40	7 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 19:51:59	2019-01-29 19:55:00	3 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-29 19:57:30	2019-01-29 19:58:06	36 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-29 22:26:54	2019-01-29 22:30:56	4 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-30 02:11:48	2019-01-30 02:15:56	4 minutes, 8 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 RH Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-30 02:12:52	2019-01-31 12:26:55	1 day, 10 hours, 14 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 23.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-30 02:13:56	2019-01-30 02:26:03	12 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 02:17:57	2019-01-30 14:11:38	11 hours, 53 minutes, 41 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 67.67 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 03:36:38	2019-01-30 03:38:41	2 minutes, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-01-30 03:46:54	2019-01-30 11:50:54	8 hours, 4 minutes	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.45 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-01-30 06:07:50	2019-01-30 06:50:22	42 minutes, 32 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 31.3 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 06:52:24	2019-01-30 06:54:20	1 minute, 56 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 06:55:27	2019-01-30 06:59:20	3 minutes, 53 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 07:04:20	2019-01-30 07:06:38	2 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 07:09:43	2019-01-30 07:10:40	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.4 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 07:16:46	2019-01-30 07:17:46	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 07:19:20	2019-01-30 07:20:52	1 minute, 32 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 07:29:01	2019-01-30 07:30:05	1 minute, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 08:03:28	2019-01-30 08:05:29	2 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 08:15:35	2019-01-30 08:17:38	2 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 08:18:39	2019-01-30 08:19:20	41 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 33.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 08:22:39	2019-01-30 08:23:40	2 minutes, 56 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 08:23:40	2019-01-30 08:24:20	40 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 08:27:40	2019-01-30 08:28:40	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 08:32:41	2019-01-30 08:34:20	1 minute, 39 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 08:34:49	2019-01-30 08:40:46	5 minutes, 57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 08:41:47	2019-01-30 08:42:47	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	System/ETHICON/Repair & Testing RH (11918)
2019-01-30 08:46:48	2019-01-30 08:59:56	13 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	System/ETHICON/Repair & Testing RH (11918)
2019-01-30 09:01:01	2019-01-30 09:16:09	15 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	System/ETHICON/Repair & Testing RH (11918)
2019-01-30 09:17:10	2019-01-30 09:18:12	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	System/ETHICON/Repair & Testing RH (11918)
2019-01-30 09:23:17	2019-01-30 09:25:22	2 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	System/ETHICON/Repair & Testing RH (11918)
2019-01-30 09:26:22	2019-01-30 09:45:45	19 minutes, 23 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	System/ETHICON/Repair & Testing RH (11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 09:46:46	2019-01-30 09:56:54	10 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-01-30 10:02:30	2019-01-30 13:12:30	2 hours, 21 minutes, 26 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-01-30 10:07:02	2019-01-30 10:55:08	3 hours, 10 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-01-30 10:12:07	2019-01-30 10:35:34	23 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Acknowledged on 2019-01-30 16:47:45 by ibitari' (Ibrahim Bitar). "None taken", comment: Technicians had been in a meeting and there weren't any products being worked on during this time. Door had been broken and fixed which allowed the humidity to return back to normal
2019-01-30 10:38:37	2019-01-30 10:39:42	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Acknowledged on 2019-01-30 16:47:45 by ibitari' (Ibrahim Bitar). "None taken", comment: Technicians had been in a meeting and there weren't any products being worked on during this time. Door had been broken and fixed which allowed the humidity to return back to normal

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 10:40:43	2019-01-30 10:41:44	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH Min value: 29.7 %RH Max value: 29.7 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2019-01-30 17:17:11 by ibitar1 (Ibrahim Bitar): "No Action Taken" comment: Technicians had been in a meeting and there weren't any products being worked on during this time. Door had been broken and fixed which allowed the humidity to return back to normal. Alarm was running for 1 minute and 1 second.
2019-01-30 11:18:25	2019-01-30 11:23:38	5 minutes, 13 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low Threshold: location value less than 15.0 %RH for System/ETHICON/Receiving&Decontamination RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 15.0 %RH for System/ETHICON/Receiving&Decontamination RH Min value: 9.3 %RH Max value: 14.1 %RH Affected location: System/ETHICON/Receiving&Decontamination RH (1912)	Acknowledged on 2019-02-01 15:50:04 by ibitar1 (Ibrahim Bitar): "NCR NR-0116615 Created", comment: This alarm was caused because the temperatures outside had reached extreme lows. A NCR (NR-0116615) was created so that we can record the actions taken. Humidity had dropped below storage limit for less than 1-2 minutes. See NCR for more information.
2019-01-30 11:19:20	2019-01-30 11:19:30	10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low/Low Threshold: location value less than 10.0 %RH for System/ETHICON/Receiving&Decontamination RH	Threshold Alarm: ETHICON Low Humidity Warning for Low/Low Threshold: location value less than 10.0 %RH for System/ETHICON/Receiving&Decontamination RH Min value: 9.3 %RH Max value: 9.3 %RH Affected location: System/ETHICON/Receiving&Decontamination RH (1912)	Acknowledged on 2019-02-01 15:50:04 by ibatar1 (Ibrahim Bitar): "NCR NR-0116615 Created", comment: This alarm was caused because the temperatures outside had reached extreme lows. A NCR (NR-0116615) was created so that we can record the actions taken. Humidity had dropped below storage limit for less than 1-2 minutes. See NCR for more information.
2019-01-30 11:52:59	2019-01-30 12:30:33	37 minutes, 34 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	Acknowledged on 2019-02-01 15:50:04 by ibatar1 (Ibrahim Bitar): "NCR NR-0116615 Created", comment: This alarm was caused because the temperatures outside had reached extreme lows. A NCR (NR-0116615) was created so that we can record the actions taken. Humidity had dropped below storage limit for less than 1-2 minutes. See NCR for more information.
2019-01-30 12:20:24	2019-01-30 12:45:49	25 minutes, 25 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.5 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2019-02-01 15:50:04 by ibatar1 (Ibrahim Bitar): "NCR NR-0116615 Created", comment: This alarm was caused because the temperatures outside had reached extreme lows. A NCR (NR-0116615) was created so that we can record the actions taken. Humidity had dropped below storage limit for less than 1-2 minutes. See NCR for more information.
2019-01-30 12:46:56	2019-01-30 12:49:00	2 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.1 %RH Max value: 34.1 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2019-02-01 15:50:04 by ibatar1 (Ibrahim Bitar): "NCR NR-0116615 Created", comment: This alarm was caused because the temperatures outside had reached extreme lows. A NCR (NR-0116615) was created so that we can record the actions taken. Humidity had dropped below storage limit for less than 1-2 minutes. See NCR for more information.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 12:50:04	2019-01-30 12:53:07	3 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.9 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.9 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-30 13:01:24	2019-01-30 13:03:28	2 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-30 13:04:20	2019-01-30 13:08:38	4 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-30 13:09:20	2019-01-30 13:12:41	3 minutes, 21 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.6 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.6 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-30 13:12:44	2019-01-30 13:13:44	1 minute	Threshold Alarm: ETHICON Low Humidity Alarm for Low Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Acknowledged on 2019-02-01 14:51:30 by ibtar1 (Ibrahim Bitar); "no action taken"; comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Acknowledged on 2019-02-01 14:51:30 by ibtar1 (Ibrahim Bitar); "no action taken"; comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 13:13:44	2019-01-30 13:17:48	4 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2019-01-30 13:17:30	2019-01-30 13:17:52	22 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.9 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-01-30 13:18:49	2019-01-30 13:21:53	3 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.3 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2019-02-01 14:50:04 by ibitar1 (Ibrahim Bitar): "No Action Taken". comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-30 13:23:53	2019-01-30 13:25:54	2 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2019-01-30 13:45:16	2019-01-30 13:47:15	1 minute, 59 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2019-01-30 14:06:30	2019-01-30 14:55:23	48 minutes, 53 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 29.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 14:23:57	2019-01-30 14:28:01	4 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2019-02-01 14:37:59 by ibitar1 (Ibrahim Bitar): "No action", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time in area.
2019-01-30 14:29:01	2019-01-30 15:01:22	32 minutes, 21 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.2 %RH Max value: 29.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2019-02-01 15:34:33 by ibitar1 (Ibrahim Bitar): "no action taken", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time in area.
2019-01-30 15:00:22	2019-01-30 15:02:22	2 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.0 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Acknowledged on 2019-02-01 14:55:20 by ibatar1 (Ibrahim Bitar): "No Action", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-30 15:02:22	2019-01-30 15:04:28	2 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.9 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11922)	Acknowledged on 2019-02-01 14:55:20 by ibatar1 (Ibrahim Bitar): "No Action", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-30 15:03:22	2019-01-30 15:05:28	2 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2019-02-01 14:55:20 by ibatar1 (Ibrahim Bitar): "No Action", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 15:06:28	2019-01-30 15:08:29	2 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 15:10:29	2019-01-30 15:14:20	3 minutes, 51 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 15:40:40	2019-01-30 15:41:41	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 15:52:46	2019-01-30 15:53:46	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 17:40:45	2019-01-31 12:16:38	18 hours, 35 minutes, 53 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 67.11 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-30 18:09:07	2019-01-30 18:47:35	38 minutes, 28 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 30.8 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 18:17:30	2019-01-31 09:52:53	15 hours, 35 minutes, 23 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.42 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-01-30 18:49:40	2019-01-30 18:50:36	56 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 18:53:38	2019-01-30 18:54:20	42 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 18:57:38	2019-01-30 19:01:42	4 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 19:03:42	2019-01-30 19:04:20	38 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-30 19:05:43	2019-01-30 19:07:45	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-30 22:08:56	2019-01-30 22:17:58	9 minutes, 2 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.97 °F Max value: 67.97 %RH Affected location: System/ETHICON/Repair & Testing T	Acknowledged on 2019-02-01 14:07:21 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm was outside of technician working hours, so there weren't any medical devices in operation.
2019-01-30 22:11:56	2019-01-30 22:44:49	32 minutes, 53 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH T	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 31.4 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH	(11916)
2019-01-30 22:25:04	2019-01-31 09:00:35	10 hours, 35 minutes, 31 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.11 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing T	(11918)
2019-01-30 22:45:45	2019-01-30 22:47:45	2 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH	Acknowledged on 2019-02-01 14:16:06 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm was caused because the temperature outside had reached extreme lows. The temperature dropped low enough so that the Stockert Product could not be in operating state. There weren't any products being operated during this time.
2019-01-30 22:56:45	2019-01-30 22:59:49	3 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH	(11918)
2019-01-31 02:12:10	2019-01-31 02:44:20	32 minutes, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 31.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH	(11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 02:15:12	2019-01-31 08:37:30	6 hours, 22 minutes, 18 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.42 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2019-02-01 14:25:54 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: his alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Stockert Product could not be in operating state. Technician was working on paperwork during the time.
2019-01-31 02:45:36	2019-01-31 02:46:37	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 02:47:38	2019-01-31 02:49:20	1 minute, 42 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 02:57:44	2019-01-31 02:58:45	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 31.7 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 06:15:03	2019-01-31 06:42:20	27 minutes, 17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 06:47:57	2019-01-31 06:51:24	3 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 06:52:42	2019-01-31 06:53:59	1 minute, 17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 06:56:18	2019-01-31 06:57:37	1 minute, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 07:04:51	2019-01-31 07:05:51	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 10:15:37	2019-01-31 10:34:47	19 minutes, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.1 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 10:38:03	2019-01-31 10:40:23	2 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 12:28:10	2019-01-31 12:30:23	2 minutes, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-31 12:32:39	2019-01-31 12:33:46	1 minute, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-31 12:37:30	2019-01-31 12:40:17	2 minutes, 47 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-31 14:27:30	2019-01-31 14:31:57	4 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-01-31 14:33:14	2019-01-31 14:36:49	3 minutes, 35 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 14:34:31	2019-02-01 08:45:36	18 hours, 11 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 28.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 15:34:51	2019-01-31 15:36:04	1 minute, 13 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-31 20:19:02 09:18:48	2019-02-01 09:18:48	17 hours, 39 minutes, 28 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 67.34 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2019-01-31 17:26:29	2019-01-31 17:27:37	1 minute, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 17:27:30	2019-01-31 17:27:41	11 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-01-31 17:28:50	2019-02-01 08:04:57	14 hours, 36 minutes, 7 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.01 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2019-01-31 17:38:13	2019-01-31 17:39:20	1 minute, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 17:43:47	2019-01-31 17:44:20	33 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 17:57:53	2019-01-31 18:04:12	6 minutes, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 18:06:21	2019-01-31 18:07:33	1 minute, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 18:09:20	2019-01-31 21:02:59	2 hours, 53 minutes, 39 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 29.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 18:29:20	2019-01-31 18:36:47	7 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Acknowledged on 2019-02-01 15:36:53 by Ibtar1 (Ibrahim Bitar): "no action" comment. This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 18:30:32	2019-01-31 19:28:24	57 minutes, 52 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 28.6 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	Acknowledged on 2019-02-01 14:48:00 by ibitar! (Ibrahim Bitar): "No Action Taken", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-31 18:57:18	2019-02-01 07:33:24	12 hours, 36 minutes, 6 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.34 °F Max value: 67.97 %RH Affected location: System/ETHICON/Repair & Testing T (1916)	Acknowledged on 2019-02-01 14:22:39 by ibitar! (Ibrahim Bitar): "No Action", comment: his alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Stockert Product could not be in operating state. There weren't any Stockert products operating in this area.
2019-01-31 19:29:33	2019-01-31 19:41:53	12 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.8 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	Acknowledged on 2019-02-01 14:42:30 by ibitar! (Ibrahim Bitar): "No Action Taken", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time. no action
2019-01-31 19:42:30	2019-01-31 19:43:09	39 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.9 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	Acknowledged on 2019-02-01 14:42:48 by ibatar! (Ibrahim Bitar): "No Action Taken", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-31 21:04:13	2019-01-31 21:18:44	14 minutes, 31 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2019-02-01 14:42:48 by ibatar! (Ibrahim Bitar): "No Action Taken", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-31 21:20:00	2019-01-31 21:29:05	9 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2019-02-01 14:48:00 by ibatar! (Ibrahim Bitar): "No Action Taken", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 21:32:18	2019-01-31 21:34:34	2 minutes, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 21:35:44	2019-01-31 21:47:31	11 minutes, 47 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 21:50:50	2019-01-31 21:52:03	1 minute, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 21:59:17	2019-01-31 22:01:32	2 minutes, 15 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 22:07:53	2019-01-31 22:09:07	1 minute, 14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-01-31 22:12:23	2019-01-31 23:45:24	1 hour, 33 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 29.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 29.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 22:33:00	2019-01-31 22:38:19	5 minutes, 19 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing RH Min value: 29.6 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2019-02-01 15:35:04 by ibitarl (Ibrahim Bitar). "No Action" comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-31 22:37:30	2019-01-31 23:15:13	37 minutes, 43 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.3 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	Acknowledged on 2019-02-01 14:41:20 by ibitarl (Ibrahim Bitar). "No Action", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-31 23:17:34	2019-01-31 23:18:43	1 minute, 9 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low/Low Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Alarm for LowLow Threshold: location value less than 30.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 29.9 %RH Max value: 29.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	Acknowledged on 2019-02-01 14:40:37 by ibitarl (Ibrahim Bitar). "No Action", comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Gen 11 could not be in operating state. There weren't any Gen 11 products being operated during this time.
2019-01-31 23:47:39	2019-01-31 23:50:53	3 minutes, 14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)
2019-01-31 23:52:03	2019-01-31 23:53:12	1 minute, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-01-31 23:55:40	2019-01-31 23:57:53	2 minutes, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.1 %RH Max value: 34.4 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-01-31 00:59:18	2019-02-01 00:01:36	2 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 00:04:20	2019-02-01 00:06:09	1 minute, 49 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 00:13:26	2019-02-01 00:14:20	54 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 00:39:20	2019-02-01 00:39:28	8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 02:17:47	2019-02-01 03:07:14	49 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 31.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-01 03:08:26	2019-02-01 03:12:48	4 minutes, 22 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 03:14:03	2019-02-01 03:15:23	1 minute, 20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 03:26:38	2019-02-01 03:27:51	1 minute, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 03:39:20	2019-02-01 03:39:34	14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 06:23:26	2019-02-01 06:53:34	30 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-01 06:54:51	2019-02-01 07:02:10	7 minutes, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-01 07:34:20	2019-02-01 07:34:40	20 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2019-02-01 14:36:38 by ibtar1 (Ibrahim Bitar): "No Action Taken" comment: This alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Stockert Product could not be in operating state. There weren't any Stockert products being operated during this time in area.
2019-02-01 07:35:49	2019-02-01 07:46:20	10 minutes, 31 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.89 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2019-02-01 14:36:46 by ibtar1 (Ibrahim Bitar): "No Action taken" comment: his alarm was caused because the temperatures outside had reached extreme lows. The temperature dropped low enough so that the Stockert Product could not be in operating state. There weren't any Stockert products being operated during this time in area.
2019-02-02 00:25:16	2019-02-02 00:26:32	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2019-02-02 01:20:03 01:26:19 6 minutes, 16 seconds
2019-02-02 01:20:03	2019-02-02 01:26:19	6 minutes, 16 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)
2019-02-02 01:27:37	2019-02-02 01:28:52	1 minute, 15 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server (17332041) on Enterprise Server (TSUSRAWSP04243.jnj.com) Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)
2019-02-07 16:44:24	2019-02-07 17:00:50	16 minutes, 26 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server (TSUSRAWSP04243.jnj.com)	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server (TSUSRAWSP04243.jnj.com) Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2019-02-08 07:13:58 by ibtar1 (Ibrahim Bitar): "Power flickered, waited for network to restore connection" comment: The power had flickered last night, the connection was restored in under 3 minutes and the all environmental control was well within the acceptance range before/after the connection loss.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-07 16:44:24	2019-02-07 16:52:40	8 minutes, 15 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSSP04243.jnl.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSSP04243.jnl.com Affected locations: Spare parts & Shipping T (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-02-08 07:14:26 by ibitar1 (Ibrahim Bitar); "Power flickered, waited for network to restore connection", comment: The power had flickered last night, the connection was restored in under 3 minutes and the all environmental control was well within the acceptance range before/after the connection loss.
2019-02-07 16:44:24	2019-02-07 16:54:11	9 minutes, 47 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSSP04243.jnl.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSSP04243.jnl.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-02-08 07:18:03 by ibitar1 (Ibrahim Bitar); "Power flickered, waited for network to restore connection", comment: The power had flickered last night, the connection was restored in under 3 minutes and the all environmental control was well within the acceptance range before/after the connection loss.
2019-02-07 16:44:24	2019-02-07 16:50:45	6 minutes, 20 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSSP04243.jnl.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSSP04243.jnl.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-02-08 07:20:32 by ibitar1 (Ibrahim Bitar); "Power flickered, waited for network to restore connection", comment: The power had flickered last night, the connection was restored in under 3 minutes and the all environmental control was well within the acceptance range before/after the connection loss.
2019-02-07 16:44:24	2019-02-07 17:03:26	19 minutes, 2 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSSP04243.jnl.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSSP04243.jnl.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-02-08 07:17:22 by ibitar1 (Ibrahim Bitar); "Power flickered, waited for network to restore connection", comment: The power had flickered last night, the connection was restored in under 3 minutes and the all environmental control was well within the acceptance range before/after the connection loss.
2019-02-08 07:39:12	2019-02-08 07:49:55	10 minutes, 43 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2019-02-08 07:17:22 by ibatar1 (Ibrahim Bitar); "Power flickered, waited for network to restore connection", comment: The power had flickered last night, the connection was restored in under 3 minutes and the all environmental control was well within the acceptance range before/after the connection loss.
2019-02-08 07:51:09	2019-02-08 07:54:20	3 minutes, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2019-02-08 07:17:22 by ibatar1 (Ibrahim Bitar); "Power flickered, waited for network to restore connection", comment: The power had flickered last night, the connection was restored in under 3 minutes and the all environmental control was well within the acceptance range before/after the connection loss.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-08 07:55:42	2019-02-08 07:57:56	2 minutes, 14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 08:06:26	2019-02-08 08:07:45	1 minute, 19 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 09:49:08	2019-02-08 09:50:24	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 09:51:32	2019-02-08 09:55:21	3 minutes, 49 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 09:56:40	2019-02-08 09:58:01	1 minute, 21 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 10:52:27	2019-02-08 10:53:42	1 minute, 15 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.2 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-08 10:57:01	2019-02-08 10:58:23	1 minute, 22 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.1 %RH Max value: 34.1 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 11:00:41	2019-02-08 11:03:59	3 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 12:43:19	2019-02-08 12:45:39	2 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 16:34:20	2019-02-08 16:56:42	22 minutes, 22 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 17:01:58	2019-02-08 17:04:11	2 minutes, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 17:04:20	2019-02-08 17:05:28	1 minute, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-08 20:32:37	2019-02-08 20:19:13	1 minute, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 20:51:00	2019-02-08 20:58:27	7 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 21:13:04	2019-02-08 21:14:15	1 minute, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11922)	
2019-02-08 21:15:32	2019-02-08 21:18:44	3 minutes, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 21:20:00	2019-02-08 21:23:09	3 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-08 21:47:43	2019-02-08 21:48:53	10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 22:29:20	2019-02-08 22:30:08	48 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 22:31:18	2019-02-08 22:34:20	3 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 22:35:44	2019-02-08 22:38:00	2 minutes, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 22:40:20	2019-02-08 22:41:30	1 minute, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 22:44:48	2019-02-08 22:57:20	12 minutes, 32 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-08 22:58:33	2019-02-08 22:59:49	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 23:02:00	2019-02-08 23:03:10	1 minute, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 23:04:18	2019-02-08 23:04:20	2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 23:07:43	2019-02-08 23:10:55	3 minutes, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 23:41:29	2019-02-08 23:42:41	1 minute, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 23:44:20	2019-02-08 23:46:04	1 minute, 44 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-08 23:54:20	2019-02-08 00:57:38	3 minutes, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-08 00:06:28	2019-02-09 00:10:59	7 minutes, 35 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 00:08:45	2019-02-09 00:10:59	2 minutes, 14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 00:19:20	2019-02-09 00:20:36	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 00:25:54	2019-02-09 00:56:49	30 minutes, 55 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 00:42:27	2019-02-09 01:28:58	46 minutes, 31 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 00:58:01	2019-02-09 06:23:25	5 hours, 25 minutes, 24 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 01:32:30	2019-02-09 01:46:37	14 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 02:02:30	2019-02-09 02:03:01	31 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 02:05:12	2019-02-09 02:12:29	7 minutes, 17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 02:35:02	2019-02-09 02:41:16	6 minutes, 14 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 02:52:40	2019-02-09 02:59:52	7 minutes, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 03:01:07	2019-02-09 03:06:23	5 minutes, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-02-09 03:07:30	2019-02-09 03:08:52	1 minute, 22 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-02-09 03:11:10	2019-02-09 03:14:23	3 minutes, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-02-09 03:19:38	2019-02-09 03:34:12	14 minutes, 34 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-02-09 03:36:25	2019-02-09 03:37:30	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-02-09 03:47:00	2019-02-09 04:08:31	21 minutes, 31 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 04:15:44	2019-02-09 04:32:12	16 minutes, 28 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-02-09 05:00:13	2019-02-09 05:01:26	1 minute, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)
2019-02-09 05:10:48	2019-02-09 06:31:11	1 hour, 20 minutes, 23 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)
2019-02-09 06:25:41	2019-02-09 06:30:02	4 minutes, 21 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-09 06:34:31	2019-02-09 06:37:42	3 minutes, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 06:37:30	2019-02-09 06:38:55	1 minute, 25 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 06:42:10	2019-02-09 06:43:27	1 minute, 17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	
2019-02-09 06:45:38	2019-02-09 07:09:43	24 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 06:48:09	2019-02-09 06:49:20	1 minute, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.2 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 06:50:37	2019-02-09 06:51:53	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 07:07:14	2019-02-09 07:08:32	1 minute, 18 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.4 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 07:14:57	2019-02-09 07:16:09	1 minute, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-09 07:57:54	2019-02-09 07:59:06	1 minute, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 09:08:38	2019-02-09 09:11:53	3 minutes, 15 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 09:13:06	2019-02-09 09:14:19	1 minute, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-09 09:14:20	2019-02-09 09:15:36	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 09:32:08	2019-02-09 09:35:23	3 minutes, 15 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2019-02-09 09:46:42	2019-02-09 09:56:52	10 minutes, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.4 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2019-02-09 09:50:58	2019-02-09 09:52:09	1 minute, 11 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-02-09 09:53:30	2019-02-09 09:55:39	2 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-02-09 09:56:52	2019-02-09 10:25:17	28 minutes, 25 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2019-02-09 12:20:50	2019-02-09 12:32:57	12 minutes, 7 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.inj.com Affected locations: Spare parts & Shipping RH (1926), Spare parts & Shipping T (1924) Acknowledged on 2019-02-11 10:53:35 by ibitari (Ibrahim Bitar). "no Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 12:20:50	2019-02-09 12:32:57	12 minutes, 7 seconds	Device ETHIC-Rec&Decon on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2019-02-11 10:07:57 by ibitar1 (Ibrahim Bitar); "No action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 12:20:52	2019-02-09 12:32:57	12 minutes, 4 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2019-02-11 10:08:56 by ibitar1 (Ibrahim Bitar); "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 12:20:53	2019-02-09 12:33:03	12 minutes, 10 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2019-02-11 10:46:28 by ibitar1 (Ibrahim Bitar); "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 13:01:34	2019-02-09 13:04:49	3 minutes, 15 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2019-02-11 11:17:44 by ibatar1 (Ibrahim Bitar); "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 3 minutes.
2019-02-09 13:01:34	2019-02-09 13:03:43	2 minutes, 8 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2019-02-11 11:33:15 by ibatar1 (Ibrahim Bitar); "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 13:03:45	2019-02-09 13:04:49	1 minute, 3 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2019-02-11 11:30:04 by ibatar1 (Ibrahim Bitar); "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 1 minute.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 13:25:25	2019-02-09 13:37:59	12 minutes, 34 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSURAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2019-02-11 10:48:33 by ibitar1 (Ibrahim Bitar); "No action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 13:25:28	2019-02-09 13:37:59	12 minutes, 31 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSURAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2019-02-11 10:41:54 by ibitar1 (Ibrahim Bitar); "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 13:25:28	2019-02-09 13:37:59	12 minutes, 31 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSURAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2019-02-11 10:10:11 by ibatar1 (Ibrahim Bitar); "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 13:25:28	2019-02-09 13:37:59	12 minutes, 31 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSURAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2019-02-11 10:07:25 by ibatar1 (Ibrahim Bitar); "No action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 14:11:43	2019-02-09 14:12:43	59 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSURAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2019-02-11 11:16:06 by ibatar1 (Ibrahim Bitar); "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 1 minute.
2019-02-09 14:11:43	2019-02-09 14:12:48	1 minute, 4 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSURAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2019-02-11 11:36:53 by ibatar1 (Ibrahim Bitar); "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 1 minute.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 14:12:45	2019-02-09 14:15:48	3 minutes, 2 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2019-02-11 11:28:27 by ibtar1 (Ibrahim Bitar): "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 3 minutes.
2019-02-09 14:12:45	2019-02-09 14:15:48	3 minutes, 2 seconds	Device ETHIC-Repair&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Repair&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2019-02-11 11:20:42 by ibtar1 (Ibrahim Bitar): "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 14:13:45	2019-02-09 14:15:48	2 minutes, 2 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Repair test (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2019-02-11 11:32:09 by ibtar1 (Ibrahim Bitar): "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 14:13:45	2019-02-09 14:15:47	2 minutes, 1 second	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-02-11 11:36:01 by ibtar1 (Ibrahim Bitar): "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 2 minutes.
2019-02-09 14:13:48	2019-02-09 14:15:47	1 minute, 59 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-02-11 11:40:12 by ibtar1 (Ibrahim Bitar): "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 2 minutes.
2019-02-09 14:28:16	2019-02-09 14:41:19	13 minutes, 2 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2019-02-11 10:40:12 by ibtar1 (Ibrahim Bitar): "No action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 14:28:17	2019-02-09 14:41:19	13 minutes, 2 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2019-02-11 10:47:30 by ibtar1 (Ibrahim Bitar): "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 14:28:17	2019-02-09 14:41:19	13 minutes, 2 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH ((1912),Receiving&Decontamination T (1914))	Acknowledged on 2019-02-11 10:36:03 by ibitari1 (Ibrahim Bitar): "No Action Taken," comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 14:28:19	2019-02-09 14:41:19	13 minutes, 2 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (1926),Spare parts & Shipping T (1924)	Acknowledged on 2019-02-11 10:50:54 by ibitari1 (Ibrahim Bitar): "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 15:11:24	2019-02-09 15:12:25	1 minute	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH ((1918),Repair & Testing T (1916))	Acknowledged on 2019-02-11 10:50:32 by ibitari1 (Ibrahim Bitar): "no action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 13 minutes.
2019-02-09 15:11:25	2019-02-09 15:12:24	59 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (1926),Spare parts & Shipping T (1924)	Acknowledged on 2019-02-11 11:14:03 by ibitari1 (Ibrahim Bitar): "No action taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 1 minute.
2019-02-09 15:11:27	2019-02-09 15:14:37	3 minutes, 9 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Warehouse RH ((1928),Warehouse T (1930))	Acknowledged on 2019-02-11 11:19:15 by ibitari1 (Ibrahim Bitar): "No Action Taken," comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 3 minutes.
2019-02-09 15:12:27	2019-02-09 15:14:37	2 minutes, 9 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH ((1922),Repair & Testing2 T (1920))	Acknowledged on 2019-02-11 11:31:47 by ibitari1 (Ibrahim Bitar): "No action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 2 minutes.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-09 15:13:33	2019-02-09 15:14:37	1 minute, 3 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2019-02-11 11:40:09 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Disconnecting Alarm had gone off on Saturday when there weren't any products being serviced. Connection was restored after 1 minute.
2019-02-13 10:39:20	2019-02-13 10:53:58	14 minutes, 38 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-13 10:57:07	2019-02-13 10:58:10	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-15 14:08:19	2019-02-15 14:09:24	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-18 08:14:40	2019-02-18 11:02:28	2 hours, 47 minutes, 48 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2019-02-25 08:48:51 by ibtar1 (Ibrahim Bitar): "no action", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 08:14:40	2019-02-18 11:02:28	2 hours, 47 minutes, 48 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2019-02-25 08:50:51 by ibtar1 (Ibrahim Bitar): "no action taken", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-18 08:14:40	2019-02-18 11:02:28	2 hours, 47 minutes, 47 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSURAWSPO4243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSURAWSPO4243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination RH (11914)	Acknowledged on 2019-02-25 08:42:25 by ibitari1 (Ibrahim Bitar): "None" comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 08:14:41	2019-02-18 11:02:28	2 hours, 47 minutes, 47 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSURAWSPO4243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSURAWSPO4243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2019-02-25 08:43:45 by ibitari1 (Ibrahim Bitar): "no action", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 09:34:20	2019-02-18 11:28:32	1 hour, 54 minutes, 12 seconds	Device ETHIC-RepairTsl2 (17332036) on Enterprise Server ITUSURAWSPO4243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTsl2 (17332036) on Enterprise Server ITUSURAWSPO4243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2019-02-25 08:45:11 by ibitari1 (Ibrahim Bitar): "no action", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 09:37:30	2019-02-18 11:25:30	1 hour, 48 minutes	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 67.04 °F Max value: 68.93 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2019-02-25 08:45:36 by ibitari1 (Ibrahim Bitar): "No Action Taken", comment: This was a planned power shut down time on President's day (technicians were not servicing product). This alarm tripped on the repair floor while the technicians were not servicing the product.
2019-02-18 10:09:20	2019-02-18 11:19:20	1 hour, 10 minutes	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.04 °F Max value: 67.93 Affected location: System/ETHICON/Repair & Testing T (11920)	Acknowledged on 2019-02-25 08:53:36 by ibitari1 (Ibrahim Bitar): "No Action Taken", comment: This was a planned power shut down time on President's day (technicians were not servicing product). This alarm tripped on the repair floor while the technicians were not servicing the product.
2019-02-18 10:17:30	2019-02-18 11:17:25	59 minutes, 55 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.90 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2019-02-25 08:53:57 by ibitari1 (Ibrahim Bitar): "no action taken", comment: This was a planned power shut down time on President's day (technicians were not servicing product). This alarm tripped on the repair floor while the technicians were not servicing the product.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-18 11:35:35	2019-02-18 11:48:39	4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-18 11:49:41	2019-02-18 11:54:46	5 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	
2019-02-18 11:50:42	2019-02-18 11:52:44	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-18 11:53:45	2019-02-18 11:56:47	3 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	
2019-02-18 11:59:20	2019-02-18 12:17:54	18 minutes, 34 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-18 12:39:20	2019-02-18 12:42:02	2 minutes, 42 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2019-02-18 13:13:13	2019-02-18 15:51:29	2 hours, 38 minutes, 16 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping T (1924)	Acknowledged on 2019-02-25 08:49:45 by ibtar1 (Ibrahim Bitar): "no action", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 13:13:13	2019-02-18 15:51:29	2 hours, 38 minutes, 15 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (1922), Repair & Testing2 T (1920)	Acknowledged on 2019-02-25 08:48:30 by ibtar1 (Ibrahim Bitar): "no action", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 13:13:13	2019-02-18 15:51:29	2 hours, 38 minutes, 16 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (1928), Warehouse T (1930)	Acknowledged on 2019-02-25 08:52:23 by ibtar1 (Ibrahim Bitar): "no action taken", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 13:13:13	2019-02-18 15:51:29	2 hours, 38 minutes, 15 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH ((1912)),Receiving&Decontamination T (1914)	Acknowledged on 2019-02-25 08:42:47 by ibtar1 (Ibrahim Bitar): "no action", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-18 13:13:13	2019-02-18 15:51:29	2 hours, 38 minutes, 15 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (1918),Repair & Testing T (1916)	Acknowledged on 2019-02-25 08:44:49 by ibtar1 (Ibrahim Bitar): "no action", comment: This was a planned power shut down time on President's day (technicians were not servicing product). The alarm did not trip before/after the power went out and came back up.
2019-02-24 16:38:50	2019-02-24 16:49:56	11 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-24 20:42:40	2019-02-24 21:00:17	37 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-02-24 22:44:20	2019-02-24 22:44:40	20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-02-24 23:15:44	2019-02-24 23:16:45	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-02-25 00:49:20	2019-02-25 00:52:25	3 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-02-25 00:53:26	2019-02-25 01:01:29	8 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-02-25 01:06:30	2019-02-25 01:07:30	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-25 01:09:20	2019-02-25 01:11:32	2 minutes, 12 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 04:37:50	2019-02-25 04:38:52	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 04:39:56	2019-02-25 05:21:05	41 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.2 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 05:29:20	2019-02-25 05:31:09	1 minute, 49 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 05:35:14	2019-02-25 05:36:12	58 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 05:37:13	2019-02-25 05:38:14	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-25 06:57:52	2019-02-25 07:02:53	5 minutes, 1 second	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-25 07:13:57	2019-02-25 07:15:01	1 minute, 4 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-25 07:22:00	2019-02-25 07:23:01	1 minute, 1 second	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-25 07:28:04	2019-02-25 07:29:05	1 minute, 1 second	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-25 07:31:07	2019-02-25 07:32:08	1 minute, 1 second	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2019-02-25 07:44:12	2019-02-25 07:45:17	1 minute, 5 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-25 08:07:18	2019-02-25 08:06:21	5 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 08:07:22	2019-02-25 08:08:24	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 08:09:20	2019-02-25 08:10:27	1 minute, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 08:30:33	2019-02-25 09:23:20	52 minutes, 47 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 08:49:38	2019-02-25 09:42:44	53 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 33.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-25 09:24:20	2019-02-25 09:24:26	6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-02-25 09:26:26	2019-02-25 09:34:34	8 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.1 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 09:39:20	2019-02-25 09:40:37	1 minute, 17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 09:47:48	2019-02-25 09:56:50	9 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-02-25 12:50:06	2019-02-25 12:56:39	6 minutes, 33 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 16:46:52	2019-02-25 16:52:01	5 minutes, 9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-02-25 17:04:04	2019-02-25 17:06:05	2 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-04 07:28:38	2019-03-04 07:31:40	3 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-04 07:32:41	2019-03-04 07:35:43	3 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-04 07:36:45	2019-03-04 07:37:46	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-04 08:00:52	2019-03-04 08:01:54	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-04 08:12:30	2019-03-04 08:24:08	1 minute, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-04 13:18:40	2019-03-04 13:22:42	4 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Alarm for Low Threshold: location value less than 15.0 %RH for System/ETHICON/Receiving&Decontamination RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low Threshold: location value less than 15.0 %RH for System/ETHICON/Receiving&Decontamination RH Min value: 11.8 %RH Max value: 13.6 %RH Affected location: System/ETHICON/Receiving&Decontamination RH (11912)	Acknowledged on 2019-03-04 14:02:14 by ibitari (Ibrahim Bitar). "No Action Taken" comment: We did not drop below 10% on the RH so there wasn't any product that have been effected. This alarm was active for only 4 minutes and the RH had gone back up.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-04 15:33:25	2019-03-04 21:49:07	7 minutes, 3 seconds	Device ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.0 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-03-04 23:48:15	2019-03-04 23:49:17	1 minute, 5 seconds	Device ETHICON-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHICON-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare carts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2019-03-05 08:36:30 by ibitari (Ibrahim Bitar): "No Action Taken" comment: This took place during the evening. The spare parts and shipping area sensor lost connection for almost one minute and was restored. There wasn't a spike in temperature control during this period.
2019-03-05 03:33:19	2019-03-05 03:44:27	11 minutes, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-03-05 03:45:25	2019-03-05 03:50:27	5 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-03-05 03:50:27	2019-03-05 04:02:30	12 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-05 04:02:35	2019-03-05 04:06:42	4 minutes, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-03-05 07:39:05	2019-03-05 07:42:07	3 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11918)	
2019-03-05 07:50:10	2019-03-05 07:56:13	6 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-03-05 07:57:30	2019-03-05 07:58:18	48 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-03-05 19:41:59	2019-03-05 19:44:01	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2019-03-05 23:42:56	2019-03-05 23:44:20	1 minute, 24 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-05 23:45:01	2019-03-05 23:50:03	5 minutes, 2 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)
2019-03-06 03:42:09	2019-03-06 03:43:11	1 minute, 2 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)
2019-03-06 03:44:12	2019-03-06 03:45:17	1 minute, 5 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)
2019-03-06 04:03:10	2019-03-06 04:05:16	2 minutes, 6 seconds	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)
2019-03-06 08:00:24	2019-03-06 08:01:25	1 minute, 1 second	System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)
2019-03-06 10:07:23	2019-03-06 10:09:20	1 minute, 57 seconds	System/ETHICON/Receiving&Decontamination RH	Threshold Alarm: ETHICON Low Humidity Alarm for Low Threshold: location value less than 15.0 %RH for System/ETHICON/Receiving&Decontamination RH	Acknowledged on 2019-03-11 12:39:15 by ibitari (Ibrahim Bitari). "None", comment: Humidity did not dip below 10%, therefore there weren't any product that were affected by this alarm.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-06 10:14:31	2019-03-06 10:18:35	4 minutes, 4 seconds	Device ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.5 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (11922)	
2019-03-09 12:48:04	2019-03-09 12:50:28	2 minutes, 23 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912); Receiving&Decontamination T (11914)	Acknowledged on 2019-03-11 12:49:11 by ibitari (Ibrahim Bitar): "No Action Taken", comment: This alarm occurred on Saturday. There weren't any products being worked and the disconnection happened for less than 3 minutes.
2019-03-09 12:48:04	2019-03-09 12:50:29	2 minutes, 24 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11928); Spare parts & Shipping T (11924)	Acknowledged on 2019-03-11 12:49:32 by ibitari (Ibrahim Bitar): "No Action Taken", comment: This alarm occurred on Saturday. There weren't any products being worked and the disconnection happened for less than 2 minutes.
2019-03-09 12:48:06	2019-03-09 12:50:27	2 minutes, 21 seconds	Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSUSRRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922); Repair & Testing2 T (11920)	Acknowledged on 2019-03-11 12:49:50 by ibitari (Ibrahim Bitar): "No Action Taken", comment: This alarm occurred on Saturday. There weren't any products being worked and the disconnection happened for less than 2 minutes.
2019-03-09 12:50:11	2019-03-09 12:51:41	1 minute, 30 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918); Repair & Testing T (11916)	Acknowledged on 2019-03-11 12:49:57 by ibitari (Ibrahim Bitar): "No Action Taken", comment: This alarm occurred on Saturday. There weren't any products being worked and the disconnection happened for less than 2 minutes.
2019-03-09 12:55:41	2019-03-09 12:56:52	1 minute, 11 seconds	Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSUSRRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922); Repair & Testing2 T (11920)	Acknowledged on 2019-03-11 12:49:40 by ibitari (Ibrahim Bitar): "No Action Taken", comment: This alarm occurred on Saturday. There weren't any products being worked and the disconnection happened for less than 2 minutes.
2019-03-09 12:55:42	2019-03-09 12:57:33	1 minute, 51 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912); Receiving&Decontamination T (11914)	Acknowledged on 2019-03-11 12:49:40 by ibitari (Ibrahim Bitar): "No Action Taken", comment: This alarm occurred on Saturday. There weren't any products being worked and the disconnection happened for less than 3 minutes.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-11 09:56:37	2019-03-11 09:57:30	53 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	
2019-03-22 18:55:54	2019-03-22 18:56:54	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-22 19:04:20	2019-03-22 19:05:01	41 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-22 19:06:56	2019-03-22 19:10:57	4 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-22 19:11:57	2019-03-22 19:12:57	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2019-03-22 19:18:58	2019-03-22 19:21:59	3 minutes, 1 second	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-22 19:29:09	2019-03-22 19:37:11	8 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/EThICON/Repair & Testing RH (1918)	
2019-03-22 19:40:15	2019-03-22 19:44:12	3 minutes, 57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.6 %RH Affected location: System/EThICON/Repair & Testing RH (1918)	
2019-03-22 19:45:16	2019-03-22 19:46:12	56 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/EThICON/Repair & Testing RH (1918)	
2019-03-22 19:48:13	2019-03-22 19:49:13	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/EThICON/Repair & Testing RH (1918)	
2019-03-22 19:50:16	2019-03-22 19:51:13	57 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/EThICON/Repair & Testing RH (1918)	
2019-03-22 20:02:15	2019-03-22 20:03:15	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/EThICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/EThICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2019-03-22 20:04:15	2019-03-22 20:05:19	1 minute, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Name: Eric Smith
Date: 5-1-2019
Signature:



Name: Robert Peters
Date: 4-2-2019
Signature:



Name: Ibrahim Bitar
Date: 4-1-2019
Signature:

