



**Document Number: SCN077563** 

**Revision: A** 

**Group: Scanned (Hardcopy) Item** 

Type: Environmental Reports - Svs Ctr

State: Released

Latest Released: YES

Implemented Date: 07/29/2020

Stamp Date: Wednesday, July 29, 2020 11:49:10 AM EST

Implemented: 07/29/2020 Group: Scanned (Hardcopy) Item
Type: Environmental Reports - Svs Ctr

## viewLinc Alarm Report

Report name ETHICON Quarterly Report

Alarm events from 2020-04-01 12:00:00 to 2020-07-01 12:00:00

Report generated on 2020-07-01 12:19:56 (UTC-05:00) Eastern Time (US & Canada)

Include zones and locations: System/ETHICON

Include alarm details:
Include system alarms:
Include device communication alarms:
Include device configuration alarms:
Include device validation alarms:
Include device calibration alarms:
Include device calibration alarms:
Include threshold alarms:
Yes
Include threshold alarms:
Yes

Include threshold categories: Alarms Only

## Summary

Total active alarms: 265
Activated alarms: 262
Deactivated alarms: 261
Acknowledged alarms: 65

Time zone: (UTC-05:00) Eastern Time (US & Canada)
Page 1 of 45

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-03-28 13:57:04	2020-03-28 13:58:00	55 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-04-01 12:07:48 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication Alarm lasted for less than one minute. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.
2020-03-28 13:57:04	2020-03-28 13:58:00	55 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-04-01 12:07:48 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication Alarm lasted for less than one minute. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.
2020-03-29 02:08:24	2020-03-29 02:09:19	55 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-04-01 12:07:48 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication Alarm lasted for less than one minute. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.
2020-04-02 22:58:16	2020-04-02 23:05:24	7 minutes, 8 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-04-03 08:16:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication alarm occurred due to networking issue. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.
2020-04-02 22:58:16	2020-04-02 23:05:24	7 minutes, 8 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-04-03 08:16:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication alarm occurred due to networking issue. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.
2020-04-02 22:58:16	2020-04-02 23:05:24	7 minutes, 7 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-04-03 08:16:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication alarm occurred due to networking issue. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-04-02 22:58:16	2020-04-02 23:05:24	7 minutes, 7 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-04-03 08:16:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication alarm occurred due to networking issue. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.
2020-04-02 22:58:16	2020-04-02 23:05:24	7 minutes, 7 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-04-03 08:16:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication alarm occurred due to networking issue. This alarm occurred during non servicing hours. Communication was restored shortly afterwards therefore no action was required.
2020-04-04 08:12:18	2020-04-04 08:32:34	20 minutes, 15 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-04-06 09:48:18 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm was caused by a communication error. This alarm occurred on a Saturday therefore there weren't any products being serviced. No action were taken as this occurred on a Saturday and the communication restored by itself.
2020-04-04 08:12:18	2020-04-04 08:41:41	29 minutes, 22 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-04-06 09:48:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm was caused by a communication error. This alarm occurred on a Saturday therefore there weren't any products being serviced. No action were taken as this occurred on a Saturday and the communication restored by itself.
2020-04-04 08:12:18	2020-04-04 08:29:35	17 minutes, 16 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-04-06 09:48:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm was caused by a communication error. This alarm occurred on a Saturday therefore there weren't any products being serviced. No action were taken as this occurred on a Saturday and the communication restored by itself.
2020-04-04 08:12:18	2020-04-04 08:30:34	18 minutes, 15 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-04-06 09:48:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm was caused by a communication error. This alarm occurred on a Saturday therefore there weren't any products being serviced. No action were taken as this occurred on a Saturday and the communication restored by itself.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-04-04 08:12:18	2020-04-04 08:29:35	17 minutes, 16 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-04-06 09:48:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm was caused by a communication error. This alarm occurred on a Saturday therefore there weren't any products being serviced. No action were taken as this occurred on a Saturday and the communication restored by itself.
2020-04-06 03:19:35	2020-04-06 03:20:37	1 minute, 1 second	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-04-06 09:50:20 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm was caused by a communication error. This alarm occurred during non servicing hours therefore there weren't any products being serviced. No action were taken as this alarm lasted for one minute and the communication restored by itself.
2020-04-06 03:19:36	2020-04-06 03:20:36	1 minute	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-04-06 09:50:20 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm was caused by a communication error. This alarm occurred during non servicing hours therefore there weren't any products being serviced. No action were taken as this alarm lasted for one minute and the communication restored by itself.
2020-04-23 03:15:39	2020-04-23 03:16:42	1 minute, 3 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-04-27 13:58:13 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication that had occurred for around 1 minute. No action was taken as the communication was restored.
2020-04-23 19:03:00	2020-04-23 19:03:59	58 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-04-27 13:58:13 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication that had occurred for around 1 minute. No action was taken as the communication was restored.
2020-05-01 02:18:59	2020-05-01 02:20:08	1 minute, 9 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-05-10 20:14:39 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error that was less than one minute. Alarm occurred during non servicing hours. Communication was restored
2020-05-03 02:04:09	2020-05-03 02:05:03	53 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-05-10 20:14:39 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error that was less than one minute. Alarm occurred during non servicing hours. Communication was restored

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-10 03:21:29	2020-05-10 03:22:30	1 minute, 1 second	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-05-10 20:14:39 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error that was less than one minute. Alarm occurred during non servicing hours. Communication was restored
2020-05-11 06:12:55	2020-05-11 06:14:09	1 minute, 14 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-05-14 15:24:13 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error that was less than one minute. Alarm occurred during non servicing hours. Communication was restored
2020-05-11 07:41:44	2020-05-11 07:42:35	51 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-05-14 15:25:49 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error that was less than one minute. Communication was restored and there were no further alarms.
2020-05-18 23:05:40	2020-05-18 23:06:17	37 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH Min value: 65.4 %RH Max value: 65.4 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2020-05-19 07:23:33	2020-05-19 08:00:40	37 minutes, 7 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH Min value: 65.2 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2020-05-19 07:28:37	2020-05-19 07:39:44	11 minutes, 7 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Receiving&Decontamination RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Receiving&Decontami nation RH Min value: 70.1 %RH Max value: 71.4 %RH Affected location: System/ETHICON/Receiving&Decontami nation RH (11912)	
2020-05-19 07:42:45	2020-05-19 07:44:47	2 minutes, 2 seconds	Threshold Alarm: ETHICON High Humidity Alarm for HighHigh Threshold: location value greater than 70.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Alarm for HighHigh Threshold: location value greater than 70.0 %RH for System/ETHICON/Repair & Testing RH Min value: 70.4 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2020-05-19 08:37:51 by ibitar1 (Ibrahim Bitar): "Remove Flood Water from Depot", comment: Due to overnight rain, there was a build up of water that entered the repair floor. The humidity alarm was tripped due to the water inside the depot. During this occurrence, there weren't any products being serviced. Water removal is in progress.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-19 07:45:40	2020-05-19 07:48:50	3 minutes, 10 seconds	Threshold Alarm: ETHICON High Humidity Alarm for HighHigh Threshold: location value greater than 70.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Alarm for HighHigh Threshold: location value greater than 70.0 %RH for System/ETHICON/Repair & Testing RH Min value: 70.1 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2020-05-19 08:37:51 by ibitar1 (Ibrahim Bitar): "Remove Flood Water from Depot", comment: Due to overnight rain, there was a build up of water that entered the repair floor. The humidity alarm was tripped due to the water inside the depot. During this occurrence, there weren't any products being serviced. Water removal is in progress.
2020-05-19 08:01:58	2020-05-19 08:13:05	11 minutes, 7 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH Min value: 65.2 %RH Max value: 68.3 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2020-05-19 08:15:06	2020-05-19 08:15:40	34 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH Min value: 65.1 %RH Max value: 65.1 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2020-05-19 08:16:10	2020-05-19 08:18:08	1 minute, 58 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH Min value: 65.1 %RH Max value: 65.4 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2020-05-19 08:34:26	2020-05-19 08:35:26	1 minute	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH Min value: 65.1 %RH Max value: 65.1 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2020-05-19 09:06:26	2020-05-19 09:07:23	57 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 65.0 %RH for System/ETHICON/Repair & Testing RH Min value: 65.1 %RH Max value: 65.1 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-20 20:03:08	2020-05-20 20:04:07	59 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-05-21 08:16:42 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error that was less than one minute. Communication was restored and there were no further alarms.
2020-05-21 05:49:01	2020-05-21 05:49:51	50 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-05-21 08:16:42 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Communication error that was less than one minute. Communication was restored and there were no further alarms.
2020-05-21 22:03:58	2020-05-21 22:55:19	51 minutes, 20 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-05-26 08:17:15 by ibitar1 (Ibrahim Bitar): "", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-21 22:03:58	2020-05-21 22:55:18	51 minutes, 20 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-05-26 08:17:16 by ibitar1 (Ibrahim Bitar): "", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-21 22:03:58	2020-05-21 22:55:18	51 minutes, 19 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-05-26 08:17:16 by ibitar1 (Ibrahim Bitar): "", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-21 22:03:59	2020-05-21 22:55:18	51 minutes, 19 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-05-26 08:17:17 by ibitar1 (Ibrahim Bitar): "", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-21 22:03:59	2020-05-21 22:55:18	51 minutes, 19 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-05-26 08:17:18 by ibitar1 (Ibrahim Bitar): "", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-22 06:20:05	2020-05-22 06:20:56	51 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-05-26 08:17:15 by ibitar1 (Ibrahim Bitar): "", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-23 07:45:32	2020-05-23 10:39:58	2 hours, 54 minutes, 26 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-05-26 08:16:31 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred on a Saturday (during non servicing hours). During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-23 07:45:32	2020-05-23 10:39:58	2 hours, 54 minutes, 25 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-05-26 08:16:31 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred on a Saturday (during non servicing hours). During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-23 07:45:32	2020-05-23 10:39:58	2 hours, 54 minutes, 25 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-05-26 08:16:31 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred on a Saturday (during non servicing hours). During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-23 07:45:32	2020-05-23 10:39:58	2 hours, 54 minutes, 25 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-05-26 08:16:31 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred on a Saturday (during non servicing hours). During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-23 07:45:32	2020-05-23 10:39:58	2 hours, 54 minutes, 25 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-05-26 08:16:31 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred on a Saturday (during non servicing hours). During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-24 01:03:39	2020-05-24 01:16:45	13 minutes, 6 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 03:03:16	2020-05-24 03:03:30	14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 03:04:20	2020-05-24 03:08:21	4 minutes, 1 second	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 09:15:44	2020-05-24 09:46:03	30 minutes, 19 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 09:51:06	2020-05-24 09:53:30	2 minutes, 24 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 10:14:24	2020-05-24 10:47:40	33 minutes, 16 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-24 10:56:45	2020-05-24 11:23:30	26 minutes, 45 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 11:29:07	2020-05-24 11:54:31	25 minutes, 24 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 12:00:32	2020-05-24 12:21:44	21 minutes, 12 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 12:27:48	2020-05-24 12:47:19	19 minutes, 31 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 12:55:24	2020-05-24 13:12:33	17 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 13:23:30	2020-05-24 13:35:39	12 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-24 13:49:47	2020-05-24 13:57:52	8 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-24 14:14:04	2020-05-24 14:17:02	2 minutes, 58 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 01:32:36	2020-05-25 01:33:35	58 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-05-26 08:17:15 by ibitar1 (Ibrahim Bitar): "", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-25 04:11:12	2020-05-25 04:13:17	2 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 05:52:34	2020-05-25 05:53:30	56 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 05:53:39	2020-05-25 05:56:38	2 minutes, 59 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-25 07:40:56	2020-05-25 07:52:22	11 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 08:52:31	2020-05-25 09:06:47	14 minutes, 16 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 09:47:23	2020-05-25 10:06:34	19 minutes, 11 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 10:29:48	2020-05-25 10:51:53	22 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 11:04:03	2020-05-25 11:23:11	19 minutes, 8 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 11:33:30	2020-05-25 11:48:26	14 minutes, 56 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-25 12:03:30	2020-05-25 12:16:43	13 minutes, 13 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 12:30:51	2020-05-25 12:41:11	10 minutes, 20 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 13:02:23	2020-05-25 13:03:24	1 minute, 1 second	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 18:42:33	2020-05-25 18:51:38	9 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 19:08:30	2020-05-25 19:16:52	8 minutes, 22 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 19:31:00	2020-05-25 19:43:30	12 minutes, 30 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-25 19:56:14	2020-05-25 20:10:23	14 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 20:20:29	2020-05-25 20:40:43	20 minutes, 14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 20:50:50	2020-05-25 21:15:20	24 minutes, 30 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 21:22:51	2020-05-25 21:50:13	27 minutes, 22 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 21:54:20	2020-05-25 22:23:30	29 minutes, 10 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 22:27:44	2020-05-25 23:00:15	32 minutes, 31 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-25 23:04:22	2020-05-25 23:41:37	37 minutes, 15 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 72.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-25 23:44:39	2020-05-26 00:24:15	39 minutes, 36 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-26 00:27:15	2020-05-26 01:13:30	46 minutes, 15 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-26 01:16:33	2020-05-26 02:02:27	45 minutes, 54 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 72.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-26 02:04:32	2020-05-26 02:52:23	47 minutes, 51 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 72.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-26 02:54:28	2020-05-26 12:06:38	9 hours, 12 minutes, 10 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 73.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-26 10:13:45	2020-05-26 10:14:40	54 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-05-26 10:45:40 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for less than one minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-26 12:08:30	2020-05-26 12:28:09	19 minutes, 39 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-26 12:33:16	2020-05-26 12:49:21	16 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-26 12:59:38	2020-05-26 13:11:05	11 minutes, 27 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 08:25:32	2020-05-27 08:28:30	2 minutes, 58 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 08:28:38	2020-05-27 08:29:39	1 minute, 1 second	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-27 09:10:17	2020-05-27 09:20:28	10 minutes, 11 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 09:51:08	2020-05-27 10:08:29	17 minutes, 21 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 10:25:50	2020-05-27 10:38:01	12 minutes, 11 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 10:39:06	2020-05-27 10:40:03	57 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 11:02:27	2020-05-27 11:11:55	9 minutes, 28 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 11:27:17	2020-05-27 11:36:31	9 minutes, 14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-27 11:52:21	2020-05-27 11:58:30	6 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 12:14:54	2020-05-27 12:20:00	5 minutes, 6 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-27 12:39:25	2020-05-27 12:40:23	58 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 04:13:49	2020-05-28 04:19:50	6 minutes, 1 second	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 05:04:43	2020-05-28 05:18:30	13 minutes, 47 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 05:57:53	2020-05-28 06:18:30	20 minutes, 37 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-28 06:51:41	2020-05-28 07:18:30	26 minutes, 49 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 07:29:21	2020-05-28 07:30:34	1 minute, 12 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2020-06-03 15:23:06 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Alarm communication occurred for less than two minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-05-28 07:40:10	2020-05-28 08:15:40	35 minutes, 30 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 08:31:34	2020-05-28 09:05:58	34 minutes, 24 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 09:17:11	2020-05-28 09:50:50	33 minutes, 39 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 10:01:02	2020-05-28 10:31:32	30 minutes, 30 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-28 10:38:42	2020-05-28 11:07:03	28 minutes, 21 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 11:13:09	2020-05-28 11:37:18	24 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 11:41:21	2020-05-28 12:03:54	22 minutes, 33 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 12:08:56	2020-05-28 12:29:13	20 minutes, 17 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 12:35:16	2020-05-28 12:53:30	18 minutes, 14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 12:59:21	2020-05-28 13:15:40	16 minutes, 19 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-05-28 13:23:54	2020-05-28 13:36:43	12 minutes, 49 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 13:50:00	2020-05-28 13:58:09	8 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-05-28 14:15:26	2020-05-28 14:18:30	3 minutes, 4 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-02 03:11:11	2020-06-02 03:12:54	1 minute, 43 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-06-03 15:23:06 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Alarm communication occurred for less than two minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-02 04:30:04	2020-06-02 04:31:47	1 minute, 42 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-06-03 15:23:06 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Alarm communication occurred for less than two minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-04 04:16:28	2020-06-04 04:18:15	1 minute, 47 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-04 08:15:06 by ibitar1 (Ibrahim Bitar): "No action Taken", comment: Alarm communication occurred for less than two minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-04 07:05:43	2020-06-04 07:07:31	1 minute, 47 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-06-04 08:15:07 by ibitar1 (Ibrahim Bitar): "No action Taken", comment: Alarm communication occurred for less than two minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-04 14:40:47	2020-06-04 15:02:10	21 minutes, 23 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Receiving&Decontamination RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Receiving&Decontami nation RH Min value: 70.3 %RH Max value: 72.2 %RH Affected location: System/ETHICON/Receiving&Decontami nation RH (11912)	
2020-06-08 02:44:06	2020-06-08 02:45:48	1 minute, 42 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-06-08 07:41:29 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for less than two minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-10 03:02:49	2020-06-10 03:10:54	8 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 03:29:19	2020-06-10 03:40:36	11 minutes, 17 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.5 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 03:58:10	2020-06-10 04:13:30	15 minutes, 20 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-10 04:26:46	2020-06-10 04:44:19	17 minutes, 33 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 04:56:39	2020-06-10 05:17:46	21 minutes, 7 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 05:28:00	2020-06-10 05:49:27	21 minutes, 27 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 05:59:33	2020-06-10 06:22:13	22 minutes, 40 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 06:28:20	2020-06-10 06:50:57	22 minutes, 37 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 06:55:04	2020-06-10 07:17:34	22 minutes, 30 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-10 07:19:37	2020-06-10 07:42:03	22 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 07:45:07	2020-06-10 08:09:42	24 minutes, 35 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 08:11:44	2020-06-10 08:35:07	23 minutes, 23 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 08:37:09	2020-06-10 10:25:57	1 hour, 48 minutes, 48 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 72.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 10:27:59	2020-06-10 10:46:17	18 minutes, 18 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 72.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 10:48:18	2020-06-10 11:05:30	17 minutes, 12 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-10 11:09:33	2020-06-10 11:24:44	15 minutes, 11 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 11:29:47	2020-06-10 11:43:07	13 minutes, 20 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 11:50:12	2020-06-10 12:03:21	13 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 12:12:27	2020-06-10 12:24:35	12 minutes, 8 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 12:35:41	2020-06-10 12:45:48	10 minutes, 7 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 12:57:58	2020-06-10 13:08:05	10 minutes, 7 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-10 13:22:15	2020-06-10 13:28:30	6 minutes, 15 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 13:43:30	2020-06-10 13:48:30	5 minutes	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 14:05:18	2020-06-10 14:08:21	3 minutes, 3 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-10 23:23:36	2020-06-10 23:24:30	53 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-06-11 07:50:52 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for less than one minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-20 08:00:39	2020-06-22 08:55:13	2 days, 0 hours, 54 minutes, 33 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-06-22 08:55:13 by ibitar1 (Ibrahim Bitar): "Calibration PO initiated", comment: The calibration PO has been initiated. Full schedule will be completed soon.
2020-06-20 08:00:39	2020-06-22 08:55:14	2 days, 0 hours, 54 minutes, 34 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-06-22 08:55:13 by ibitar1 (Ibrahim Bitar): "Calibration PO initiated", comment: The calibration PO has been initiated. Full schedule will be completed soon.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-20 08:00:40	2020-06-22 08:55:14	2 days, 0 hours, 54 minutes, 34 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-06-22 08:55:14 by ibitar1 (Ibrahim Bitar): "Calibration PO initiated", comment: The calibration PO has been initiated. Full schedule will be completed soon.
2020-06-20 08:00:40	2020-06-22 08:55:15	2 days, 0 hours, 54 minutes, 34 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-06-22 08:55:14 by ibitar1 (Ibrahim Bitar): "Calibration PO initiated", comment: The calibration PO has been initiated. Full schedule will be completed soon.
2020-06-20 08:01:03	2020-06-22 08:55:15	2 days, 0 hours, 54 minutes, 12 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Calibration Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-22 08:55:15 by ibitar1 (Ibrahim Bitar): "Calibration PO initiated", comment: The calibration PO has been initiated. Full schedule will be completed soon.
2020-06-21 02:19:54	2020-06-21 02:21:09	1 minute, 15 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-22 08:55:52 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-21 02:19:56	2020-06-21 02:20:59	1 minute, 3 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-06-22 08:55:54 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-22 04:04:17	2020-06-22 04:05:13	56 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-06-22 08:55:56 by ibitar1 (Ibrahim Bitar): "No action taken", comment: Alarm communication occurred during non servicing hours. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-22 10:12:04	2020-06-22 10:13:56	1 minute, 51 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2020-06-22 10:31:03 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred during for 2 minutes. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-22 10:12:04	2020-06-22 10:13:17	1 minute, 12 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-06-22 10:31:04 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred during for 2 minutes. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-23 08:09:37	2020-06-23 08:10:46	1 minute, 8 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2020-06-23 08:32:38 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-24 07:30:28	2020-06-24 07:31:40	1 minute, 12 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-24 07:56:20 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-24 08:09:11	2020-06-24 08:10:16	1 minute, 4 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-06-24 08:32:58 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-24 08:09:12	2020-06-24 08:10:18	1 minute, 5 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-24 08:32:58 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-24 09:15:57	2020-06-24 09:17:10	1 minute, 13 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-24 09:27:41 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-24 09:36:59	2020-06-24 09:38:20	1 minute, 21 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2020-06-24 09:55:12 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-24 09:41:15	2020-06-24 09:42:45	1 minute, 29 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243_inj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2020-06-24 09:55:12 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-24 10:39:32	2020-06-24 10:41:10	1 minute, 38 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-24 11:00:15 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-27 11:39:15	2020-06-27 11:42:13	2 minutes, 58 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 11:59:31	2020-06-27 12:05:33	6 minutes, 2 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 12:25:49	2020-06-27 12:29:53	4 minutes, 4 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-27 12:51:10	2020-06-27 12:59:28	8 minutes, 18 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 13:20:44	2020-06-27 13:29:52	9 minutes, 8 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 13:48:30	2020-06-27 13:58:15	9 minutes, 45 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 14:17:00	2020-06-27 14:23:30	6 minutes, 30 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 14:41:20	2020-06-27 14:45:24	4 minutes, 4 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 15:02:38	2020-06-27 15:06:41	4 minutes, 3 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-27 15:24:56	2020-06-27 15:26:57	2 minutes, 1 second	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 19:47:19	2020-06-27 19:50:21	3 minutes, 2 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 20:08:41	2020-06-27 20:15:43	7 minutes, 2 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 20:29:55	2020-06-27 20:42:06	12 minutes, 11 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 20:55:17	2020-06-27 21:08:28	13 minutes, 11 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 21:24:42	2020-06-27 21:37:53	13 minutes, 11 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-27 21:50:03	2020-06-27 22:06:17	16 minutes, 14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 22:17:26	2020-06-27 22:36:58	19 minutes, 32 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 22:47:07	2020-06-27 23:07:23	20 minutes, 16 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 23:20:34	2020-06-27 23:42:54	22 minutes, 20 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 71.0 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-27 23:54:34	2020-06-28 00:17:54	23 minutes, 20 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 00:29:07	2020-06-28 00:55:26	26 minutes, 19 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-28 01:06:36	2020-06-28 01:33:12	26 minutes, 36 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 01:45:22	2020-06-28 02:15:17	29 minutes, 55 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 02:26:26	2020-06-28 02:55:52	29 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 03:07:01	2020-06-28 03:36:58	29 minutes, 57 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 03:47:07	2020-06-28 04:18:30	31 minutes, 23 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 04:30:59	2020-06-28 05:01:27	30 minutes, 28 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-28 05:11:41	2020-06-28 05:44:17	32 minutes, 36 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 05:55:24	2020-06-28 06:27:57	32 minutes, 33 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 06:38:07	2020-06-28 07:12:01	33 minutes, 54 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 07:19:13	2020-06-28 07:53:30	34 minutes, 17 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 08:00:48	2020-06-28 08:35:14	34 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 08:41:47	2020-06-28 09:17:10	35 minutes, 23 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-28 09:22:15	2020-06-28 09:57:47	35 minutes, 32 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 10:02:52	2020-06-28 10:38:23	35 minutes, 31 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 10:42:27	2020-06-28 11:18:01	35 minutes, 34 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 11:21:04	2020-06-28 11:53:30	32 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 72.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 11:55:21	2020-06-28 16:09:54	4 hours, 14 minutes, 33 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 73.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 16:10:55	2020-06-28 16:33:30	22 minutes, 35 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 72.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-28 16:37:51	2020-06-28 16:52:04	14 minutes, 13 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 17:04:18	2020-06-28 17:14:32	10 minutes, 14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 17:30:50	2020-06-28 17:34:53	4 minutes, 3 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 21:47:13	2020-06-28 21:53:18	6 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 22:09:40	2020-06-28 22:20:50	11 minutes, 10 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 22:33:00	2020-06-28 22:49:20	16 minutes, 20 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-28 22:58:30	2020-06-28 23:18:09	19 minutes, 39 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 23:23:14	2020-06-28 23:48:30	25 minutes, 16 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-28 23:52:42	2020-06-29 00:19:10	26 minutes, 28 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-29 00:25:12	2020-06-29 00:56:39	31 minutes, 27 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-29 00:58:30	2020-06-29 01:31:11	32 minutes, 41 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-29 01:33:13	2020-06-29 02:10:25	37 minutes, 12 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-29 02:11:26	2020-06-29 13:03:30	10 hours, 52 minutes, 4 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 74.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-29 02:35:48	2020-06-29 02:36:49	1 minute	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2020-06-29 08:42:14 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: Alarm communication occurred for 1 minute. During this time frame, data collectors were collecting the data offline. Data was reloaded into the system after the communication was restored.
2020-06-29 13:04:37	2020-06-29 13:21:58	17 minutes, 21 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 72.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-29 13:29:08	2020-06-29 13:42:17	13 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-29 13:56:41	2020-06-29 14:03:12	6 minutes, 31 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 01:44:40	2020-06-30 01:47:44	3 minutes, 4 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-30 02:09:21	2020-06-30 02:18:30	9 minutes, 9 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 02:41:14	2020-06-30 02:55:41	14 minutes, 27 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 03:12:20	2020-06-30 03:28:04	15 minutes, 44 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 03:40:34	2020-06-30 04:01:48	21 minutes, 14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 71.0 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 04:13:30	2020-06-30 04:36:50	23 minutes, 20 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 04:47:21	2020-06-30 05:15:01	27 minutes, 40 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-30 05:25:28	2020-06-30 05:53:30	28 minutes, 2 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 06:03:48	2020-06-30 06:34:53	31 minutes, 5 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 06:45:19	2020-06-30 07:17:48	32 minutes, 29 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 07:26:08	2020-06-30 07:58:30	32 minutes, 22 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 08:07:15	2020-06-30 08:37:04	29 minutes, 49 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 08:44:05	2020-06-30 09:13:30	29 minutes, 25 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-30 09:18:30	2020-06-30 09:44:10	25 minutes, 40 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 09:47:28	2020-06-30 10:58:20	1 hour, 10 minutes, 52 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 11:01:24	2020-06-30 11:21:13	19 minutes, 49 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 11:27:35	2020-06-30 11:29:50	2 minutes, 15 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 11:30:57	2020-06-30 11:32:01	1 minute, 4 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 11:33:10	2020-06-30 11:40:36	7 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.9 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-30 11:41:54	2020-06-30 11:43:07	1 minute, 13 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 11:59:47	2020-06-30 12:00:48	1 minute, 1 second	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 12:20:07	2020-06-30 12:23:09	3 minutes, 2 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 12:41:34	2020-06-30 12:43:22	1 minute, 48 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 21:30:46	2020-06-30 21:32:47	2 minutes, 1 second	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 21:49:58	2020-06-30 22:01:06	11 minutes, 8 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 70.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-06-30 22:13:14	2020-06-30 22:27:22	14 minutes, 8 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 70.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 22:37:29	2020-06-30 22:56:43	19 minutes, 14 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 23:04:48	2020-06-30 23:26:01	21 minutes, 13 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-06-30 23:32:05	2020-06-30 23:56:20	24 minutes, 15 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 71.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 00:04:29	2020-07-01 00:32:45	28 minutes, 16 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 00:40:50	2020-07-01 01:11:20	30 minutes, 30 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 71.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-07-01 01:18:25	2020-07-01 01:51:52	33 minutes, 27 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 71.8 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 01:56:55	2020-07-01 02:33:20	36 minutes, 25 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 02:38:24	2020-07-01 03:16:05	37 minutes, 41 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.2 %RH Max value: 72.0 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 03:21:08	2020-07-01 04:01:21	40 minutes, 13 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.3 %RH Max value: 72.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 04:06:28	2020-07-01 04:48:30	42 minutes, 2 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 04:51:33	2020-07-01 05:34:57	43 minutes, 24 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2020-07-01 05:37:59	2020-07-01 06:21:02	43 minutes, 3 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 72.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 06:23:04	2020-07-01 11:53:30	5 hours, 30 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Min value: 70.1 %RH Max value: 73.5 %RH Affected location: System/ETHICON/Warehouse RH (11928)	
2020-07-01 11:58:30		21 minutes, 26 seconds	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON High Humidity Warning for High Threshold: location value greater than 70.0 %RH for System/ETHICON/Warehouse RH Affected location: System/ETHICON/Warehouse RH (11928)	

Name: Eric Smith Name: Robert Peters Name: Ibrahim Bitar

Date:Date:Date:Signature:Signature:Signature: