



Document Number: SCN064637

Revision: A

Group: Scanned (Hardcopy) Item

Type: Environmental Reports - Svs Ctr

State: Released

Latest Released: YES

Implemented Date: 05/20/2019

Stamp Date: Monday, May 20, 2019 4:12:33 PM EST

viewLinc Alarm Report

Report name	ETHICON Quarterly Report
Alarm events	from 2018-10-01 12:00:00 to 2019-01-01 12:00:00
Report generated on	2019-01-01 12:03:34 (UTC-05:00) Eastern Time (US & Canada)
Include zones and locations:	System/ETHICON
Include alarm details:	No
Include system alarms:	Yes
Include device communication alarms:	Yes
Include device configuration alarms:	Yes
Include device validation alarms:	Yes
Include device calibration alarms:	Yes
Include threshold alarms:	Yes
Include threshold categories:	Alarms Only

Summary

Total active alarms:	219
Activated alarms:	168
Deactivated alarms:	169
Acknowledged alarms:	108

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-01-21 05:36:27	2018-10-09 11:15:42	8 months, 21 days, 4 hours, 39 minutes, 15 seconds	Configuration Database	Configuration Changed Alarm: Default Configuration Changed Alarm for Configuration Database	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities Configuration Database" comment: System under observation.
2018-08-17 10:02:09	2018-08-17 10:05:10	3 minutes, 1 second	Threshold Alarm: ETHICON Hi/Lo	Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities value greater than 80.0 %RH for System/ETHICON/Warehouse RH" comment: System under observation.
2018-08-17 10:05:14	2018-08-17 10:06:12	58 seconds	Threshold Alarm: ETHICON Hi/Lo	Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.3 %RH Max value: 80.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)
2018-08-17 10:18:25	2018-08-17 10:27:30	9 minutes, 5 seconds	Threshold Alarm: ETHICON Hi/Lo	Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)
2018-08-17 10:40:39	2018-08-17 10:47:38	6 minutes, 59 seconds	Threshold Alarm: ETHICON Hi/Lo	Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 81.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)
2018-08-17 11:01:09	2018-08-17 11:09:08	7 minutes, 59 seconds	Threshold Alarm: ETHICON Hi/Lo	Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.7 %RH Affected location: System/ETHICON/Warehouse RH (11928)
2018-08-18 06:36:17	2018-08-18 06:37:17	1 minute	Threshold Alarm: ETHICON Hi/Lo	Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-08-18 07:04:53	2018-08-18 07:09:58	5 minutes, 5 seconds	System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:41 by microm (Maurice Croom); "Facilities notified " comment: System under observation.
2018-08-18 07:35:06	2018-08-18 07:43:09	8 minutes, 3 seconds	System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:41 by microm (Maurice Croom); "Facilities notified " comment: System under observation.
2018-08-18 08:06:25	2018-08-18 08:16:28	10 minutes, 3 seconds	System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:41 by microm (Maurice Croom); "Facilities notified " comment: System under observation.
2018-08-18 08:36:54	2018-08-18 08:47:13	10 minutes, 19 seconds	System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:42 by microm (Maurice Croom); "Facilities notified " comment: System under observation.
2018-08-18 09:06:22	2018-08-18 09:15:41	9 minutes, 19 seconds	System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microm (Maurice Croom); "Facilities notified " comment: System under observation.
2018-08-18 09:34:01	2018-08-18 09:40:03	6 minutes, 2 seconds	System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Acknowledged on 2018-10-09 11:15:43 by microm (Maurice Croom); "Facilities notified " comment: System under observation.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-08-18 09:59:19	2018-08-18 10:03:27	4 minutes, 8 seconds	Threshold Alarm: ETHICON HI\Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON HI\Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:45 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-10 19:31:02	2018-09-10 19:36:04	5 minutes, 2 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing T (11918),Repair & Testing RH (11916)	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-10 19:31:02	2018-09-10 19:38:05	7 minutes, 3 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-10 19:31:02	2018-09-10 19:38:05	7 minutes, 3 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2018-10-09 11:15:44 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-10 19:31:02	2018-09-10 19:36:04	5 minutes, 1 second	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2018-10-09 11:15:44 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-10 19:31:02	2018-09-10 19:42:06	11 minutes, 4 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2018-10-09 11:15:44 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-12 15:46:20	2018-09-12 19:40:23	3 hours, 54 minutes, 3 seconds	Threshold Alarm: ETHICON HI\Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Affected location: System/ETHICON/Repair & Testing2 T (11920)	Threshold Alarm: ETHICON HI\Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.53 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities notified" comment: System under observation.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-09-12 19:31:10	2018-09-12 18 minutes, 6 seconds		Threshold Alarm: ETHICON Hilo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Hilo/Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.89 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-13 22:59:35	2018-09-13 3 hours, 22 minutes, 19 seconds		Threshold Alarm: ETHICON Hilo/Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Hilo/Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.19 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 11:15:45 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-13 21:08:23	2018-09-13 23 seconds		Threshold Alarm: ETHICON Hilo/Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Hilo/Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-13 22:53:34	2018-09-13 1 hour, 44 minutes, 13 seconds		Threshold Alarm: ETHICON Hilo/Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Hilo/Lo Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-20 05:00:46	2018-09-28 09:13:04	8 days, 4 hours, 12 minutes, 18 seconds	Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITUSRRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Device Alarm for Device ETHIC-RepairTs2 (17332036) on ITUSRRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922); Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-20 05:00:46	2018-09-28 09:20:07	8 days, 4 hours, 19 minutes, 21 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSRRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on ITUSRRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918); Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-20 05:00:46	2018-09-28 09:33:38	8 days, 4 hours, 32 minutes, 52 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on ITUSRRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926); Spare parts & Shipping T (11924)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-09-20 05:00:46	2018-09-28 09:31:20	8 days, 4 hours, 24 minutes, 26 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Enterprise Server (17332038) on ITSUSRAWSP04243.jnj.com Affected locations. Receiving&Decontamination T (11912),Receiving&Decontamination T (11914)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-09-20 05:00:51	2018-09-28 09:31:20	8 days, 4 hours, 30 minutes, 28 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Device Calibration Reminder: ETHICON Enterprise Server (17332038) on ITSUSRAWSP04243.jnj.com Affected locations. Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-09-25 12:08:40	2018-09-25 12:12:42	4 minutes, 2 seconds	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-09-26 01:18:04	2018-09-26 01:19:04	1 minute	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-09-26 01:24:05	2018-09-26 01:26:09	2 minutes, 4 seconds	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-09-26 01:51:50	2018-09-26 01:52:51	1 minute, 1 second	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location Value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified " comment: System under observation.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-09-26 01:53:52	2018-09-26 01:57:53	4 minutes, 1 second	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 02:21:59	2018-09-26 02:29:00	7 minutes, 1 second	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 02:52:09	2018-09-26 02:55:10	3 minutes, 1 second	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 02:57:13	2018-09-26 03:00:10	2 minutes, 57 seconds	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 03:23:38	2018-09-26 03:31:41	8 minutes, 3 seconds	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:45 by microom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 03:57:18	2018-09-26 04:05:10	7 minutes, 52 seconds	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON H/L/o Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.3 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:45 by microom (Maurice Croom); "Facilities notified" comment: System under observation.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-09-26 04:28:49	2018-09-26 04:41:01	12 minutes, 12 seconds	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:45 by mcroom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 05:04:27	2018-09-26 05:20:52	16 minutes, 25 seconds	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:45 by mcroom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 05:44:15	2018-09-26 05:58:18	14 minutes, 3 seconds	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:41 by mcroom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 06:19:34	2018-09-26 06:32:37	13 minutes, 3 seconds	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.6 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by mcroom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 06:53:47	2018-09-26 07:00:27	6 minutes, 40 seconds	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.4 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by mcroom (Maurice Croom); "Facilities notified" comment: System under observation.
2018-09-26 07:23:36	2018-09-26 07:24:36	1 minute	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hi/Lo Warning for High Threshold: location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.1 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by mcroom (Maurice Croom); "Facilities notified" comment: System under observation.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-09-26 07:25:10	2018-09-26 07:28:38	3 minutes, 28 seconds	Threshold Alarm: ETHICON Hilo Warning for High Threshold; location value greater than 80.0 %RH for System/ETHICON/Warehouse RH	Threshold Alarm: ETHICON Hilo Warning for High Threshold; location value greater than 80.0 %RH for System/ETHICON/Warehouse RH Min value: 80.1 %RH Max value: 80.2 %RH Affected location: System/ETHICON/Warehouse RH (11928)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.
2018-09-28 09:11:14	2018-09-28 09:12:05	51 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922); Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 11:15:45 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.
2018-09-28 09:17:16	2018-09-28 09:18:09	52 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918); Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:45 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.
2018-09-28 09:23:20	2018-09-28 09:24:10	49 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912); Receiving&Decontamination T (11914)	Acknowledged on 2018-10-09 11:15:45 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.
2018-09-28 09:29:28	2018-09-28 09:30:21	52 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928); Warehouse T (11930)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.
2018-09-28 09:32:29	2018-09-28 09:33:38	1 minute, 8 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926); Spare parts & Shipping T (11924)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.
2018-10-06 11:11:56	2018-10-06 11:16:16	4 minutes, 20 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926); Spare parts & Shipping T (11924)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.
2018-10-06 11:11:56	2018-10-06 11:16:16	4 minutes, 20 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918); Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:43 by microom (Maurice Croom); "Facilities notified"; comment: System under observation.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-10-06 11:51:04	2018-10-06 11:53:41	2 minutes, 37 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITUSRRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-10-06 12:38:51	2018-10-06 12:41:15	2 minutes, 24 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITUSRRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:42 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-10-06 12:38:51	2018-10-06 12:41:13	2 minutes, 22 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITUSRRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-10-06 12:39:23	2018-10-06 12:41:13	1 minute, 50 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITUSRRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-10-06 12:40:37	2018-10-06 12:41:08	31 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSRRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITUSRRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 11:15:41 by microom (Maurice Croom); "Facilities notified " comment: System under observation.
2018-10-09 14:14:20	2018-10-09 14:29:14	14 minutes, 54 seconds	Threshold Alarm: ETHICON Hi Temp Alarm for HighHigh Threshold: location value greater than 70.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Hi Temp Alarm for HighHigh Threshold: location value greater than 70.00 °F for System/ETHICON/Repair & Testing T Min value: 71.08 °F Max value: 71.23 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2018-10-09 14:29:14 by microom (Maurice Croom); "Facilities notified " comment: Threshold Template Modified
2018-10-09 14:14:20	2018-10-09 14:29:14	14 minutes, 54 seconds	Threshold Alarm: ETHICON Hi Temp Warning for High threshold: location value greater than 69.50 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Hi Temp Warning for High threshold: location value greater than 69.50 °F for System/ETHICON/Repair & Testing T Min value: 71.08 °F Max value: 71.23 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2018-10-09 14:29:14 by microom (Maurice Croom); "Facilities notified " comment: Threshold Template Modified

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-10-09 14:43:31	2018-10-09 14:29:14	14 minutes, 43 seconds	Threshold Alarm: ETHICON Hi Temp Alarm for High-High Threshold: location Value greater than 70.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Hi Temp Alarm for High-High Threshold: location value greater than 70.00 °F for System/ETHICON/Repair & Testing2 T Min value: 70.93 °F Max value: 71.08 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 14:29:14 by mcroom (Maurice Croom). comment: Threshold Template Modified
2018-10-09 14:14:31	2018-10-09 14:29:14	14 minutes, 43 seconds	Threshold Alarm: ETHICON Hi Temp Warning for High Threshold: location value greater than 69.50 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Hi Temp Warning for High Threshold: location value greater than 69.50 °F for System/ETHICON/Repair & Testing2 T Min value: 70.93 °F Max value: 71.08 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-10-09 14:29:14 by mcroom (Maurice Croom). comment: Threshold Template Modified
2018-10-12 03:44:20	2018-10-12 03:44:44	24 seconds	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11920)	Acknowledged on 2018-10-09 14:29:14 by mcroom (Maurice Croom). comment: Threshold Template Modified
2018-10-12 03:45:41	2018-10-12 03:47:42	2 minutes, 1 second	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2018-10-09 14:29:14 by mcroom (Maurice Croom). comment: Threshold Template Modified
2018-10-12 03:52:44	2018-10-12 03:53:46	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2018-10-09 14:29:14 by mcroom (Maurice Croom). comment: Threshold Template Modified
2018-10-12 03:54:20	2018-10-12 03:54:50	30 seconds	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Acknowledged on 2018-10-09 14:29:14 by mcroom (Maurice Croom). comment: Threshold Template Modified

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-10-12 03:55:48	2018-10-12 07:03:12	3 hours, 7 minutes, 24 seconds	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.7 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2018-10-12 06:12:03 by microon (Maurice Croom); ""
2018-10-12 04:10:53	2018-10-12 04:11:54	1 minute, 1 second	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2018-10-12 04:12:30	2018-10-12 04:14:57	2 minutes, 27 seconds	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2018-10-12 04:15:58	2018-10-12 06:38:43	2 hours, 22 minutes, 45 seconds	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2018-10-12 06:39:46	2018-10-12 07:01:06	21 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing2 RH Min value: 34.0 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing2 RH (1922)	
2018-10-20 18:41:24	2018-10-20 18:42:24	1 minute	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humid Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-10-28 16:33:45	2018-10-28 16:40:50	7 minutes, 4 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSURAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH ('11912),Receiving&Decontamination T ('11914)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments", comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:33:45	2018-10-28 16:40:50	7 minutes, 4 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSURAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T ('11930)	Acknowledged on 2018-10-29 12:52:51 by mcroom (Maurice Croom); "See comments", comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:33:45	2018-10-28 16:39:48	6 minutes, 3 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSURAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T ('11924)	Acknowledged on 2018-10-29 12:52:51 by mcroom (Maurice Croom); "See comments", comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:33:45	2018-10-28 16:46:53	13 minutes, 7 seconds	Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTs2 (17332036) on Enterprise Server ITSURAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T ('11920)	Acknowledged on 2018-10-29 12:52:51 by mcroom (Maurice Croom); "See comments", comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:33:45	2018-10-28 16:46:53	13 minutes, 7 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSURAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T ('11916)	Acknowledged on 2018-10-29 12:52:51 by mcroom (Maurice Croom); "See comments", comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:41:51	2018-10-28 16:48:54	7 minutes, 3 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSURAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSURAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T ('11930)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments", comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-10-28 16:41:51	2018-10-28 16:49:56	8 minutes, 4 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments" comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:51:57	2018-10-28 17:02:03	22 minutes, 14 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments" comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:51:57	2018-10-28 16:57:59	10 minutes, 5 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments" comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:51:57	2018-10-28 16:57:59	6 minutes, 2 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments" comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:51:57	2018-10-28 17:03:05	11 minutes, 7 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments" comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.
2018-10-28 16:51:57	2018-10-28 17:01:02	9 minutes, 4 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2018-10-29 12:52:50 by mcroom (Maurice Croom); "See comments" comment: There was a network outage that caused multiple communication errors. No further action was needed. The network was restored and device data that was taken was stored on the loggers and transferred when the network was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-09 23:42:10	2018-11-09 23:43:20	1 minute, 9 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912),Receiving&Decontamination T (11914)	Acknowledged on 2018-11-12 11:10:53 by microon (Maurice Croom): "see comments", comment: Device communication alarm was intermittent and the loggers log every 5 minutes. No data was lost. Internal memory of the device has all data and uploads to viewLinc when the alarm goes off. Alarm viewLinc when the alarm goes off. Alarm was less than 2 minutes due to a brief network LAN lose.
2018-11-09 23:42:10	2018-11-09 23:43:19	1 minute, 8 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928),Warehouse T (11930)	Acknowledged on 2018-11-12 11:10:53 by microon (Maurice Croom): "see comments", comment: Device communication alarm was intermittent and the loggers log every 5 minutes. No data was lost. Internal memory of the device has all data and uploads to viewLinc when the alarm goes off. Alarm viewLinc when the alarm goes off. Alarm was less than 2 minutes due to a brief network LAN lose.
2018-11-09 23:42:10	2018-11-09 23:43:36	1 minute, 25 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922),Repair & Testing2 T (11920)	Acknowledged on 2018-11-12 11:10:52 by microon (Maurice Croom): "see comments", comment: Device communication alarm was intermittent and the loggers log every 5 minutes. No data was lost. Internal memory of the device has all data and uploads to viewLinc when the alarm goes off. Alarm viewLinc when the alarm goes off. Alarm was less than 2 minutes due to a brief network LAN lose.
2018-11-09 23:42:11	2018-11-09 23:43:18	1 minute, 7 seconds	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926),Spare parts & Shipping T (11924)	Acknowledged on 2018-11-12 11:10:52 by microon (Maurice Croom): "see comments", comment: Device communication alarm was intermittent and the loggers log every 5 minutes. No data was lost. Internal memory of the device has all data and uploads to viewLinc when the alarm goes off. Alarm viewLinc when the alarm goes off. Alarm was less than 2 minutes due to a brief network LAN lose.
2018-11-09 23:42:11	2018-11-09 23:43:18	1 minute, 7 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918),Repair & Testing T (11916)	Acknowledged on 2018-11-12 11:10:53 by microon (Maurice Croom): "see comments", comment: Device communication alarm was intermittent and the loggers log every 5 minutes. No data was lost. Internal memory of the device has all data and uploads to viewLinc when the alarm goes off. Alarm viewLinc when the alarm goes off. Alarm was less than 2 minutes due to a brief network LAN lose.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-10 06:25:53	2018-11-10 06:27:30	1 minute, 37 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-10 06:27:58	2018-11-10 08:12:30	1 hour, 44 minutes, 32 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-10 07:32:14	2018-11-10 07:39:18	7 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 68.64 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-10 07:40:22	2018-11-10 07:46:22	6 minutes	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-10 07:54:20	2018-11-10 07:54:29	9 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-10 20:54:21	2018-11-10 20:59:23	5 minutes, 2 seconds	Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-10 21:00:24	2018-11-10 21:02:26	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-10 23:03:31	2018-11-11 08:52:06	11 hours, 48 minutes, 35 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-10 23:01:01	2018-11-10 23:03:02	2 minutes, 1 second	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-10 23:04:03	2018-11-10 23:24:10	20 minutes, 7 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2018-11-10 23:24:20	2018-11-10 23:25:15	55 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2018-11-10 23:39:15	2018-11-11 09:08:11	9 hours, 28 minutes, 56 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.22 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-11 07:11:44	2018-11-11 07:12:30	46 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-11-12 11:14:34 by mcroom (Maurice Croom): "See comments" comment: There were minor deviations below 68 degrees for less than a minute. The HVAC system was adjusting to a drop in external temperatures. No capital equipment was operated during this time. No further actions were taken nor required.
2018-11-11 07:12:49	2018-11-11 07:56:48	43 minutes, 59 seconds	Temperature Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-11-12 11:14:34 by mcroom (Maurice Croom): "see comments" comment: There were minor deviations below 68 degrees for less than a minute. The HVAC system was adjusting to a drop in external temperatures. No capital equipment was operated during this time. No further actions were taken nor required.
2018-11-14 01:56:12	2018-11-14 01:57:14	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-11-12 11:14:34 by mcroom (Maurice Croom): "see comments" comment: There were minor deviations below 68 degrees for less than a minute. The HVAC system was adjusting to a drop in external temperatures. No capital equipment was operated during this time. No further actions were taken nor required.
2018-11-14 01:58:21	2018-11-14 08:58:25	7 hours, 0 minutes, 4 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-11-12 11:14:34 by mcroom (Maurice Croom): "see comments" comment: There were minor deviations below 68 degrees for less than a minute. The HVAC system was adjusting to a drop in external temperatures. No capital equipment was operated during this time. No further actions were taken nor required.
2018-11-14 03:21:47	2018-11-14 03:24:53	3 minutes, 6 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-11-12 11:14:34 by mcroom (Maurice Croom): "see comments" comment: There were minor deviations below 68 degrees for less than a minute. The HVAC system was adjusting to a drop in external temperatures. No capital equipment was operated during this time. No further actions were taken nor required.
2018-11-14 03:36:56	2018-11-14 03:37:58	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-11-12 11:14:34 by mcroom (Maurice Croom): "see comments" comment: There were minor deviations below 68 degrees for less than a minute. The HVAC system was adjusting to a drop in external temperatures. No capital equipment was operated during this time. No further actions were taken nor required.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-14 04:04:09	2018-11-14 04:05:15	1 minute, 6 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	
2018-11-14 07:54:20	2018-11-14 08:05:42	11 minutes, 22 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (1916)	
2018-11-14 08:24:20	2018-11-14 08:25:52	28 minutes, 45 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	
2018-11-14 08:22:50	2018-11-14 08:23:52	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.4 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-14 08:24:58	2018-11-14 08:25:57	59 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.2 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-14 08:24:58	2018-11-14 08:25:57	59 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	
2018-11-14 08:28:00	2018-11-14 08:29:02	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.1 %RH Max value: 34.1 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-14 08:34:06	2018-11-14 08:35:12	1 minute, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-14 08:54:16	2018-11-14 08:55:23	1 minute, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-14 08:59:28	2018-11-14 09:01:37	2 minutes, 9 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	
2018-11-14 09:40:57	2018-11-14 09:41:59	1 minute, 2 seconds	Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-14 09:45:06	2018-11-14 09:50:10	5 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2018-11-22 07:43:35	2018-11-22 07:44:38	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	
2018-11-22 07:45:41	2018-11-22 07:46:44	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	
2018-11-22 07:54:54	2018-11-22 07:55:56	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	
2018-11-22 07:57:30	2018-11-22 07:59:02	1 minute, 32 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	
2018-11-23 06:28:49	2018-11-23 06:29:52	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-23 06:30:54	2018-11-23 06:38:59	8 minutes, 5 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-23 06:42:02	2018-11-23 07:20:17	38 minutes, 15 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.93 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-23 07:21:19	2018-11-23 07:29:24	8 minutes, 5 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-23 07:30:27	2018-11-23 08:08:55	38 minutes, 28 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 08:06:56	2018-11-27 08:08:02	1 minute, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-27 08:16:07	2018-11-27 08:17:15	1 minute, 8 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.3 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-27 08:19:20	2018-11-27 08:20:33	1 minute, 13 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 34.1 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 34.1 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2018-11-27 11:15:26	2018-11-27 11:19:20	3 minutes, 54 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2018-11-27 12:03:52	2018-11-27 12:05:02	1 minute, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2018-11-27 12:06:57	2018-11-27 12:08:03	1 minute, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.9 %RH Max value: 32.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 32.9 %RH Max value: 32.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2018-11-27 12:10:10	2018-11-27 12:16:14	6 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)
2018-11-27 12:19:19	2018-11-27 12:21:23	2 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.8 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.8 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-27 12:22:29	2018-11-27 12:23:34	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.1 %RH Max value: 34.1 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-27 12:24:39	2018-11-27 12:25:37	58 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-27 12:30:47	2018-11-27 12:31:52	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.9 %RH Max value: 33.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-27 12:34:20	2018-11-27 12:35:01	41 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-27 12:39:03	2018-11-27 12:39:20	17 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-11-27 12:45:21	2018-11-27 12:46:21	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-27 12:49:20	2018-11-27 12:49:24	4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.6 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-27 12:51:25	2018-11-27 12:52:32	1 minute, 7 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.5 %RH Max value: 33.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-27 12:55:36	2018-11-27 12:57:42	2 minutes, 6 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-27 19:18:01	2018-11-27 19:19:03	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-27 19:20:06	2018-11-27 19:21:08	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 19:22:30	2018-11-27 19:27:17	4 minutes, 47 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-27 19:26:14	2018-11-27 19:27:17	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-27 19:29:19	2018-11-27 19:35:23	6 minutes, 4 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 19:42:30	2018-11-27 19:44:31	2 minutes, 1 second	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 19:45:33	2018-11-27 19:46:36	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 19:47:42	2018-11-27 19:48:42	1 minute	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 19:49:44	2018-11-27 19:59:49	10 minutes, 5 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-27 20:00:52	2018-11-28 08:46:23	12 hours, 45 minutes, 31 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.23 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 20:42:06	2018-11-27 20:43:09	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.23 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-27 20:44:12	2018-11-28 09:13:34	12 hours, 29 minutes, 22 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.30 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2018-11-27 23:22:15	2018-11-27 23:23:17	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 07:22:40	2018-11-28 07:25:43	3 minutes, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.7 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 07:26:45	2018-11-28 07:27:48	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-28 07:28:51	2018-11-28 07:29:20	29 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 07:31:56	2018-11-28 07:32:58	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 11:21:43	2018-11-28 11:22:46	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.5 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 11:24:53	2018-11-28 11:25:51	58 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 11:26:53	2018-11-28 11:28:57	2 minutes, 4 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.2 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 15:28:10	2018-11-28 15:30:15	2 minutes, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.5 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-11-28 15:31:12	2018-11-28 15:32:14	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.4 %RH Max value: 34.4 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 15:34:16	2018-11-28 15:35:21	1 minute, 5 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 15:38:20	2018-11-28 15:39:20	1 minute	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	
2018-11-28 19:27:34	2018-11-29 07:44:32	12 hours, 16 minutes, 58 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.45 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-11-28 19:57:41	2018-11-29 07:34:20	11 hours, 36 minutes, 39 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.52 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2018-12-04 14:31:57	2018-12-04 14:33:59	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (11918)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-04 14:35:03	2018-12-04 14:37:01	1 minute, 58 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.6 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-12-05 14:52:57	2018-12-05 14:53:59	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.9 %RH Max value: 34.9 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-12-05 14:54:20	2018-12-05 14:55:05	45 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.8 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-12-05 15:04:09	2018-12-05 15:05:19	1 minute, 10 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.7 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-12-05 15:14:20	2018-12-05 15:17:40	3 minutes, 20 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 34.3 %RH Max value: 34.8 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	
2018-12-07 03:02:30	2018-12-07 08:51:11	5 hours, 48 minutes, 41 seconds	Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.19 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-07 03:24:20	2018-12-07 09:14:20	5 hours, 50 minutes	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.26 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2018-12-07 21:12:14	2018-12-07 21:17:30	5 minutes, 16 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 68.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-12-07 21:18:20	2018-12-08 12:53:27	15 hours, 35 minutes, 7 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.90 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	
2018-12-07 21:31:21	2018-12-08 13:07:28	15 hours, 36 minutes, 7 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 67.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	
2018-12-08 05:56:32	2018-12-08 05:57:30	58 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:35:39 by ibitar1 (Ibrahim Bitar); "No Action Taken" comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-08 05:58:35	2018-12-08 06:00:37	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:32:57 by ibitar1 (Ibrahim Bitar); "No Action Taken" comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-08 06:02:30	2018-12-08 06:02:41	11 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:32:28 by ibitar1 (Ibrahim Bitar); "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-08 06:12:45	2018-12-08 06:27:30	14 minutes, 45 seconds	Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:32:28 by ibitar1 (Ibrahim Bitar); "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-08 06:30:47	2018-12-08 09:03:31	2 hours, 32 minutes, 44 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:32:28 by ibatar1 (Ibrahim Bitar); "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-08 08:08:09	2018-12-08 08:09:20	1 minute, 11 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:32:28 by ibatar1 (Ibrahim Bitar); "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-08 08:34:17	2018-12-08 08:34:20	3 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11916)	Acknowledged on 2018-12-10 11:40:35 by ibatar1 (Ibrahim Bitar); "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-08 08:38:20	2018-12-08 08:39:20	1 minute	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11916)	Acknowledged on 2018-12-10 11:40:35 by ibatar1 (Ibrahim Bitar); "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-08 09:04:29	2018-12-08 09:06:31	2 minutes, 2 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:25:44 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-08 14:47:56	2018-12-08 14:49:00	1 minute, 3 seconds	Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTst2 (17332036) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing2 RH (11922), Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:46:49 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. The communication was down for only one minute and was restored.
2018-12-08 14:47:58	2018-12-08 14:49:00	1 minute, 1 second	Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Spare&Ship (17332040) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Spare parts & Shipping RH (11926), Spare parts & Shipping T (11924)	Acknowledged on 2018-12-10 11:44:00 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. The communication was down for only one minute and was restored.
2018-12-08 14:47:58	2018-12-08 14:48:57	58 seconds	Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-RepairTest (17332042) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Repair & Testing RH (11918), Repair & Testing T (11916)	Acknowledged on 2018-12-10 11:47:18 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. The communication was down for only one minute and was restored.
2018-12-08 14:47:58	2018-12-08 14:48:57	58 seconds	Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Rec&Decon (17332041) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Receiving&Decontamination RH (11912), Receiving&Decontamination T (11914)	Acknowledged on 2018-12-09 18:41:52 by ibitar1 (Ibrahim Bitar): "Communication was restored less than 60 seconds after", comment: no action
2018-12-08 14:47:59	2018-12-08 14:48:57	58 seconds	Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com	Communication Alarm: ETHICON Device Alarm for Device ETHIC-Warehouse (17332038) on Enterprise Server ITSUSRAWSP04243.jnj.com Affected locations: Warehouse RH (11928), Warehouse T (11930)	Acknowledged on 2018-12-10 11:43:31 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. The communication was down for only one minute and was restored.
2018-12-08 16:59:15	2018-12-09 12:08:50	19 hours, 9 minutes, 35 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 68.04 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (11916)	Acknowledged on 2018-12-10 11:43:31 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. The communication was down for only one minute and was restored.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-08 17:02:17	2018-12-09 11:44:44	18 hours, 42 minutes, 27 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:25:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-09 07:00:22	2018-12-09 07:01:24	1 minute, 2 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:25:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-09 07:09:27	2018-12-09 07:10:28	1 minute, 1 second	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:25:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-09 07:11:28	2018-12-09 07:12:29	1 minute, 1 second	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:25:17 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-09 07:13:34	2018-12-09 07:14:32	58 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:18:17 by ibitar1 (Ibrahim Bitar): "No Action was taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.
2018-12-09 07:17:37	2018-12-09 07:20:36	2 minutes, 59 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for LowLow Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (11920)	Acknowledged on 2018-12-10 11:17:45 by ibitar1 (Ibrahim Bitar): "No Action Taken", comment: This alarm had been triggered while there weren't any technicians working on any devices. No action was taken.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-09 20:03:37	2018-12-10 10:35:58	14 hours, 32 minutes, 21 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 67.08 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 67.08 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)
2018-12-09 09:05:38	2018-12-10 09:56:24	13 hours, 50 minutes, 46 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 66.94 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 66.94 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)
2018-12-10 01:23:06	2018-12-10 01:24:04	58 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 68.00 Affected location: System/ETHICON/Repair & Testing2 T (1920)	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.97 °F Max value: 68.00 Affected location: System/ETHICON/Repair & Testing2 T (1920)
2018-12-10 01:25:05	2018-12-10 09:06:10	7 hours, 41 minutes, 5 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 66.94 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	Acknowledged on 2018-12-10 11:15:26 by Ibitar1 (Ibrahim Bitar); "No action taken", comment: This alarm had been triggered while there wasn't any technicians working on any devices. No action was taken.
2018-12-10 09:21:48	2018-12-10 09:21:48	7 hours, 42 minutes, 39 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.08 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	Acknowledged on 2018-12-10 11:15:42 by Ibitar1 (Ibrahim Bitar); "Advised BWI technicians to not work on units and Contacted Facility", comment: AC Temperature setting has been adjusted at 10:12:2018 7:00 by Paul Kolp. Advised BWI technicians to not work and Contacted Facility. Returned to working on the units after the temperature had been restored to normal threshold.
2018-12-10 10:05:12	2018-12-11 10:05:12	15 hours, 51 minutes, 38 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 66.38 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing2 T Min value: 66.38 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	Acknowledged on 2018-12-10 11:37:04 by Ibitar1 (Ibrahim Bitar); "Advised BWI technicians to not work and Contacted Facility", comment: AC Temperature setting has been adjusted at 10:12:2018 7:00 by Paul Kolp. Advised BWI technicians to not work and Contacted Facility maintenance. Returned to working on the units after the temperature had been restored to normal threshold.

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-10 18:20:38	2018-12-11 10:49:20	16 hours, 28 minutes, 42 seconds	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Warning for Low Threshold: location value less than 69.00 °F for System/ETHICON/Repair & Testing T Min value: 66.56 °F Max value: 68.97 °F Affected location: System/ETHICON/Repair & Testing T	
2018-12-10 19:09:20	2018-12-10 19:10:58	1 minute, 38 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	
2018-12-10 20:09:16	2018-12-11 08:41:19	12 hours, 32 minutes, 3 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for Low Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	
2018-12-10 20:25:23	2018-12-10 20:26:26	1 minute, 3 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Acknowledged on 2018-12-11 08:41:19 by ibtar1 (Ibrahim Bitar); "", comment: Alarm Template Modified
2018-12-10 20:26:26	2018-12-11 08:41:19	12 hours, 14 minutes, 53 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for Low Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing RH	Acknowledged on 2018-12-11 08:41:19 by ibtar1 (Ibrahim Bitar); "", comment: Alarm Template Modified
2018-12-10 20:26:26	2018-12-11 08:41:19	12 hours, 14 minutes, 53 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for Low Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing RH	Acknowledged on 2018-12-11 08:41:19 by ibtar1 (Ibrahim Bitar); "", comment: Alarm Template Modified
2018-12-10 20:27:28	2018-12-10 20:28:31	1 minute, 3 seconds	Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	

Activation	Deactivation	Duration	Source	Description	Acknowledgement
2018-12-10 20:29:20	2018-12-10 20:30:36	1 minute, 16 seconds	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH	Threshold Alarm: ETHICON Low Humidity Warning for Low Threshold: location value less than 35.0 %RH for System/ETHICON/Repair & Testing RH Min value: 33.7 %RH Max value: 34.2 %RH Affected location: System/ETHICON/Repair & Testing RH (1918)	Acknowledged on 2018-12-11 10:50:27 by ibitari (Ibrahim Bitar). "Advised BWI technicians to not work and contacted facility." comment: Temperature had dropped over night and caused the temperature indoor to drop. AC temperature setting has been adjusted at 11.12.2018 7:00 by Paul Kolp. Returned to working on the units after the temperature had been restored to normal threshold.
2018-12-11 08:41:49	2018-12-11 09:31:54	50 minutes, 5 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing T Min value: 67.37 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing T (1916)	Acknowledged on 2018-12-11 10:50:27 by ibitari (Ibrahim Bitar). "Advised BWI technicians to not work and contacted facility." comment: Temperature had dropped over night and caused the temperature indoor to drop. AC temperature setting has been adjusted at 11.12.2018 7:00 by Paul Kolp. Returned to working on the units after the temperature had been restored to normal threshold.
2018-12-11 08:41:49	2018-12-11 09:14:42	32 minutes, 53 seconds	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T	Threshold Alarm: ETHICON Low Temperature Alarm for Low/Low Threshold: location value less than 68.00 °F for System/ETHICON/Repair & Testing2 T Min value: 67.53 °F Max value: 67.97 °F Affected location: System/ETHICON/Repair & Testing2 T (1920)	Acknowledged on 2018-12-11 10:50:27 by ibitari (Ibrahim Bitar). "Advised BWI technicians to not work and contacted facility." comment: Temperature had dropped over night and caused the temperature indoor to drop. AC temperature setting has been adjusted at 11.12.2018 7:00 by Paul Kolp. Returned to working on the units after the temperature had been restored to normal threshold.

Name: ERIC SMITH
Date: 1/4/2019
Signature: 

Time zone: (UTC-05:00) Eastern Time (US & Canada)

Name: Robert Peters Hobart
Date: 1/3/2019
Signature: 

Name: Ibrahim Bitar
Date: 1/3/2019
Signature: 

