

Milling machine.pdf

File | E:\Milling%20machine.pdf

DIFFERENCES BETWEEN HORIZONTAL & VERTICAL MILLING MACHINES


SL. NO.	HORIZONTAL MILLING MACHINE	VERTICAL MILLING MACHINE
01	Spindle is horizontal & parallel to the worktable.	Spindle is vertical & perpendicular to the worktable.
02	Cutter cannot be moved up & down.	Cutter can be moved up & down.
03	Cutter is mounted on the arbor.	Cutter is directly mounted on the spindle.
04	Spindle cannot be tilted.	Spindle can be tilted for angular cutting.
05	Operations such as plain milling, gear cutting, form milling, straddle milling, gang milling etc., can be performed.	Operations such as slot milling, T-slot milling, angular milling, flat milling etc., can be performed and also drilling, boring and reaming can be carried out.

Type here to search

33°C Haze


SFD
A → -16
F → -6
ED → 10
=
C → 12
B → 0
BM) AF = R

Plain milling



- It is the operation of production of a flat surface parallel to the axis of rotation of the cutter.
- It is also called as slab milling.
- Plain milling cutters or slab milling cutters are used to perform this operation.

Face milling



- The face milling is the operation performed by the face milling cutter rotated about an axis at right angles to the work surface.
- The depth of cut is provided to the table.