Ex.No.-1.2-Design and Draft the given 2D Sketches in modelling software.

AIM:

To sketch the given drawing with dimensions using fusion 360 tool.

REQUIREMENTS:

1.Autodesk fusion 360


2.Windows 11

3.16 GB of RAM (integrated graphics recommend 2 GB or more)

4.2.5 Mbps or faster download; 500 Kbps or faster upload

PROCEDURE:


1. Open a new file and then select the sketch icon.
2. Select the plane for sketching.
3. Use sketching features (line, circle, arc, rectangle, polygon, etc.,) to draw the given sketch.
   Lines / Outer Boundaries: Length: 100 mm, Height: 50 mm]
   Circles / Holes: Diameter: 25 mm]
   Arcs / Fillets: Radius: 10 mm]




4. Use sketch modifying features (cut, trim, mirror, move, etc.,) to edit the sketch.




5. Use inspect feature to measure the dimensions of the sketch.




6. After finishing the sketch use the finish sketch option to finalize the sketch.




7. After finishing the sketch, switch to drawing mode to plot the sketch in ISO standard.






SKETCHS:


(R21.00)
(R21.00)
100
(Ø30.00)
(R20.00)
50
(Ø30.00)
(Ø30.00)
(R32.00)
-200
-150
-100
(Ø30.00)
(Ø32.00)
(R20.00)
(R20.00)
(Ø30.00)
(Ø30.00)
(R21.00)
(R21.00)
(80.00)
(80.00)
(20.00)
(50.00)
(50.00)

OUTPUT:



RESULT:

Thus the given sketch is drawn and drafted using the fusion 360 tool.