

Beam Loss in the First Segment of the FRIB Linac

R. Shane, S. Cogan, S. M. Lidia, T. Maruta

Facility for Rare Isotope Beams (FRIB), Michigan State University, East Lansing, MI 48824 USA


Loss Monitoring

Why monitor beam loss?

- · Assist with tuning
- · Minimize activation
- · Extend machine lifetime
- · Avoid beam damage

Challenges for FRIB


- · High beam intensity
- · Folded geometry
- Superconducting components



Loss Limits

- · High beam intensity means significant damage is possible quickly
- Slow loss limits set primarily by heat load (magnet quenching) and machine degradation, rather than activation of beamline parts

Beam loss (W/m)	Stop beam?	Response time		
P < 1	No	≥ 1 sec		
1 ≤ P < 10	Yes	1 sec (slow)		
P ≥ 10	Yes	< 15 µs (fast)		



Devices

Beam Measurements

- Halo monitor rings (HMR)
- Beam current monitors (BCM)

Radiation Measurements

- · Ionization chambers (IC)
- · Neutron detectors (ND)

Temperature Measurements

Resistive temperature devices (RTD)

Commissioned										
Commissioned		LS1	FS1	LS2	LS2	FS2	LS3	BDS		
		L31	131	low energy	high energy	F32	133	503		
3	Fast Loss < 35 ms	DBCM	DBCM	DBCM	DBCM	DBCM	DBCM	DBCM		
		HMR	BLM	BLM	BLM	BLM	BLM	BLM		
nts RTD)	w loss 00 ms	HMR/Temp	BLM	BLM	BLM	BLM	BLM	BLM		
		HMR/Temp		Temp	DBCM	DBCM	DBCM	DBCM		
	Slow 100									

Distribution

- · BCM distributed throughout accelerator
- HMR/Temp important for slow losses in LS1
 - · HMR in boxes between cryomodules, RTDs within cryomodules
- BLM important for slow losses in rest of linac
 - · ND primarily mounted to outside of cryomodules
 - IC mounted to magnet stands below beamline in folding segments (pairs)

Beam Current Monitor (BCM)
Halo Monitor Ring (HMR)

O Neutron Detectors, Ion Chambers

