

Accessory Protocol Interface Module (APIM) Reset



NOTE: An **APIM** Reset consists of a battery disconnect and a SYNC® system Master Reset. It may **not** be necessary to perform a Master Reset after disconnecting the battery if the concern is resolved.

NOTE: This procedure clears all **CMDTCs**. The **DTCs** must be recorded now if other non-SYNC® diagnoses are to be performed after this procedure.

1. Remove any devices connected to the **USB** port(s), audio input jack/socket (if equipped), Secure Digital (SD) slot (if equipped), or RCA jacks (if equipped).
2. Disconnect the negative battery cable for 1 minute, then reconnect it. Refer to Section 414-01.
3. **NOTE:** Performing a Master Reset returns all preference settings to the factory defaults, erases the phone book and call histories, and deletes any Bluetooth devices paired with the SYNC® system. For vehicles with navigation, the customer's saved destinations (home, favorites, and previous) are erased. For vehicles with a Telematics Control Unit (TCU), any devices paired with the MyFord® Mobile or MyLincoln Mobile™ phone application will be deleted.

Perform a Master Reset. If necessary, refer to “Master Reset” in the Owner's Literature.

4. Verify system function using the Multi-Media Interface Tester 105-00120 to test the audio output for the **USB** port(s), audio input jack/socket (if equipped), and Bluetooth. If equipped, test the audio output for the RCA jacks using RCA Adapter 105-00121.
5. **NOTE:** If the concern remains after completing the **APIM** Reset procedure, advise the customer to power their device off and back on for a simple reboot. In some cases, if possible, the device's battery may also need to be removed and re-installed to complete a reboot. Delete SYNC® from the device's Bluetooth menu prior to re-pairing the phone to the SYNC® system. If necessary, the customer can also perform a Master Clear, Master Reset, or Factory Data Reset on their device following the manufacturer's instructions in the device's owner's manual and/or website. Customer devices may affect the operation of SYNC® and this should be understood to prevent unnecessary diagnosis or repairs to the system.

If a concern is still present, return to the Symptom Charts.