




https://en.trxcom.net/Products_details/386.html
Here is says there are NO MAGNETICS inside TRJE101AGNL

What's wrong

- 1) Poorly draun Schematic.
- 2) TXD+/TXD- on SFP connector side must be swapped
- 3) Ethernet connector has no embedded magnetics. Need another connector

sfp

01.05.2026 12:57

Sheet: 1/1