

CEDAR HOLLOW PROPERTY INSPECTION SERVICES

Comprehensive Property Condition Assessment | Doc ID: DOC-INS-001640

Subject Property:	18 Larkspur Ln	Inspection Date:	February 15, 2025
Client:	Servicing Audit Dept	Inspector:	Robert Jenkins, CMI #9842
Weather:	Clear, 68°F	Property Type:	Single Family Residence
Foundation:	Poured Concrete (Sound)	Roof Condition:	Architectural Shingle (End of life)

1. Structural & Building Envelope

Exterior siding, masonry, windows, and door seals were inspected. No structural settling observed. Roof shingles show granule loss and curling across the rear slope, with an active leak at the rear valley. Estimated remaining useful life 0-2 years; full roof replacement recommended.

2. Mechanical, Electrical & Plumbing

Electrical service panel 200A main disconnect; copper branch wiring; GFCI receptacles functional. HVAC system operational on cooling and heating cycles. Water pressure tested at 55 PSI.

[End of Page 1 — Continued on Page 2]

3. Interior Living Areas & Additions / Modifications

Special Finding — Water Damage: Moisture readings of 28% at the primary bedroom ceiling and the exterior wall below the rear roof valley. Drywall staining and soft spots over approx. 60 sq ft. Repair of the roof and interior damage is required. Overall condition is downgraded from C3 to C4 (below average) until repairs are completed.

4. Inspector Summary & Rating

System	Rating	Comments
Roofing	Poor	Active leak at rear valley
HVAC	Good	Serviced fall 2024
Plumbing	Satisfactory	No active leaks detected
Overall Condition	C4 (Below Average)	Deferred maintenance: roof and water damage