

Steel & Smelting

- › Steel factories are **very dangerous** because:
 - Workers handle **very hot melted metal**
 - Big machines like **cranes move heavy loads**
 - There are **gases and furnaces** that can fail
- › Common accidents:
 - Molten metal spilling or exploding
 - Cranes dropping heavy materials
 - Furnace or gas leaks
- › Real examples:
 - Accidents like **Visakhapatnam steel plant** and **Tata Steel** incidents
- › In **Gujarat**, many factory deaths happen because:
 - There are lots of **heavy industries + chemical factories**
 - These environments are **high-risk**