

INSPECTION REPORT

Finding: bolt M8 torque out of spec (18 Nm measured, 25 Nm required)

Recommended action: retorque and re-inspect