Inspection summary

Property	9 Hollis Way · single-family, 2 stories, built 1979, about 1,960 sq ft
Client	Ruth and David Okafor (buyers)
Inspected	Friday, October 9, 2026 · 1:00 pm to 4:15 pm · weather clear, 61°F
Inspector	Bay Area Inspections · license on file · sample report

This report records the condition of the visible, accessible parts of the home on the day of inspection. Items are rated Satisfactory, Monitor or Repair. Repair items are listed with a recommendation; the inspector does not estimate costs.

Summary of findings

- Repair · Water heater near end of service life (page 12)
- Satisfactory · Garage door and opener (page 7)
- Satisfactory · Roof covering (page 3)
- Satisfactory · Electrical panel (page 9)

Roof and gutters

Roof covering · Satisfactory. Architectural asphalt shingles, about 6 years old. No missing or lifted shingles observed. Flashing at the chimney is sealed.

Gutters and downspouts · Satisfactory. Gutters are clear. Downspouts discharge at least 4 feet from the foundation.

Exterior: decks, balconies and railings

Rear deck structure · Satisfactory. Pressure-treated framing on concrete footings. Ledger is flashed and bolted to the house. No soft or decayed boards found.

Front porch steps · Satisfactory. Handrail is secure. Riser heights are even.

Exterior: siding, windows and doors

Siding · Satisfactory. Fiber-cement lap siding in good condition. Caulk at window trim is intact.

Windows · Satisfactory. Double-pane vinyl windows open and lock. No failed seals observed.

Exterior doors · Satisfactory. Weatherstripping is intact at the front and rear doors.

Foundation and grading

Foundation walls · Monitor. Minor efflorescence on the north foundation wall, about 3 feet wide. No active moisture at the time of inspection. Keep gutters clear and recheck after heavy rain.

Grading · Satisfactory. Soil slopes away from the house on all sides.

Garage

Garage door and opener · Satisfactory. Auto-reverse works when the door meets resistance. Photo-eyes are mounted at the correct height.

Fire separation door · Satisfactory. Solid-core door between the garage and the house closes and latches.

Attic and insulation

Attic access · Satisfactory. Pull-down stair in the hall closet. Hardware is secure.

Insulation · Satisfactory. Blown-in fiberglass, about 12 inches deep. Bathroom fans vent to the exterior.

Electrical: service and panel

Service panel · Satisfactory. 200 amp panel in the garage. Breakers are labeled. No double-tapped breakers.

Electrical: branch circuits and outlets

Interior outlets · Satisfactory. A sample of outlets in each room tested correctly for polarity and ground.

Light fixtures · Satisfactory. Fixtures and switches operated normally.

Heating: overview

Heating system · Satisfactory. Gas forced-air furnace with ducted supply to every room. Thermostat responded to calls for heat.

Plumbing · Water heater

Gas water heater, 50 gallons, located in the garage. Strapping present.

Water heater is 14 years old and near the end of its service life. Recommend replacement.

No active leaks were observed at the time of inspection.

Heating: furnace

Furnace · Satisfactory. Gas furnace, 80,000 BTU, about 9 years old. Service sticker shows it was serviced in March 2026. Filter is clean.

Venting · Satisfactory. Flue connections are sealed and slope up toward the chimney.

Cooling

Air conditioner · Satisfactory. Split system, 3 tons, about 9 years old. Temperature drop across the coil measured 18°F.

Plumbing: fixtures

Faucets · Satisfactory. All faucets run hot and cold on the correct sides.

Plumbing: supply and drains

Supply piping · Satisfactory. Copper supply lines. Water pressure measured 62 psi at the hose bib.

Drains · Satisfactory. All fixtures drained without backup.

Kitchen

Appliances · Satisfactory. Range, dishwasher and disposal operated normally.

Sink and counters · Satisfactory. Sink is sealed at the counter. No leaks under the sink.

Laundry

Dryer vent · Satisfactory. Rigid metal duct vents to the exterior. Lint screen is clean.

Bathrooms: primary

Shower and tub · Satisfactory. Grout and caulk are intact. Drain flows freely.

Ventilation · Satisfactory. Exhaust fan operates and vents to the exterior.

Bathrooms: hall and half bath

Fixtures · Satisfactory. Toilets are secure to the floor. Sinks drain normally.

Interior: floors, walls and ceilings

Floors · Satisfactory. Hardwood on the main floor and carpet upstairs show normal wear.

Walls and ceilings · Satisfactory. No stains or cracks that suggest moisture or movement.

Interior: doors and stairs

Stairs · Satisfactory. Handrail is continuous and secure. Balusters are spaced less than 4 inches apart.

Fireplace and chimney

Fireplace · Satisfactory. Wood-burning fireplace with a working damper. Recommend a chimney sweep before first use.

Smoke and carbon monoxide alarms

Alarms · Satisfactory. Smoke alarms present in each bedroom and hallway. Carbon monoxide alarm present on each floor.

Crawlspace

Vapor barrier · Satisfactory. Plastic vapor barrier covers the soil. No standing water.

Maintenance notes

- Replace the furnace filter every three months.
- Clean gutters each fall and spring.
- Test smoke and carbon monoxide alarms monthly.
- Recaulk tubs and showers when gaps appear.

Standards of practice and limitations

This inspection follows the standards of practice of the state home inspector association. It is a visual, non-invasive inspection of readily accessible systems and components on the day of inspection.

The inspector does not move furniture, open walls or predict future conditions. This report is not a warranty or a guarantee.

Inspector certification

I certify that I personally inspected the property and that this report reflects my findings on the date of inspection.

_____

Inspector signature on file

Bay Area Inspections · sample report · Friday, October 9, 2026