CTAS344 - CBS Legend Data&Voice2 2nd Floor (Rev#5) -SO#59289 **Telephone** - 1CAT5e Cables to nearest MDF, rminated on Rack Mounted Patch Panel Data 1CAT5e Cables to nearest MDF, terminated on Rack Mounted Patch Panels Digital Signage - 1CAT5e Cables to nearest MDF, erminated on Rack Mounted Patch Panels CI/FAX - 1CAT5e Cables to nearest MDF, terminated on BIX HIGH BAY PALLET STORAGE AREA Callbox Antenna - 1 CAT5e cabled to nearest MDF, Terminated on Rack Mounted Patch Panels Gemsys - 1CAT5e Cables to nearest MDF, terminated on Rack Mounted Patch Panel CATV - 1 RG-6 cabled to Main MDF Remote Cabinet - Alternate MDF's - cabled as 1 - All cable drops must have a 20' service loop coiled at ceiling before dropped 2 - All cables in floor conduit must have a 20' service loop coiled under the counter 3 - All cables must have a 20' service loop at MDF End, coiled in ceiling. Tech Lunch Room (See notes on Retail Floor Plans) 1 Telephone - 1 spare Parts Pass Thru AI not TC