## Table 6 to Subpart UUUUU of Part 63 - Establishing PM CPMS Operating Limits

Link to an amendment published at 83 FR 56727, Nov. 14, 2018.

As stated in § 63.10007, you must comply with the following requirements for establishing operating limits:

If you have an applicable emission limit for	And you choose to establish PM CPMS operating limits, you must	And	Using	According to the following procedures
mercury HAP metals, individual non-mercury HAP metals, total HAP metals, or individual	Install, certify, maintain, and operate a PM CPMS for monitoring emissions discharged to the atmosphere according to § 63.10010(h)(1)	PM CPMS output signal	PM CPMS and the PM or HAP metals performance	1. Collect PM CPMS output data during the entire period of the performance tests. 2. Record the average hourly PM CPMS output for each test run in the performance test. 3. Determine the PM CPMS operating limit in accordance with the requirements of § 63.10023(b)(2) from data obtained during the performance test demonstrating compliance with the filterable PM or HAP metals emissions limitations.

[81 FR 20201, Apr. 6, 2016]