

| Vehicle Exterior |        |                            |
|------------------|--------|----------------------------|
| Item             | Result | Notes                      |
| Lights           | OK     | Replaced 1x low beam globe |
| Wipers           | OK     |                            |
| Seatbelts        | OK     |                            |
| Doors            | OK     |                            |
| Windows          | OK     |                            |
| AC / Heater      | OK     |                            |
| DTC Scan         | OK     |                            |

| Under Bonnet           |         |                                                              |
|------------------------|---------|--------------------------------------------------------------|
| Item                   | Result  | Notes                                                        |
| Drive Belts            | OK      |                                                              |
| Vacuum & Coolant Hoses | CAUTION | coolant stain evident at outlet block. Recheck next service. |
| Battery                | OK      | Rated 720 CCA / Tested 690 CCA                               |
| Coolant                | OK      | Glycol 27%                                                   |
| Brake Fluid            | OK      |                                                              |
| Power Steering Fluid   | OK      |                                                              |

| Brakes & Tyres                                |             |          |        |       |
|-----------------------------------------------|-------------|----------|--------|-------|
| Position                                      | Tread Depth | Pressure | Brakes | Notes |
| Left Front                                    | 3.5mm       | 38 PSI   | 5mm    |       |
| Right Front                                   | 3.5mm       | 38 PSI   | 5mm    |       |
| Left Rear                                     | 0.5mm       | 38 PSI   | 7mm    |       |
| Right Rear                                    | 0.5mm       | 38 PSI   | 7mm    |       |
| Spare                                         | —           | 50 PSI   | —      |       |
| Replace rear tyres. Recommend wheel alignment |             |          |        |       |

| Chassis & Body                          |          |                               |
|-----------------------------------------|----------|-------------------------------|
| Component                               | Status   | Notes                         |
| Transmission                            | OK       |                               |
| Differentials                           | ADVISORY | Diff bushes starting to split |
| Tailshaft / Prop Shaft / Centre Bearing | ADVISORY | Centre bearing split          |
|                                         |          |                               |

|                        |          |                                                       |
|------------------------|----------|-------------------------------------------------------|
| Driveshafts & CV Boots | OK       |                                                       |
| Suspension – Front     | ADVISORY | Front lower inner control arm bushes wearing          |
| Suspension – Rear      | ADVISORY | RHR upper outer control arm bushes has excessive play |

- Vehicle inspection

# TAX INVOICE

To: The Car Guys

From: Jamie Watson · ABN 67 443 578 471

| DESCRIPTION                               | HRS | RATE       | AMOUNT (ex GST) |
|-------------------------------------------|-----|------------|-----------------|
| Inspection, quick checks, wash down, wsm. | 4.5 | \$50.00/hr | \$225.00        |
| Subtotal                                  |     |            | \$225.00        |
| GST (10%)                                 |     |            | \$22.50         |
| TOTAL (inc. GST)                          |     |            | \$247.50        |

Bank: HSBC Account: Jamie Watson BSB: 342 201 Acct: 185014087

Jamie Watson · Contract Mechanic for The Car Guys · ABN 67 443 578 471 · Generated 10/05/2026  
Inspection based on visible components only. Parts requiring disassembly are not inspected unless otherwise stated.