initializing all pin variables and interrupts



Redrawing lcd method



ISR to convert analog value to temperature



Mesuring data and turning on/off pumps



Checking switches