

## STANDARD OPERATING PROCEDURE FOR LASER CUTTING

- Recommended PPEs to be used.
- Select the programme from the computer
- Load the raw material with the help of EOT crane on the table and take the table in to the cutting chamber and align the raw material at right angle.
- Check the grade and thickness of the material.
- Select the material specification (M.S/S.S and thickness) for cutting as per programme.
- Execute the calibration for the loaded material and reset.
- Ensure the all indicators displayed on the SLTL window.
- Select the correct programme for cutting as per drawing.
- Switch on the fume exhaust
- Do not leave the laser machine while running.