

STANDARD OPERATING PROCEDURE FOR PAINTING

- Use required PPE's.
- All fabricated and finished components are shifted to paint area.
- As per customer requirement the specified painting is coated.
- Ensure surface preparation by blasting/ cleaning with ferro guard
- Ensure air pressure is set, the painting hose arrangement and paint guns are fitted for painting
- Ensure the air pressure is maintained within the required bar to get uniform surface
- Temperature shall not be below 10⁰c and above 50⁰ c
- Humidity shall not be more than 85%
- As per drawing requirement paint thickness should be obtained.
- After painting the drying time is set according to paint manufacture guidelines
- The final component is packed as per customer requirement and send it to dispatch.