

STANDARD OPERATING PROCEDURE (SOP)

for MAINTENANCE(MED) SPARES PREPARATION

- Use the Safety Helmet, Safety Shoe and Red Cotton Hand Gloves.
- Engage the trained/experience people.
- Work under supervisor/shift in-charge/HOD.
- Identify the repair and plan for maintenance work, spares to use the proper tools and equipment's and check the condition of tools, spares and work area.
- Use the equipment for shifting of require materials for safe handling.
- While bearing removing use goggles
- Clean and inspect the area before starting the hot work if require i.e. gas cutting, grinding, welding.
- Keep a constant watch on the working area.
- Don't use the mobile phones during the work activity.
- Maintain safe distance from the spares to avoid physical harm.
- Clean the area, machine, tools after completing of job.