

STANDARD OPERATING PROCEDURE (SOP)

for TURNING OPERATION

- Use the Safety Helmet, Safety Shoe, Safety Goggle, and Red Cotton Gloves & Apron.
- Only trained/authorized operator is allowed to operate the machine.
- Work under supervisor/shift in-charge/HOD.
- Inspect the machine and check that the lathe is clean and safety guards are in place.
- Turn the chuck by hand to confirm the work piece will not hit the chuck or tailstock.
- Never leave the chuck key in the chuck, remove it and secure it in its holding place.
- Carefully select the correct spindle speed using the feed chart for the specific material being cut.
- Securely mount the cutting tool in the tool post and set its height.
- Use cutting fluid as needed to prevent the work piece from heating up.
- Stop the machine to measure the work piece and adjust the cut depth as required.
- Keep a constant watch on the working area.
- When work piece is ready press the stop button.
- Separate the finished products.
- Don't use the mobile phones during the work activity.
- Maintain safe distance from the machine in running condition and don't touch by hand.
- Clean the area, machine, tools after completing of job.

- Use this  type of tool for removal scrap from the turning location
don't use bare hands/ Gloved hands to be removed.