## Machine Log Summary #7497630

Date: 2023-11-02

Unit Code	Equipment	Service Type	Technician	Downtime	Area	Notes
MC-238	Plasma Cutter	Inspection	Peter Schmidt	2.5	Plant 1C	Tightened loose bolts.
MC-218	CNC Milling Machine	Corrective	Peter Schmidt	3.5	Plant 2B	Worn gasket replaced.
MC-235	Assembly Robot	Preventive	Jan Kowalski	2.5	Plant 2B	Replaced fuse (5A).
MC-255	Paint Booth	Inspection	Jan Kowalski	2.4	Plant 3A	
MC-217	Hydraulic Press	Corrective	Carlos Garcia	3.6	Plant 3A	Sensor recalibrated.
MC-273	Packaging Line	Corrective	Peter Schmidt	2.5	Plant 3A	
MC-226	Lathe	Preventive	Carlos Garcia	1.7	Plant 1C	Worn gasket replaced.

Ensure that each service entry has the required approvals. Service summaries have been forwarded to the engineering team. All maintenance durations are recorded for performance metrics. Check remaining life-cycles of key components from this report.

Lubrication Checked	N/A
Calibration Verified	Yes
Emergency Stop Tested	Yes

Signed off:	Performed by: