

Page 1: General Bearing Overview

Standard operating procedures for industrial machine bearings. Regular inspection prevents catastrophic motor and axle failure. Check for unusual noise, heat accumulation, and excessive vibration during daily rounds.

Page 2: Bearing Wear Diagnosis & Action

Defect Type: Bearing Wear and Fatigue Scoring.

Symptom: Circular scoring marks, metallic noise, or overheating in rotational assembly.

Action Required: Immediately isolate machine power. Remove bearing housing and replace worn ball bearings with part #BRG-9920. Apply high-temperature synthetic grease prior to restarting operations. Priority: High.