Weld inspection report.

A crack was found along the support seam.

Linear fracture propagation of 40 mm measured.

Fatigue cracking is suspected near the toe of the weld..