SCANNED REPORT

A crack was found on the welded support seam.

Fracture is propagating along the weld.

Halt loads.