
SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 1 of 10

RISK RANK 3

PURPOSE:

This procedure provides step-by-step guidance for implementing the Personal Protective Equipment Procedure, ensuring all field workers inspect, maintain and understand the out of service standards for their Personal Protective Equipment.

HAZARDS

TYPE	HAZARD	TYPE	HAZARD	TYPE	HAZARD
Physical	Slips, Trips, Falls	Chemical	H2S	Property	Equipment
	Mobile Equipment		Fuel		Third Party Property
	Pinch Points		Cement	Productivity	Down time
	Night/Low lighting	Biological	Wildlife		Inefficient
	Noise 82<		Insect bites	Legal	Suspension
	Energy		Influenza		Out of Service
	Environment	Social	Harassment		Fine
	Other Workers		Violence		Regulations
	Work Alone				

REFERENCES

PPE	Prevention	References
Fire Retardant Coveralls	Hazard Assessment	Alberta OH&S
CSA Z96 Hi-Vis Coveralls	Safety Meeting	Federal OH&S
Steel Toed Boots	Inspection	Task List
Safety Glasses	Maintenance	Standard Operating Procedure
Gloves	FLHA	
Hard Hat	Ear Plugs or Muffs	
Hearing Protection	Training	

You are required to perform at a Job, there are some items that need to be considered:	
Has the Job or Task been Risk Assessed	Is There additional personal
Evaluate the workplace background and conditions, active work zones, Low light levels	Do you have other workers accompanying you; Supervisors, Trainees or 3 rd Party
How far away is the Work Site, Travel Time, ERP Response Time;	Is there mobile equipment in area, loaders, track hoes, casing trucks, vac or water trucks.
Do you have a High Vis Safety Vest for additional personal; Learn More	
Do you have a Lock Out Tag Out plan in place;	
Do you have a Spotter for tight places;	
Have you implemented Hi Visibility around moving equipment?	

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 2 of 10

RISK RANK 3

Silverpoint Energy Services Inc Management provides the following procedures for each Personal Protective Equipment (PPE) item listed in the Silverpoint Energy Services Inc. policy. These procedures outline proper inspection, use, maintenance, marking PPE out of service, and replacement.

1. Hard Hats

Inspection:

- Before Each Use: Inspect for cracks, dents, deformities, or any signs of impact. Check the suspension system for fraying or wear.
- After Each Use: Store in a dry, cool place away from direct sunlight to avoid material degradation.

Use:

- Wear hard hats in designated areas where head injury risks are present (e.g., from falling objects or head strikes).
- Ensure the hard hat is properly fitted, with the suspension system adjusted for a secure and comfortable fit.

Maintenance:

- Clean the shell and suspension system with mild soap and water regularly. Avoid solvents and harsh chemicals.

Marking Out-of-Service and Replacement:

- If cracks, impact marks, or damaged suspension are identified, place the hard hat out of service immediately by marking it with an "Out of Service" tag.
- Replace the hard hat before starting or continuing work. Report the defect to your supervisor for proper disposal and request a new one.

2. Safety Glasses

Inspection:

Before Each Use:

- Check for scratches, cracks, or loose frames. Ensure lenses are clean and free of smudges.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 3 of 10

RISK RANK 3

Use:

- Wear safety glasses in environments with risks of flying debris, particles, or exposure to hazardous light.

Maintenance:

- Clean lenses with a soft cloth and approved lens cleaner. Ensure no buildup of dirt that could reduce visibility or effectiveness.

Marking Out-of-Service and Replacement:

- If lenses are scratched or cracked, immediately place them out of service by attaching an "Out of Service" tag.
- Replace safety glasses before proceeding with any tasks. Report the defective glasses for replacement.

3. Face Shields

Inspection:

- Before Each Use: Inspect the shield for cracks, scratches, or any structural damage. Check straps and headbands for secure attachment.

Use:

- Use a face shield in addition to safety glasses when facing high-impact risks or potential chemical exposure.

Maintenance:

- Clean the face shield with a soft cloth and an approved cleaner. Ensure straps are free from wear and tear.

Marking Out-of-Service and Replacement:

- If the face shield becomes cracked or scratched, mark it as "Out of Service" and remove it from the workspace.
- Replace the shield before work resumes. Report the defect to a supervisor.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 4 of 10

RISK RANK 3

4. Hearing Protection

Inspection:

- Before Each Use: Inspect earmuffs for proper fit, check earplugs for dirt or damage. Replace foam inserts when necessary.

Use:

- Wear ear protection when noise levels exceed 85 dB.

Maintenance:

- Clean reusable earplugs or earmuffs regularly with soap and water. Replace foam earplugs after each use if they are single-use.

Marking Out-of-Service and Replacement:

- If the protection is damaged or does not properly seal the ear, place it out of service immediately.
- Replace hearing protection before continuing work and report any defective units to the supervisor.

5. Gloves

Inspection:

- Before Each Use: Inspect for tears, holes, or signs of wear. Ensure the glove material matches the task's hazard level.

Use:

- Wear gloves appropriate for handling sharp objects, chemicals, or high-temperature materials.

Maintenance:

- Clean gloves as per manufacturer instructions. Store gloves in a dry, cool area when not in use.

Marking Out-of-Service and Replacement:

- Mark gloves as out of service if they are torn, worn, or compromised in any way. Attach a tag and remove them from circulation.
- Replace gloves with new ones immediately to ensure safety during work.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 5 of 10

RISK RANK 3

6. Steel-Toed Boots

Inspection:

- Before Each Use: Inspect soles for wear, steel toes for exposure, and the upper material for tears or damage.

Use:

- Wear steel-toed boots in work environments with risks of foot injuries due to heavy objects or hazardous materials.

Maintenance:

- Clean regularly and treat leather to maintain durability and water resistance. Dry boots after exposure to moisture.

Marking Out-of-Service and Replacement:

- If the steel toe is exposed, the sole is worn down, or the boot is torn, mark it out of service immediately and tag it.
- Replace boots before resuming any work.

7. Coveralls Fire-Retardant

Inspection:

- Before Each Use: Check for rips, tears, and or compromised fire-retardant properties.

Use:

- Wear coveralls in fire, explosive risk areas.

Maintenance:

- Launder according to manufacturer instructions. Use industrial laundering services to maintain fire-retardant properties. Avoid bleach and fabric softeners.

Marking Out-of-Service and Replacement:

- Remove coveralls from service if there are rips, tears, if fire retardancy. Attach an "Out of Service" tag.
- Replace coveralls before work continues. Ensure proper disposal of damaged coveralls.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 6 of 10

RISK RANK 3

7.1. Coveralls High-Visibility

Inspection:

- Before Each Use: Check for rips, tears, or compromised material. Inspect reflective strips for wear.

Use:

- Wear coveralls where high visibility is needed, especially in low-light and or high-traffic areas.

Maintenance:

- Launder according to manufacturer instructions. Use industrial laundering services to maintain high visibility reflective properties. Avoid bleach and fabric softeners.

Marking Out-of-Service and Replacement:

- Remove coveralls from service if there are rips, tears in the material or high visibility stripes is compromised. Attach an "Out of Service" tag.
- Replace coveralls before work continues. Ensure proper disposal of damaged coveralls.

7.2 Vests High-Visibility

Inspection:

- Before Each Use: Check for rips, tears, or compromised material. Inspect reflective strips for wear.

Use:

- Wear Vests where high visibility is needed, especially in low-light and or traffic areas and when there are two or more Silverpoint Workers.

Maintenance:

- Launder according to manufacturer instructions. Use industrial laundering services to maintain high visibility reflective properties. Avoid bleach and fabric softeners.

Marking Out-of-Service and Replacement:

- Remove Vests from service if there are rips, tears in the material or high visibility stripes is compromised. Attach an "Out of Service" tag.
- Replace coveralls before work continues. Ensure proper disposal of damaged coveralls.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 7 of 10

RISK RANK 3

8. Body Harness

Inspection:

- Before Each Use: Inspect for fraying, cuts, and wear on straps and buckles. Ensure secure connections and that all parts are functional.

Use:

- Use when working at heights exceeding 3 meters or in areas where fall protection is required. Ensure proper fit and secure attachment to anchor points.

Maintenance:

- Clean harness with mild soap and water. Store in a dry, cool place. Avoid contact with sharp objects or chemicals.

Marking Out-of-Service and Replacement:

- After a fall or if damage is identified, immediately tag the harness as "Out of Service" and remove it.
- Replace the harness with a new one before continuing any work at heights.

9. Life Line

Use:

- Use a lifeline when working at heights or in confined spaces as part of a fall arrest system.

Inspection:

- Before Each Use: Inspect the lifeline for cuts, abrasions, and wear. Ensure the line and its connectors are intact and secure.

Maintenance:

- Clean and store lifelines in a dry, cool area away from sharp objects or chemicals. Ensure the line remains tangle-free.

Marking Out-of-Service and Replacement:

- Tag the lifeline "Out of Service" if any damage or wear is found. Immediately remove from service.
- Replace the lifeline before work continues.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 8 of 10

RISK RANK 3

10. Flotation Jacket

Use:

- Required when working near or over water, on ice, or in environments where there is a risk of immersion. A flotation jacket provides buoyancy and thermal protection.

Inspection:

- Check for tears, punctures, or other signs of damage to the outer material and flotation components before each use. Ensure zippers, buckles, and reflective strips are functional.

Maintenance:

- Store in a dry, well-ventilated area when not in use. Avoid prolonged exposure to direct sunlight, chemicals, or excessive moisture, as these can degrade the jacket's performance.

Out-of-Service:

- Remove from service if the jacket shows any signs of damage, including compromised flotation material, non-functioning closures, or significant wear.

Replacement:

- Replace the flotation jacket immediately if it is damaged or fails inspection, before resuming any work near or over water.

11. H₂S Personal Monitors

NOTE: Silverpoint Energy Services does not supply Personal H₂S Monitors. In the event that the worker contractor does need a H₂S Monitor arrangements will be made for the worker to obtain a Personal H₂S Monitor. Ask you Supervisor for details.

Inspection:

- Before Each Use: Ensure the monitor is calibrated, has a full battery, and is free of physical damage. Test its alarm function.

Use:

- Wear the monitor in areas where hydrogen sulfide (H₂S) is a potential hazard. Ensure it is turned on and functioning properly throughout the task.

Maintenance:

- Calibrate regularly according to manufacturer guidelines. Store in a cool, dry place when not in use.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.

SILVERPOINT VACUUM TRUCK SERVICES
STANDARD OPERATING PROCEDURE
Personal Protective Equipment Procedure

Proc. No: Vac 4.00.01
Page 9 of 10

RISK RANK 3

Marking Out-of-Service and Replacement:

- If calibration fails or the monitor malfunctions, tag it as "Out of Service" and remove it from use immediately.
- Replace or recalibrate the monitor before entering any H₂S risk areas.

11. Responsibilities

Employee Responsibilities:

- Conduct inspections before every use.
- Place PPE out of service if it is damaged or no longer effective.
- Notify a supervisor and ensure immediate replacement of defective PPE.

Supervisor Responsibilities:

- Ensure employees adhere to this procedure.
- Conduct regular PPE inspections.
- Provide replacement PPE promptly when needed.

12. Review and Revision

This PPE policy will be reviewed annually or whenever there is a significant change in operations, regulations, or safety standards. The policy will be updated as necessary to ensure continued compliance with Canadian Federal OH&S regulations and industry best practices.

References:

This policy is designed in accordance with the Canadian Federal Occupational Health and Safety (OH&S) regulations and industry best practices to prevent workplace injuries and accidents.

- Canadian Federal Occupational Health and Safety Code
 - CSA Z94.1-15 (Industrial Protective Headwear)
 - CSA Z195-14 (Protective Footwear)
 - CSA Z94.3-15 (Eye and Face Protectors)
 - CSA Z462 (Workplace Electrical Safety)
 - CSA Z94.4-18 (Hearing Protection)
 - CSA Z259.10 (Fall Protection)
 - Part XII (12.10) (Flotation Jacket)

Any questions contact your Supervisor.

Select PPE items used by Silverpoint Energy Services Inc. workers and contractors require additional specific inspection, maintenance, and out-of-service criteria and standards. For PPE requiring further instruction and guidance, Silverpoint Management will provide additional instructions on safe use, inspection, maintenance, and out-of-service requirements.