

Brumley South, Inc.

Part #346888

Index #4



GSI Scanner Mirror Assembly
Now Supported
Tencor Surfscan 6100, 6200, 6400 Series

Scanner Part Numbers: 346888, 289167, 162930, 204587, 3005502, 3005507-Others

Tencor Surfscan 6000 Series

THE PROBLEM:

"Hard Down" GSI Mirror Scanner is
BAD

OEM no longer supports and has ZERO STOCK.

THE SOLUTION:

Brumley South now has in STOCK Mirror Scanner assemblies.

Same Day Shipping

DETAILS:

Refurbished back to OEM condition.
Tencor Tested in Surfscan .
This should be installed by Tech that has Tencor Optical Alignment
Training.

1 Year Warranty





PRICING:
Exchange price = \$19,500.00
Typically in stock
Repair price = \$15,500.00
8 week lead time

Contact Information

Brumley South, Inc 422 N. Broad Street Mooresville, NC 28115 Ph (704) 664-9251

Purchasing: Cheryl Gregory Ext. 204 Email: orders@brumleysouth.com www.brumleysouth.com

Date: 8/25