

# DEPARTMENT OF ELECTRONICS AND TELECOMMUNICATION ENGINEERING

# BM 3121 MEDICAL IMAGING

## Nuclear Medicine Imaging Quality Assurance

Name: U.G.C. Jayasankha

Index Number: 170259P

## Contents

1	Intr	oducti	ion to Nuclear Medicine Imaging		2		
2	Quality Assurance Aspects of Nuclear Medicine Imaging						
3	Pha	ntoms	for Nuclear Medicine Imaging QA		4		
4	Qua	ality A	assurance Methods and Protocols of Nuclear Me	dicir	ıe		
	Ima	ging			6		
	4.1	Qualit	y assurance methods for Hardware		. 6		
		4.1.1	Test for Center of Rotation		. 6		
		4.1.2	Camera Calibration		. 6		
	4.2	Qualit	y assurance methods for Imaging system		. 7		
		4.2.1	Flood field uniformity		. 7		
		4.2.2	Energy Resolution		. 8		
		4.2.3	Shield Leakage Test		. 8		
		4.2.4	Counter rate performance Test				
	4.3	Qualit	y assurance methods for Image quality		. 9		
		4.3.1	SNR				
		4.3.2	CNR				
		4.3.3	Image Uniformity test		. 9		
		4.3.4	Spatial Resolution				
		4.3.5	Artefacts		. 11		
	4.4	Qualit	y assurance methods for display print quality				
		4.4.1	Display Print quality control				
		4.4.2	Display quality control				
	4.5	Qualit	sy assurance methods for Safety measures				
		4.5.1	Background radiation check				
5	Recent advancements in Nuclear Medicine Imaging Quality Assur-						
	anc	е			13		
6	Ref	erence			14		

## 1 Introduction to Nuclear Medicine Imaging

Nuclear Medicine Imaging is a imaging modality which contrasts with other imaging modalities because other modalities focus on providing anatomical details of organs while Nuclear Medicine Imaging focuses on providing details of physiological functions. For that isotopes which emits radiation are injected to the body.

Nuclear Medicine Imaging is mainly divided into two.

- 1. Single Photon Imaging (SPECT) Single Gamma rays emitted by radionuclide are detected
- 2. Positron Emission Tomography (PET) Two annihilation photos emitted from positron emitting radionuclide are detected



Figure 1: PET Scanner

Following figure shows the basic structure of Nuclear Medicine Imaging Scanners.




Figure 2: Basic structure of SPECT/PET Scanner

## 2 Quality Assurance Aspects of Nuclear Medicine Imaging

In any imaging modality quality assurance is important to ensure the safety of all the people who engages with the scan and to achieve best quality image to diagnose the patient. In Nuclear Medicine Imaging quality assurance should be taken into consideration strictly because of the involvement of radiation and radioactive substances. There is a trade-off between the patients' safety and the quality of the image. Quality assurance methods are required here because of that. There are several topics to be addressed in Nuclear Medicine Imaging quality assurance.

- How to get high quality images
- How to keep the consistency of the image quality
- How to ensure the patient safety by using least amount of exposure to radiation
- How to minimize the cost
- How to increase the efficiency
- How to identify errors and repair




Figure 3: Quality Assurance & QC cycle

## 3 Phantoms for Nuclear Medicine Imaging QA

Phantoms are used for quality assurance purposes to measure relevant parameters. In Nuclear Medicine imaging, phantoms are different than others because radioactive substances should be inserted into these. There are several kinds of phantoms used for different quality assurance tests and methods.

- i. Tomographic Uniformity Phantom Cylindrical Structure with uniform concentration of radioactive substance
- ii. Tomographic point source Spherical structure with point source of radiation at the center
- iii. Resolution Phantoms Point radiation sources are spread all over the structure with uniform attenuation
- iv. Total performance phantom Phantoms with known shapes inside
- v. A liquid filled flood source



Figure 4: Phantoms and Calibration equipment for PET-CT



Figure 5: Cylindrical phantom

## 4 Quality Assurance Methods and Protocols of Nuclear Medicine Imaging

This section describes the main quality assurance methods and protocols used in diagnostic ultrasound.

#### 4.1 Quality assurance methods for Hardware

#### 4.1.1 Test for Center of Rotation

Test for center of rotation is to ensure that the physical center of the system coincides with the center computed center of the system using the cameras and collimators. Procedure of this test is to use all the combinations of cameras and collimators which




Figure 6: Center of rotation - SPECT

are used for diagnostic procedures. Corrective measures should be taken if there is a mismatch.

#### 4.1.2 Camera Calibration

Camera calibration is done using uniform distribution phantom. This protocol is to calibrate the radiation intensity measured by scintillation camera according to the actual radiation measured. The phantom used in this protocol has a known radioactivity. Therefore the adjustments are made where the radioactivity converts to the voltage.




Figure 7: Scintillation Camera

### 4.2 Quality assurance methods for Imaging system

#### 4.2.1 Flood field uniformity

Flood field uniformity test measures the uniformity of the camera response for a uniform flux of radiation. A uniform flood phantom is used for this test as shown in



Figure 8: Uniform flood source

above figure. It is uniformly filled Co-57 or Te-99m. A PET scan of this phantom is taken daily and checks for non-uniformity by visual inspection. A quantitative measurement is taken weekly by checking for uniformity by the software. Phantoms should be refilled each time and to maintain uniformity it should be mixed thoroughly.

#### 4.2.2 Energy Resolution

Energy resolution depicts the ability to identify different energy photons. This measurement is made by the intrinsic energy resolution using a point radiation source. For a quantitative measurement multi-channel analyzer is used for the gamma camera.

Equation for the energy resolution,

$$\Delta E(\%) = \frac{FWHME}{E} \times 100$$

FWHME - Width of Photo-peak E - Photo-peak mean energy

#### 4.2.3 Shield Leakage Test

Shield leakage test is used to measure the gamma camera count rates when exposed to a radioactive source outside the collimator. To check count rates at various points on the shield, a cubic source is used. These count rates are compared with count rate records of the source was placed at 100 mm off from the collimator face.

Leakage count rates calculated by following equation.

$$L(\%) = \frac{Observed\_count\_rate}{Reference\_count\_rate} \times 100\%$$




Figure 9: Shield leakage test steps

#### 4.2.4 Counter rate performance Test

Maximum count rate capacity and count rate losses of camera can be measured by this test. Standard phantom is used to measure those parameters.

#### 4.3 Quality assurance methods for Image quality

#### 4.3.1 SNR

Signal to Noise ratio is one of the most important parameter which shows the quality of the image. Main sources of noise are the deviating system components and moving body parts of the patient. In a high quality image SNR is significantly high with big portion of signal and few noise portion. Signal should be higher than noise component. SNR is defined as follows,

$$SNR = \frac{Mean\_signal\_intensity}{S.D\_noise}$$

Since windows functions many other functions are used in the system, SNR value based on above equation does not depicts the exact amount of noise. Therefore CNR - Contrast to Noise ratio is preferred for that.

#### 4.3.2 CNR.

Contrast means the ability to distinguish two different things. Here in imaging, contrast is the ability to distinguish two different tissues and identify separately. Contrast to Noise ratio is a measurement of this. A spherical phantom is kept in a volume of fluid of know size containing uniform concentration of radioactive substances. Then the value of pixels in the background of the sphere and the values of pixels inside the sphere can be measured.

$$Contrast = \frac{Value_{sphere} - Value_{background}}{Value_{sphere} + Value_{background}}$$
 
$$CNR = \frac{Contrast}{\sigma_{background}}$$

Basically CNR measures the ability of the imaging system to determine a particular are of different type or activity from the background.

#### 4.3.3 Image Uniformity test

Image Uniformity test is used to ensure that the output of the camera is an uniform image with respect to a uniform object. Uniform sources are used for this test. Generally there is no parameter to determine how uniform the image is. Main reason for the non-uniformity us the attenuation with increasing depth of the phantom. It is measured by the difference of contrast of a symmetrical artefact with respect to a uniform background.




Figure 10: Image uniformity test for circular uniform phantom

#### 4.3.4 Spatial Resolution

Spatial resolution is an important parameter which indicates the smallest distance between to objects that can be identified as two objects separately in the image. With time due to exposure for gamma rays, camera losses its ability and spatial resolution is reduced. Thus measuring it is a quality assurance procedure.

Using transmission or emission phantoms spatial resolution can be qualitatively assessed.




Figure 11: +Assessment of spatial resolution

#### 4.3.5 Artefacts

Artefacts are the objects and ghostly images which can be seen on images but which do not exist physically. This can lead to doctors to wrong interpretations. There are reasons to see artefacts in images. Normally a PET or SPECT scanner comes with a CT scanner built in parallel. In order to use the PET; CT scanner is also used. Therefore artefacts in that system also contribute to the final outcome.

Cause of Artefact	Description
Metallic Implants	Dental fillings, bone prosthetics etc. cause streak artefacts in the CT image. This result in associated PET/SPECT artefacts
Respiratory Motion of the patient	Acquisition time of PET is relatively higher than CT. Therefore several breathing cycles are involved during a single PET scan. The difference in chest position during PET and Ct can cause artefacts
Truncation artefacts	Caused because of the extension of body parts of the patients beyond the field of view
Contrast Agents	Orally administered contrast agents such as Iodine and Barium Sulphate can cause similar effects to metallic implants

### 4.4 Quality assurance methods for display print quality

This tests are used when the printed images are taken from the same system.

#### 4.4.1 Display Print quality control

There can be differences in the image printed on the film and image displayed in the computer display. Quality assurance method is to reduce the deterioration of the image while printing it into a film.

Following figure shows a standard test pattern used for this test. It is consisted with several gray scale squares with different intensities. After imaging this, it can be printed onto a film and measure the gray scale values using a densitometer.

#### 4.4.2 Display quality control

Using the same image in the previous topic, this test also can be done. Image is loaded onto the computer display and checked whether the different squares with




Figure 12: SMPTE test pattern for Display quality

different gray-scales can be contrasted. If not there is a issue on the Display monitor and needed to be repaired.

#### 4.5 Quality assurance methods for Safety measures

#### 4.5.1 Background radiation check

Background radiation check is a daily protocol followed in imaging unit to ensure that the radiation exposure is maintained int the accepted range. This test is important for both the patient and the operator of the scanner. To count the amount of radiation in the imaging room a gamma detector is used. If the radiation level is more than the maximum level of radiation allowed, imaging processes should be stopped and the people inside the room should be evacuated safely. And the room should be decontaminated and should take necessary steps to fix whatever the problem which caused the high amount of radiation in the room.

## 5 Recent advancements in Nuclear Medicine Imaging Quality Assurance

PET

SPECT scanners are widely used for cancer detection nowadays. When radioactive medicine are injected to the body, they go through all over the body and stops at places with high metabolism. That means radioactive substances are collected at cancerous cells. Therefore these places are bright spots in the PET/SPECT images. If these bright spots are not spread out all over body they can be treated and removed. Therefore Nuclear Medicine Imaging is really important for treating cancers.

Since this procedure requires high contrast to identify small cancerous spots a CT scanner is also attached with the PET scanner. But this combined machine requires new quality assurance methods and phantoms to be operated. Every parameter discussed earlier should be tested for both systems. There are no specific protocols to check parameters that are results of combination of systems. A new research




Figure 13: PET+CT phantom

has developed a phantom to be used in Quality Assurance in CT + PET/SPECT

system. It solves most of the problems discussed above. New protocols and Quality assurance methods are published according to this by International Atomic Energy Agency and World Health Organization.

## 6 Reference

- 1. nternational Atomic Energy Agency, QUALITY ASSURANCE FOR PET AND PET/CT SYSTEMS, Vienna: IAEA, 2009.
- 2. P. Keim, "An Overview of PET Quality Assurance Procedures: Part 1," Journal of Nuclear Medicine Technology, vol. 22, no. 1, pp. 27-34, 1994.
- 3. A. R. Webb, Introduction to biomedical imaging. Hoboken, N. J.: John Wiley & Sons, 2006.
- 4. Internation Atomic Energy Agency, Quality Assurance for SPECT Systems, Vienna: IAEA, 2009.
- 5. "Home," RSS. [Online]. Available: http://www.aapm.org/. [Accessed: 18-May-2020].
- 6. Biodex, "PET Phantoms," Biodex, [Online]. Available: http://www.biodex.com/nuclear-medicine/products/pet-positron-emission-tomography/pet-phantoms. [Accessed 23 05 2020].

## Appendix

# List of Figures

1	PET Scanner	2
2	Basic structure of SPECT/PET Scanner	2
3	Quality Assurance & QC cycle	
4	Phantoms and Calibration equipment for PET-CT	4
5	Cylindrical phantom	5
6	Center of rotation - SPECT	6
7	Scintillation Camera	7
8	Uniform flood source	
9	Shield leakage test steps	
10	Image uniformity test for circular uniform phantom	10
11	+Assessment of spatial resolution	10
12	SMPTE test pattern for Display quality	12
13	PET+CT phantom	13