RELEASE NOTES

Release Notes for PathPilot® v2.0.1

Release Date: January 9, 2018

Fixed Issues

All Machines

• Some files are not correctly recognized as G-code, and the File tab will not load them. (PP-1887)

Mills

• Resolved a RapidTurn® pausing issue when using G-codes dependent on spindle speed sensing.

Lathe

• Resolved a rare G96 arc blend following error.

