

Process Name/ Title: Cleaning Countermeasure if Level 3 & Level 4 Limit occur WORK INSTRUCTION

Document No:

WI-PRO-SHM-040

August 15,2017

Effective Date: Customer Code:

Rev. No.:

0

Page No.:

1 of 1

No.

Work Procedure/ Illustration

TRJ/TRQSS

Note: Standard Cleaning / Removal of flux is 1 time at the top and 1 time in between terminal

Product Code/Name:

ALL

1. Conduct 100 % visual Inspection after removal of flux



NG Limit of Flux Removal



Level 3




2. Remove flux 2~3 times at the top

(from left to right)

NOTE: If encounter the 2 limit of flux removal, conduct 200 % cleaning

1. Return the work piece into jig.



NOTE: Gently return the workpiece into

jig to avoid component damage.





4. Remove flux 2~3 times in between terminals (from up to down)



5. Clean the bamboo stick into wire cleaner



7. Conduct again 100 % visual Inspection. Make sure the limit of removal of flux is OK.



Yh			
	Prepare	Check_	Approve
	Ramilo	o. Merin	T. Sugiyama



6. Clean / remove flux in

both side of terminal.

Eff./Rev. Date Doc/DRCN No. Details of change 08/15/2017 Revise Check Approve Est. date: