

Process Name/ Title:
Wire Cutting and Crimping /
Wire and Strip Length Measurement Procedure

Document No:

WI-PRO-CNC-011

July 10, 2017

WORK INSTRUCTION
Product Code/Name: Custo
ALL

Customer Code: ALL Effective Date: Rev. No.:

0

Page No.:

Page 1 of 1

	ALL ALL ITEM C TOURS	Records/Remarks/
No.	Work Procedure/ Illustration	Quality Pointers
	1. Wire Length Measurement	
	Tools: Scale Measurement Point: End of core wire to the other end of core wire.	
	10 20 30 40 50 60 70 80 90 100	
	Important Points:	
	*When measuring wire length, make sure that wire and scale are in parallel position. *Always measure starting from 0 (zero) point.	
	10 20 30 40 50 60 70 80 90 100	
	*Do not measure when wire is bent or askew.	
	10 20 30 40 50 60 70 80 90 100	
	2. Strip Length Measurement	
	Tools: Steel ruler (150 mm) Measurement Point: End of insulation to end of core wire.	
	10 20 30	
	1-4	
	Important Points:	
	*When measuring strip length, end of steel ruler (zero 0 point) must touch the end of insulation.	
	Even and straight cut Cut Diagonally Uneven cut	
	Good NO Good	
	NBC (Philippines)	
	MASTER COPY	Çheck Approve
	Prepare 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Check Approve
-	NBCP-1013 NA Previously established Work Instruction(for history purpose only) Z. Mende	z O.MERIN T. SUGIYAMA
Eff./Rev.Date		07/10/2017