

EXDA Sensors Mapping Export

Project: VH2D-Project
 Responsible Researcher: PhD Student Javier I. Camacho
 Total Groups: 7
 Total Sensor IDs: 11
 Total Sensor Mappings: 15
 Sensor Mounting Reference File: frontend/public/SensorMountingLocation-000.pdf
 Generated: 2026-05-25 20:32:29

Group: Prep

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
Prep	P1	pressure	DAQ-1	CH1	125402	-80.88	5L	(0.45,0.593,0.396)	flush	Yes	No	-	Complete
					4	pC/bar							
Prep	P2	pressure	DAQ-2	CH2	626680	-37.02	6L	(0.450,0.290,0.403)	flush	Yes	No	-	Complete
					1	pC/bar							
Prep	Trig-1	voltage	DAQ-1	CH5	-	- pC/bar	-	(-, -, -)	N/A	Yes	No	M-Duino	Complete
Prep	Trig-2	voltage	DAQ-2	CH4	-	- pC/bar	-	(-, -, -)	N/A	Yes	No	M-Duino	Complete

Group: VH2D-01

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-01	P1	pressure	DAQ-1	CH1	125402	-80.88	5L	(0.45,0.593,0.396)	flush	Yes	No	-	Complete
					4	pC/bar							
VH2D-01	P2	pressure	DAQ-2	CH2	626680	-37.02	6L	(0.450,0.290,0.403)	flush	Yes	No	-	Incomplete
					1	pC/bar							
VH2D-01	P3	pressure	DAQ-1	CH3	-	- pC/bar	-	(-, -, -)	other	Yes	Yes	-	Incomplete
VH2D-01	P4	pressure	DAQ-1	CH4	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
VH2D-01	P5	pressure	DAQ-2	CH1	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
VH2D-01	P6	pressure	DAQ-2	CH2	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
VH2D-01	P7	pressure	DAQ-2	CH3	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
VH2D-01	P8	pressure	DAQ-3	CH1	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
VH2D-01	Trig-1	voltage	DAQ-1	CH5	-	- pC/bar	-	(-, -, -)	N/A	Yes	No	M-Duino	Complete
VH2D-01	Trig-2	voltage	DAQ-2	CH4	-	- pC/bar	-	(-, -, -)	N/A	Yes	No	M-Duino	Complete
VH2D-01	Trig-3	voltage	DAQ-3	CH2	-	- pC/bar	-	(-, -, -)	N/A	Yes	No	M-Duino	Complete

Group: VH2D-02

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-02	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

=====
Group: VH2D-03

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-03	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

=====
Group: VH2D-04

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-04	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

=====
Group: VH2D-05

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-05	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

=====
Group: VH2D-06

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-06	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

Sensor Mounting Reference Diagram

Source: frontend/public/SensorMountingLocation-000.pdf

Pressure Sensor Location Mapping Overview

