

切削参数参考表
Recommended Milling Conditions

加工材料 Work Material			铜合金 Copper			
外径 Dia.	角半径(R) Corner Radius	颈长(l1) Under Neck Length	主轴转速 Spindle Speed	进给速度 Feed	切深量 Depth of Cut	
			min-1	mm/min	ap mm	ae mm
1	0.05	4	25,000	2,200	0.03	0.6
		6	20,000	1,800	0.024	0.6
		8	16,000	1,400	0.02	0.6
		10	12,000	1,000	0.02	0.6
	0.4	4	25,000	2,200	0.055	0.6
		6	20,000	1,800	0.045	0.6
		8	16,000	1,400	0.04	0.6
		10	12,000	1,000	0.03	0.6
	0.2	4	25,000	2,200	0.11	0.6
		5	22,000	2,000	0.1	0.6
		6	20,000	1,800	0.09	0.6
		8	16,000	1,400	0.08	0.6
		10	12,000	1,000	0.06	0.6
		12	12,000	1,000	0.06	0.6
1.5	0.2	6	20,000	2,400	0.12	0.9
		8	20,000	1,600	0.1	0.9
		10	16,000	1,600	0.1	0.9
		12	16,000	1,000	0.07	0.9
		16	12,000	1,000	0.08	0.9
2	0.1	8	14,000	2,600	0.06	1.2
		10	12,000	2,000	0.06	1.2
		12	12,000	2,000	0.05	1.2
	0.2	8	14,000	2,600	0.12	1.2
		10	12,000	2,000	0.12	1.2
		12	12,000	2,000	0.1	1.2
		16	10,000	1,600	0.08	1.2
	0.5	8	14,000	2,600	0.3	1.2
		10	12,000	2,000	0.3	1.2
		12	12,000	2,000	0.25	1.2
3	0.2	16	10,000	1,600	0.2	1.2
		20	8,000	1,200	0.15	1.2
		10	14,000	3,000	0.15	1.8
		12	14,000	3,000	0.12	1.8
		14	13,000	2,600	0.1	1.8
	0.3	16	12,000	2,400	0.08	1.8
		20	10,000	1,800	0.08	1.8
		12	14,000	3,000	0.18	1.8
		16	12,000	2,400	0.15	1.8
	0.5	20	10,000	1,800	0.12	1.8
		10	14,000	3,000	0.3	1.8
		12	14,000	3,000	0.3	1.8
		16	12,000	2,400	0.25	1.8
		20	10,000	1,800	0.2	1.8

加工材料 Work Material			铜合金 Copper			
外径 Dia.	角半径(R) Corner Radius	颈长(l1) Under Neck Length	主轴转速 Spindle Speed	进给速度 Feed	切深量 Depth of Cut	
			min-1	mm/min	ap mm	ae mm
4	0.2	12	10,000	2,800	0.14	2.8
		16	10,000	2,800	0.14	2.8
		20	8,000	2,200	0.12	2.8
	0.3	12	10,000	2,800	0.18	2.8
		16	10,000	2,800	0.18	2.8
		20	8,000	2,200	0.15	2.8
	0.5	12	10,000	2,800	0.3	2.4
		16	10,000	2,800	0.3	2.4
		20	8,000	2,200	0.24	2.4
备注 Notes		※本切削参数仅供参考。请根据实际的加工形状和所使用的机床等调整切削参数。 ※切深量的ap表示轴向切深量，ae表示径向切深量。 ※轴向进刀建议采用螺旋进刀及倾斜进刀方式。 ※沟槽切削时建议参考切削参数表，进给速度设定为60%以下，并采用来回切削加工方式。 ※发生振刀时，请以相同的比率降低主轴转速和进给速度。此外，主轴转速过低时，也以相同的比率降低。 ※建议使用油冷冷却方式。 ※ The cutting parameters are for reference only. Please adjust the cutting parameters according to the actual machining shape and the machine tool used. ※ The ap of the cutting depth indicates the axial cutting depth, and the ae indicates the radial cutting depth. ※ Screw feed and inclined feed are recommended for axial feed. ※ It is recommended to refer to the cutting parameter table when grooving cutting, the feed speed is set to less than 60%, and the cutting mode is adopted. ※ When vibrating knife occurs, please reduce the spindle speed and feed speed in the same ratio. In addition, when the spindle speed is too low, it is also reduced at the same rate. ※ Oil cooling is recommended.				

切削参数参考表
Recommended Milling Conditions