

Customer accepts the risk of these holes being too close ot the board edge

