December 17, 2024

IMPORTANT UPDATE

Correction: Resistor Value Update

The VCA output sound was faulty: the low frequencies were filtered (the VCF output is OK).

The previously listed value of the resistor was incorrect.

R50

Incorrect Value: 330Ω Correct Value: $51K\Omega$

R52

Incorrect Value: $1K\Omega$ Correct Value: $68K\Omega$

I've also updated the documentation and files in the repository to reflect this change.