




Why a Free Heading Did Not Produce a Smooth 3D Turn



Model schematic (not an optimized mission result): straight corridors remain expected, but unlimited corners are removed.