


Strain at sensor T8 due to Truck 1 moving across bridge 705



Strain at sensor T9 due to Truck 1 moving across bridge 705

