


Strain at sensor T17 due to Truck 1 moving across bridge 705



Strain at sensor T18 due to Truck 1 moving across bridge 705

