



Return Part address:
East Gate, Trenchard Way
GU146GU Farnborough
UNITED KINGDOM

UNSERVICEABLE

Repair Station Number GAL FARNBOROUGH	Date 23-Jun-2025	Quantity 1	Customer Purchase Order	Customer Code	Customs Value
--	---------------------	---------------	-------------------------	---------------	---------------

Customer Company Name:	Customer Phone:
Customer Contact Name:	Customer Email:

Check all that apply ☐ Scheduled Removal ☐ Customer Repair ☐ Rental Return (Complete Rental Section) ☐ QA Material Evaluation ☐ Warranty Core
☐ Special Missions Aircraft; e.g., SEMA ☐ Original Aircraft Equipment ☐ AOS/Plane Parts ☐ Exchange Core ☐ Unused Return for Credit

Aircraft Model G650ER	Aircraft Serial # 6327	Aircraft Registration # OE-LTF	A/C Hours 2748:48	A/C Cycles 1064	Complete if Engine Related Squawk ☐ Engine ☐ APU	Engine Model Engine S/N	Engine Time Engine Cycles
Complete if Rental Return Rental Time Rental Cycles Date Installed Date Removed							

FAA CFR 43.10 requires operators to document and certify the life status of each life-limited part listed in AMM Chapter 5. Life Status Data: Enter values for fields that apply per AMM Chapter 5.

Part Name HARNESS POCKET DOOR W/ENCODER			Part Number 42598-01			Serial Number NSN	Manufacture Date
Time and Cycles Since New			Time and Cycles Since Overhaul / Restore (OH / Res)			Total Life / Installed Life	
Time Since New	Cycles Since New	Yrs / Mths Since New	Time Since OH / Res	Cycles Since OH / Res	Yrs / Mths Since OH / Res	Total Life Yrs / Mths	Installed Life Yrs / Mths

Please refer to the Method of Execution (MOE) document for instructions to complete this form and the addendum sheet. For landing gear and APUs, if the total hours and cycles of life-limited component sub-assemblies are different than the top-level assembly, individual hours and cycles for the sub-assemblies must be provided on the addendum sheet. The MOE and a blank addendum sheet may be found using the QR code shown or by visiting <https://www.mygulfstream.com/wps/myportal/mygulfstream/parts/gulfstream-repair-tag>.



Failure Information - Help Reduce No Fault Found - Send related pictures and videos to: NFF@Gulfstream.com

Reason for Part Removal: FOUND OPEN CIRCUIT / HIGH RESISTANCE ON K1 RELAY PIN 1/2 ON THE ENCODER PLUG	Work Performed/Resolution:
---	----------------------------

Download fault code from on-board maintenance computer Are fault codes available? ☐ Yes ☒ No Code: Code:	Point of contact with most knowledge about failure mode / fault isolation Name Phone
Condition at Time of Failure - check all boxes that apply - other data may be required. ☒ On ground ☐ In Flight ☐ At first power up ☐ Climb Time: ☒ At any power up ☐ Descent ☐ Landing Cruise Altitude:	FIM Section Used MyCMP Diagnostics Session Number
Did the replacement part solve the problem? ☐ Yes ☐ No	

Customer Property Repair		
Priority ☐ AOG ☐ Urgent ☐ Routine	Requested Return Date	Certification Requirements ☐ FAA 8130-3 ☐ EASA Form 1 Other:
Ship to Address:	Carrier: Carrier Account #: Shipping Instructions:	Paint ☐ Yes ☐ No Paint Color Code: Paint Color Code:

Customer Use I certify that the information regarding aircraft and unit total time and cycles in service provided above is accurate and was verified by the aircraft records required by US Federal Aviation Regulation 91.417		
Authorized Customer - Print Name	Authorized Customer Signature	Customer Certificate Number
☐ Military	☐ FAA Rating Airframe/Power plant	Date Signed ☐ Certified Repair Station / Certificate ☐ FNAA

Gulfstream Internal Use						
GAC Sales Order #	GAC Work Order #	Return Authorization #	SAP Batch #	Tag Originator Name	Employee ID #	Inspection Stamp

Incomplete forms will be returned for completion at operator's expense before parts are processed. Please refer to the Instructions in the Method of Execution document.