

微算機實驗報告

Lab #14

姓名:楊哲睿


系級:電機10 學號:0610780

上課時間:4EF、4IJ

一、實驗目的:

- 瞭解如何用 C 語言撰寫微控器程式。
- 瞭解 Timer/Counter 工作原理進行距離量測。
- 利用超音波模組實現測距的功能,將超音波反射的概念結合。


二、硬體架構:



三、程式流程圖:


● 基本題

顯示以公分為單位的距離(要到小數點第一位)。



● 進階題

加入按鈕模組,當按下按鈕可以切換成以公尺為單位的距離(要到小數點第三位)。



四、問題與討論:

● 如何用 C 語言設定某腳位為 input-only?

實際上,沒有什麼方法可以將 8051 的 pin 設置為只能輸入或輸出專用;因為所有引腳都是雙向的。

但是,如果向一個腳位寫「①」,漏極開路驅動器(open-drain driver)會被設為 ON,任何外部的訊號都無法改變該腳位「①」的狀態。此時輸入只能讀到「①」。

但如果向一個腳位寫「1」,則會將漏極開路驅動器設為 0FF,因此外部信號可以將該腳位設置為高電位 (1) 或低電位 (0),也就是說,此時輸入可以讀取外部信號的狀態。

所以說,當我們把 PORT 設為 0xFF 時,會讓外部資料可以傳送進 PORT,算是部分 input-only;反之如果不希望外部資料輸入,就可以先 把 PORT 設為 0x00。

● 在使用 C 語言時,有 RO 到 R7 這些暫存器嗎?

8051 的指令集中,可以直接定址的有 R0 到 R7 一共 8 個暫存器,Keil C51 拿其中的 6 個暫存器來組成 3 個 16 位元的暫存器作為傳遞 C 的函數參數之用,因此函數的參數大於 3 個的部份就必需用「記憶體」而不能直接使用「暫存器」。

也就是說,R0到R7不能像組合語言一樣直接使用,但是仍可以使用這些儲存空間,只要定義好儲存空間在記憶體中的位址,就可以使用這些暫存器。

● 如何使用 C 語言宣告變數,以及有哪些該注意的地方?

一般來說,就跟平時寫 C 語言一樣那樣宣告變數,只是變數宣告在 程式中間時好像會有問題,所以在宣告變數時最好在程式的開頭或是函 式的起始位置等地方宣告。

● 組語有 TABLE,那 C 語言該怎麼實踐? 可以用 C 語言裡面的 array 去實現組合語言中 TABLE 的功能。

五、程式碼與註解:

● 基本題

顯示以公分為單位的距離(要到小數點第一位)。

以下的 code 不是很完整,沒有完全跑出結果哪

```
#include <reg52.h>
#include <stdio.h>
#include <LCD 8 bit.h>
#include <math.h>
#define sound_velocity 34300 /* sound velocity in cm
per second */
#define period in us pow(10,-6)
#define Clock_period 1.085*period_in_us /* period for
clock cycle of 8051*/
sbit Echo_pin = P2^7; /* Echo pin */
void Delay_us()
   TL0 = 0xF5;
   TH0 = 0xFF;
   TR0 = 1;
   while (TF0==0);
      TR0 = 0;
   TF0 = 0;
}
void init_timer(){
   TMOD = 0 \times 01;
   /*initialize Timer*/
   TF0 = 0;
   TR0 = 0;
}
void send_trigger_pulse(){
   Trigger_pin = 1;
                             /* pull trigger pin HIGH
*/
   Delay_us();
                          /* provide 10uS Delay*/
                          /* pull trigger pin LOW*/
   Trigger_pin = 0;
}
```

```
void main()
{
   float distance measurement, value;
   unsigned char distance in cm[10];
                        /* Initialize 16x2 LCD */
   LCD Init();
   LCD_String_xy(1, 1, "Distance:");
                        /* Initialize Timer*/
   init timer();
   while(1)
   {
       send trigger pulse(); /* send trigger pulse
of 10us */
       while(!Echo pin);
                                      /* Waiting for
Echo */
                                          /* Timer
          TR0 = 1;
Starts */
       while(Echo pin && !TF0);
                                 /* Waiting for
Echo goes LOW */
                                          /* Stop the
          TR0 = 0;
timer */
       /* calculate distance using timer */
       value = Clock period * sound velocity;
       distance measurement = (TL0 | (TH0 << 8)); /* read
timer register for time count */
       distance measurement =
(distance_measurement*value) / 2.0; /* find distance(in
cm) */
       sprintf(distance_in_cm, "%.2f",
distance_measurement);
       LCD_String_xy(2,1,distance_in_cm); /* show
distance on 16x2 LCD */
       LCD_String(" cm ");
       delay(100);
```

```
}
```

● 進階題

加入按鈕模組,當按下按鈕可以切換成以公尺為單位的距離(要到小數 點第三位)。

以下的 code 不是很完整,沒有完全跑出結果哪

```
#include <reg52.h>
#define sound_velocity 34300 /* sound velocity in cm
per second */
#define period in us 0.000001
#define Clock_period 1.085*period_in_us /* period for
clock cycle of 8051*/
sbit Trigger pin = P3^6;
                               /* Trigger pin */
sbit Echo pin = P3^7; /* Echo pin */
#define LcdDataBus P2
sbit LCD RS = P1^0;
sbit LCD RW = P1^1;
sbit LCD_EN = P1^2;
/* local function to generate delay */
void delay_us(int cnt) {
   for(int i = 0; i < cnt; i++);
}
/* Function to send the command to LCD */
void Lcd_CmdWrite(char cmd) {
   LcdDataBus = cmd; // Send the command to LCD
   LCD_RS = 0;
                       // Select the Command Register by
pulling RS LOW
                       // Select the Write Operation by
   LCD_RW = 0;
pulling RW LOW
```

```
LCD EN = 1; // Send a High-to-Low Pusle at
Enable Pin
   delay us(10);
   LCD_EN = 0;
   delay_us(1000);
}
/* Function to send the Data to LCD */
void Lcd DataWrite(char dat) {
   LcdDataBus = dat; // Send the data to LCD
                     // Select the Data Register by
   LCD RS = 1;
pulling RS HIGH
                     // Select the Write Operation by
   LCD_RW = 0;
pulling RW LOW
   LCD EN = 1;
                      // Send a High-to-Low Pusle at
Enable Pin
   delay us(10);
   LCD_EN = 0;
   delay_us(1000);
}
void delay(int k) {
   for(int i = 0; i < k; i++)
       for(int j = 0; j < 112; j++);
}
void Delay_us() {
   TL0 = 0xF5;
   TH0 = 0xFF;
   TR0 = 1;
   while(TF0 == 0);
       TR0 = 0;
   TF0 = 0;
}
void init_timer() {
   TMOD = 0 \times 01;
   /*initialize Timer*/
```

```
TF0 = 0;
   TR0 = 0;
}
void send_trigger_pulse() {
   Trigger pin = 1;
                                /* pull trigger pin HIGH
*/
                            /* provide 10uS Delay*/
   Delay_us();
   Trigger pin = 0;
                            /* pull trigger pin LOW*/
}
void main()
{
   float distance measurement = 10;
   //unsigned char distance in cm[10];
   Lcd_CmdWrite(0x38);  // enable 5x7 mode for
chars
   Lcd CmdWrite(0x0E);
                             // Display OFF, Cursor ON
   Lcd CmdWrite(0x01);
                            // Clear Display
   Lcd_CmdWrite(0x80);
                             // Move the cursor to
beginning of first line
   init_timer();
                            /* Initialize Timer*/
   while(1) {
       float distance_measurement = 10, value;
       int temp, temp1, temp2, temp3, temp4, temp5;
       Lcd CmdWrite(0xc0);
                                   /* send trigger pulse
       send trigger pulse();
of 10us */
                                      /* Waiting for
       while(!Echo pin);
Echo */
                                           /* Timer
          TR0 = 1;
Starts */
       while(Echo_pin && !TF0);
                                      /* Waiting for
```

```
Echo goes LOW */
           TR0 = 0;
                                            /* Stop the
timer */
       /* calculate distance using timer */
       value = Clock period * sound velocity;
       distance_measurement = (TL0|(TH0<<8)); /* read</pre>
timer register for time count */
       distance measurement =
(distance measurement*value)/2.0; /* find distance(in
cm) */
       distance measurement = distance measurement *
1000;
       temp = distance measurement/10;
       temp1 = distance measurement-temp*10;
       distance measurement =distance measurement/10;
       temp = distance_measurement/10;
       temp2 = distance measurement-temp*10;
       distance_measurement =distance_measurement/10;
       temp = distance measurement/10;
       temp3 = distance measurement-temp*10;
       distance_measurement =distance_measurement/10;
       temp = distance measurement/10;
       temp4 = distance_measurement-temp*10;
       distance measurement = distance measurement/10;
       temp = distance measurement/10;
       temp5 = distance measurement-temp*10;
       Lcd_DataWrite('0'+temp5);
       Lcd DataWrite('0'+temp4);
       Lcd_DataWrite('.');
       Lcd_DataWrite('0'+temp3);
       Lcd_DataWrite('0'+temp2);
       Lcd_DataWrite('0'+temp1);
```

```
Lcd_DataWrite('c');
Lcd_DataWrite('m');

delay(100);
}
```

六、心得:

這次實驗真的世界無敵難的,我到現在還是不知道怎麼讓他動起來,程式碼看了好久好久,改了一堆地方都沒有用,幸好這已經是最後一次實驗了,希望之後如果還有機會的話,可以知道怎麼讓他正常的運作。感覺會用 C 語言控制 8051 也是一件很重要必須要會的事情,雖然這次上課沒弄懂,相信之後總有一天我會征服他的。