

Property damage claim

North Fern Mutual demonstration form

CLAIM REFERENCE

CL-8508

POLICYHOLDER

Hayden Lake

LOSS DATE

September 9, 2026

LOCATION

21 Fictional Lane

Statement of loss

A water supply fitting failed in the service room during the evening. Water damaged the floor finish and a storage cabinet. The policyholder isolated the water supply and notified the building manager.

Requested reimbursement

The policyholder requests reimbursement of documented repair expenses. Estimated loss: \$2,812.00. Supporting reports and vendor records are attached separately.

Declaration

I certify that this fictional statement represents the circumstances described in this demonstration.
Policyholder: Hayden Lake. Signature: SAMPLE ONLY.

Reference 8508 / continued

Additional loss details

Continuation of CL-8508. The affected cabinet contained spare equipment and cleaning materials. None of the items are personal records or genuine customer property.

Supporting statement

The policyholder had not observed a leak before the incident. An equipment inspection two weeks earlier recorded normal operation. Repairs await the contractor's final scope.

Incident report

Maple Current Facilities team

REPORT NUMBER

IR-8511

INCIDENT DATE

September 12, 2026

REPORTING OFFICER

Jordan Lark

SITE

21 Fictional Lane, service room

Observed conditions

At 18:20 the facilities officer found standing water next to the supply cabinet. The floor covering was wet along the north wall. No injuries were reported.

Immediate response

The officer closed the isolation valve, placed warning signs at the entrance, and moved stored materials away from the wet area. A repair contractor attended the following morning.

Cause and follow up

A split flexible supply hose was visible behind the cabinet. Retain the damaged fitting for inspection and record moisture readings before reinstating the floor.

Reference 8511 / continued

Follow up observations

Continuation of IR-8511. The second inspection found no further escape of water. A moisture meter showed the greatest reading near the cabinet base.

Witness statement

Jordan Lark reported hearing water flow before entering the room. The witness contacted the facilities desk immediately. Photographic evidence is represented by the written site notes in this synthetic record.

Repair estimate

Quarry Lane Restoration

ESTIMATE REFERENCE

EST-8517

PREPARED FOR

Parker Quinn

SITE

21 Fictional Lane

VALID THROUGH

October 30, 2026

Proposed work

Remove the damaged floor finish, dry the substrate, and replace the affected panels. Reinstate cabinet skirting after moisture readings meet the installation requirement.

Conditions

This quotation is an estimate for proposed work. It is subject to customer acceptance before scheduling. Additional concealed damage requires a revised written estimate.

Proposed work	Hours	Estimated cost
Removal and drying	8	\$960.00
Floor finish and skirting	12	\$1,440.00
Estimated total		\$2,400.00

Reference 8517 / continued

Work schedule and exclusions

Continuation of estimate EST-8517. Allow two days for drying and one day for reinstatement. The quoted scope excludes structural repair and work outside the affected room.

Acceptance

The customer may approve the proposed scope in writing. Materials will be ordered after acceptance. This estimate is valid until the date stated on its first page.

Invoice

North Fern Services to Juniper Works

INVOICE NUMBER

INV-8520

BILL TO

Juniper Works, 14 Example Way

ISSUED

September 21, 2026

PAYMENT TERMS

Net 30, USD

Payment requested

Please remit \$1,699.00 for the completed services listed below. Reference INV-8520 with your payment. No account or payment details in this fixture are real.

Remittance note

Payment is due thirty days after issue. Contact billing@example.invalid for a corrected copy.

Service	Quantity	Amount
Equipment restoration	1	\$1,519.00
Inspection and travel	1	\$180.00
TOTAL DUE		\$1,699.00

Reference 8520 / continued

Service detail

Continuation of INV-8520. Technician work log: isolate damaged fittings, complete pressure testing, and confirm the equipment is safe to return to service.

Work completed

Inspection: 1.5 hours. Restoration: 3.0 hours. Verification: 1.0 hour. The charges summarize work already delivered and form part of the amount due on the preceding page.

Invoice

Maple Current Services to Cobalt Harbor

INVOICE NUMBER

INV-8523

BILL TO

Cobalt Harbor, 14 Example Way

ISSUED

September 24, 2026

PAYMENT TERMS

Net 30, USD

Payment requested

Please remit \$1,948.00 for the completed services listed below. Reference INV-8523 with your payment. No account or payment details in this fixture are real.

Remittance note

Payment is due thirty days after issue. Contact billing@example.invalid for a corrected copy.

Service	Quantity	Amount
Equipment restoration	1	\$1,768.00
Inspection and travel	1	\$180.00
TOTAL DUE		\$1,948.00

Claim correspondence

Morrow Studio Claims desk

TO

Skyler Brooks

FROM

claims@example.invalid

DATE

September 2, 2026

SUBJECT

Supporting information for CL-8526

Dear policyholder

Thank you for providing the supporting documents. We have received the initial loss statement and contractor records. The assigned reviewer will compare the records with the policy terms.

Next step

Please retain the damaged materials until the inspection is complete. If you locate additional photographs from the day of the loss, send copies with your claim reference.

Regards

Alex Rowan, demonstration claims coordinator. This letter contains no coverage decision and belongs to a synthetic example.