Report number - EDAD9EF4-1F72-4B69-9460-C2AA6A90A5CA-1780966844

BUILDING AND PEST INSPECTION
MELBOURNE.COM.AU

Property and Timber Pest

Inspection Date: 9 Jun 2026

Property Address: 9 Furness Close Wyndham Vale 3024

Contents

Inspection Details 3

General description of property 4

Accessibility 7

Property Inspection Report

Summary 11

Significant Items 12

Additional comments 29

Conclusion 75

Timber Pest Inspection Report

Summary 76

Significant Items 77

Conclusion 82

Risk management options 82

Definitions to help you better understand this report 84

Terms on which this report was prepared 86

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

Inspection Details

Property Address:	9 Furness Close Wyndham Vale 3024
Date:	9 Jun 2026

Client

Name:	James Goodricke
Email Address:	
Phone Number:	

Consultant

Name:	Chamkaur Virk
Email Address:	paulybyres@gmail.com
Company Name:	Building and Pest Professionals
Company Address:	www.buildingandpestinspectionmelbourne.com.au
Company Phone Number:	0408 666 539

General description of property

Building Type:	Detached house
Storeys:	Single storey
Smoke detectors:	2 fitted, but not tested IMPORTANT NOTE - The adequacy and testing of smoke detectors is outside the scope of this standard inspection and report. Accordingly, it is strongly recommended that a further inspection be undertaken by a suitably qualified person.
Siting of the building:	Towards the middle of a medium block
Gradient:	The land is gently sloping
Site drainage:	The site appears to be adequately drained
Access:	Easy pedestrian and vehicular access
Main utility services:	Electricity, Gas, Sewerage, Mains water
Occupancy status:	Occupied
Furnished:	Partially furnished
Strata or company title properties:	No
Weather conditions:	Dry

Primary method of construction

Main building – floor construction:	Slab on ground
Main building – wall construction:	Timber framed, Brick veneer

Main building – roof construction:	Timber framed, Finished with roofing tiles
Other timber building elements:	Architraves, Doors, Skirting
Overall standard of construction:	Acceptable
Overall quality of workmanship and materials:	Acceptable
Level of maintenance:	Reasonably maintained

Special conditions or instructions

Special requirements, requests or instructions given by the client or the client's representative -

There are no special conditions or instructions

Accomodation and significant ancillaries

STOREY	LIVING ROOMS	BEDROOMS	BATHROOM / ENSUITE	SEPARATE TOILET	KITCHEN	LAUNDRY	POOL*	OTHER	NAME OF OTHER
Ground	1	4	2	0	1	1	0	0	
Totals	1	4	2	0	1	1	0	0	

Parking

TYPE	OFF STREET PARKING SPACES (UNCOVERED)	GARAGE (COVERED)	CARPORT (COVERED)
Attached	0	2	0
Detached	0	0	0
Totals	0	2	0

Inspection Agreement

AS 4349.1-2007 and 4349.3-2010 require that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building and which is in reasonable condition, having been adequately maintained over the life of the building. This means that building being inspected may not comply with Australian Standards, building regulations or specific state or territory requirements applicable at the time of the inspection

Inspection agreement supplied: Unknown

Terminology

The definitions below apply to the types of defects associated with individual items / parts or inspection areas -

Damage	The building material or item has deteriorated or is not fit for its designed purpose
Distortion, warping, twisting	The item has moved out of shape or moved from its position
Water penetration, Dampness	Moisture has gained access to unplanned and / or unacceptable areas
Material Deterioration	The item is subject to one or more of the following defects; rusting, rotting, corrosion, decay
Operational	The item or part does not function as expected
Installation	The installation of an item is unacceptable, has failed or is absent

Scope of inspection

BUILDING INSPECTION

This is a visual Building Inspection Report carried out in accordance with AS4349.1 -2007. The purpose of this inspection is to provide advice to the Client regarding the condition of the Building & Site at the time of inspection. The report covers only safety hazards, major defects, and a general impression regarding the extent of minor defects. The building was compared with a building that was constructed in accordance with the generally accepted practice at the time of construction and which has been maintained such that there has been no significant loss of strength and serviceability.

TIMBER PEST INSPECTION

This Visual Timber Pest Inspection & Report is in accordance with Australian Standard 4349.3 -Inspection of Buildings Part 3: Timber Pest Inspections. This Report only deals with the detection or non-detection of Timber Pest Attack and Conditions Conducive to Timber Pest Attack discernible at the time of inspection. The inspection was limited to the Readily Accessible Areas of the Building & Site and was based on a visual examination of surface work (excluding furniture and stored items), and the carrying out of Tests.

Accessibility

Unless noted in “Special Conditions or Instructions”, the inspection only covered the Readily Accessible Areas of the Building and Site (see Note below).

Note. With strata and company title properties, the inspection was limited to the interior and the immediate exterior of the particular residence inspected. Common property was not inspected.

“Readily Accessible Areas” means areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. The term ‘readily accessible’ also includes:

(a) accessible subfloor areas on a sloping site where the minimum clearance is not less than 150 mm high, provided that the area is not more than 2 metres from a point with conforming clearance (i.e. 400 mm high by 600 mm wide); and

(b) areas at the eaves of accessible roof spaces that are within the consultant’s unobstructed line of sight and within arm’s length from a point with conforming clearance (i.e. 600 mm high by 600 mm wide).

“Building and Site” means the inspection of the nominated residence together with relevant features including any car accommodation, detached laundry, ablution facilities and garden sheds, retaining walls more than 700 mm high, paths and driveways, steps, fencing, earth, embankments, surface water drainage and stormwater run-off within 30 m of the building, but within the property boundaries.

For the Timber Pest Report, the term “Building and Site” is extended to include the main building (or main buildings in the case of a building complex) and all timber structures (such as outbuildings, landscaping, retaining walls, fences, bridges, trees and stumps with a diameter greater than 100 mm and timber embedded in soil) and the land within the property boundaries up to a distance of 50 metres from the main building(s).

The inspection did not include areas, which were inaccessible, not readily accessible or obstructed at the time of inspection. Areas, which are not normally accessible, were not inspected and include - but not limited to - the interior of a flat roof or beneath a suspended floor filled with earth. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include – but are not limited to – roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder’s debris, vegetation, pavements or earth.

Areas Inspected

The inspection covered the Readily Accessible Areas of the property

- Building interior
- Building exterior
- Roof exterior
- Roof space

Areas not inspected

The inspection did not include areas, which were inaccessible, not readily accessible or obstructed at the time of inspection. The Consultant did not move or remove any obstructions which may be concealing evidence of defects. Areas, which are not normally accessible, were not inspected. Evidence of defects in obstructed or concealed areas may only be revealed when the items are moved or removed or access has been provided.

Obstructions and Limitations

The following obstructions may conceal defects:

- Built-in cupboards
- Ceilings
- Clothing and personal effects
- Fittings
- Floor coverings
- Flooring
- Stored articles in cupboards
- Stored articles in wardrobes
- Vegetation
- Formwork
- Builder's debris
- Building materials
- Thermal insulation
- Sarking
- Leaves

Obstructions increase the risk of undetected defects, please see the overall risk rating for undetected defects.

Inaccessible Areas

The following areas were inaccessible:

- Areas of low roof pitch

Findings Summary

The summary below is used to give a brief overview of observations made in each inspection area. The summary is NEVER to be relied upon as a comprehensive report and the client MUST read the entire report and not rely solely on this summary.

Property Inspection Report

Major Defect

Garage	Cracks in concrete slabs
All External Areas	Minor cracks category 2
All External Areas	Slope away water from foundations & Concrete paths recommended along perimeter
Bathroom	Bathroom waterproofing/leaks

Minor Defect

All External Areas	Fill the gaps
All External Areas	Fence
Roof exterior	Roof tile pointing
All External Areas	Loose gutter clips
All External Areas	Cracked concrete
Garage	Paintworks
All External Areas	Soil erosion
All Internal Areas	Cornice
Laundry	Install raven seal
Laundry	Stuck and moisture damaged doors
Bedroom 2	Plaster cracks
All Internal Areas	Damaged/leak windows

All Internal Areas	Skirting cracks
All Internal Areas	Damaged quads

For your information

All External Areas	ADDITIONAL EXTERNAL PHOTOS
All Internal Areas	ADDITIONAL INTERNAL PHOTOS
Bedroom 1	ADDITIONAL BEDROOM 1 PHOTOS
Bedroom 2	ADDITIONAL BEDROOM 2 PHOTOS
Bedroom 3	ADDITIONAL BEDROOM 3 PHOTOS
Bedroom 4	ADDITIONAL BEDROOM 4 PHOTOS
All Internal Areas	Smoke Detectors and Alarms
Roofspace	ADDITIONAL ROOFSPACE PHOTOS

Timber Pest Inspection Report

Conditions conducive to timber pest attack

All External Areas	Timber fence bridging
All External Areas	DURABLE NOTICE FOUND IN ELECTRIC METER BOX
All External Areas	Conducive synthetic against the house
All Internal Areas	Termite tapper used

Summary

SUMMARY INFORMATION: The summary below is used to give a brief overview of observations made in each inspection area. The items listed in the summary are noted in detail under the applicable sub headings within the body of the report. The summary is NEVER to be relied upon as a comprehensive report and the client MUST read the entire report and not rely solely on this summary. If there is a discrepancy between the information provided in this summary and that contained within the body of the Report, the information in the body of the Report shall override this summary. (See definitions & information below the summary to help understand the report)

Evidence of Serious Safety Hazard	**Not Found**
Evidence of Major Defect	**Found**
Evidence of Minor Defect	**Found**

Additional specialist inspections

It is Strongly Recommended that the following Inspections and Reports be obtained prior to any decision to purchase the Property and/or before settlement. Obtaining these reports will better equip the purchaser to make an informed decision.

- Structural engineer
- Structural engineer to access brick cracks around corner

Undetected defect risk assessment

Due to the level of accessibility for inspection including the presence of obstructions, the overall degree of risk of undetected structural damage and conditions conducive to structural damage was considered:

MODERATE - HIGH

A further inspection is strongly recommended of those areas that were not readily accessible and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This will involve a separate visit to the site, permission from the owner of the property and additional cost.

Unless stated otherwise, any recommendation or advice given in this Report should be implemented as a matter of urgency.

Significant Items

The following items and matters were reported on in accordance with the Scope of Inspection. For building elements not identified in this Condition Report, monitoring and normal maintenance must be carried out.

Serious Safety Hazard

No evidence was found

Major Defect

Major Defect 1.01

Location: Garage

Finding: Cracks in concrete slabs

The garage floor exhibits significant cracking, as illustrated in the images. These cracks may indicate underlying issues such as settlement or inadequate concrete mix. If left unaddressed, the damage could worsen and compromise the structural integrity of the floor. It is recommended to consult a structural engineer to assess the extent of the issue and implement appropriate repair measures, such as crack injection or floor slab replacement, to prevent further deterioration.

Cracks to slabs are defective where they are Category 3 and 4.
Category 1 and 2 cracks to slabs are to be monitored for a period of 12 months. At the end of the monitoring period, cracks are defective if they are greater than category 2 and attributed to the actions of the builder.
Refer to table 2.10 in Victorian Guide to Standards and Tolerances 2015

Major Defect 1.02

Location: All External Areas

Finding: Minor cracks category 2

The external walls exhibit notable vertical cracking, particularly at the junctions of brickwork. This defect may compromise structural integrity and could lead to water ingress, exacerbating potential deterioration. Remedial action is recommended, including consultation with a structural engineer to assess the extent of movement. Repairs should involve repointing the affected areas and implementing measures to prevent further shifting, such as underpinning or improved drainage, to ensure the property's long-term stability and safety.

AS 2870 Crack Categories

Category 0 – Hairline Cracks
- Crack width: < 0.1 mm
- Very fine, barely visible
- No structural concern
- Normal shrinkage

———

Category 1 – Fine Cracks
- Crack width: < 1 mm
- Easily filled with paint
- Cosmetic only
- No repair usually needed

———

Category 2 – Noticeable Cracks
- Crack width: 1–5 mm
- Doors/windows may stick slightly
- Can be repaired with filler
- Minor structural movement

……

Category 3 – Moderate Cracks
- Crack width: 5–15 mm
- Bricks may be displaced
- Doors/windows stick badly
- Service pipes may crack
- Structural repair required

———

Category 4 – Severe Cracks
- Crack width: 15–25 mm
- Significant wall distortion
- Major structural damage
- Extensive repair needed

———

Category 5 – Very Severe Cracks
- Crack width: > 25 mm
- Wall instability
- Risk of failure
- Major rebuilding required

14
13
12
11

Major Defect 1.03

Location: All External Areas

Finding: Slope away water from foundations & Concrete paths recommended along perimeter

In the All External Areas, the gravel levels are improperly graded, resulting in water pooling against the house. This condition poses a risk of water ingress and associated damage to the foundation and lower structural elements. It is recommended that the gravel be re-graded to ensure proper drainage, directing water to flow away from the property. Remedial action should include adjusting the surface gradient and potentially installing drainage solutions to prevent ongoing water accumulation adjacent to the residential structure.



Major Defect 1.04

Location: Bathroom

Finding: Bathroom waterproofing/leaks

The inspection of the bathroom revealed evidence of moisture intrusion at the base of the shower screen. The moisture meter indicated elevated readings, suggesting that water is escaping and compromising the surrounding materials. This condition may lead to further deterioration, such as mold growth or structural damage, if not addressed promptly. It is recommended to reseal the affected area and ensure proper waterproofing. Engaging a professional contractor to evaluate and rectify the waterproofing system is advised to prevent future occurrences.



Minor Defect

Minor Defect 2.01

Location: All External Areas

Finding: Fill the gaps

Recommended fill the gaps between roof tiles and eaves

Minor Defect 2.02

Location: All External Areas

Finding: Fence

The fences were not all in good order with some requiring maintenance works to be completed. An investigation (by a competent person e.g. a fencing contractor) is recommended to determine the method and extent of any remedial work required and associated costs.

Minor Defect 2.03

Location: Roof exterior

Finding: Roof tile pointing

Unless documented otherwise, the absence of pointing where required is defective.
Pointing is defective if it becomes dislodged or washed out.
The pointing is defective if it is not uniform in colour, texture and trowelled off to provide a neat appearance. The rectification of pointing shall match the existing colour and texture as close as practicable.

Minor cracking of pointing is not defective.

Minor Defect 2.04

Location: All External Areas

Finding: Loose gutter clips

During the inspection of the roof exterior, it was observed that several gutter clips were loose, which may compromise the efficiency of the guttering system in managing rainwater drainage. This defect poses a risk of water overflow and potential damage to the property's structure. It is recommended that a licensed roof plumber be engaged to secure the gutter clips properly. Ensuring that the gutter system is firmly attached will help maintain its functionality and prevent any associated water damage to the property.



Minor Defect 2.05

Location: All External Areas

Finding: Cracked concrete

Some cracking / deterioration was observed to sections of concrete paving recommend to replace where necessary as some of it has limited service life remaining. (Some photo examples following] Cracking in concrete is common and is not always attributable to unsatisfactory workmanship. Common causes of cracking include shrinkage stress, stress due to trees, commercial or heavy vehicle traffic, soil movement due to changes in the moisture content as a result of garden watering or drainage problems. Tripping hazards should be filled or ground flat for the safety of the home's occupants. An investigation (by a competent person e.g. a licensed concreting contractor) is recommended to determine the method and extent of any remedial work required, and associated costs.



Minor Defect 2.06

Location: Garage

Finding: Paintworks

The garage wall displays uneven paint patches, suggesting previous repairs or incomplete painting. This aesthetic inconsistency may not affect structural integrity but detracts from visual appeal. It is recommended to repaint the entire wall for uniformity, ensuring the patches are sanded smoothly prior to painting. This remedial action would enhance the overall appearance

and maintain the property's value.

Minor Defect 2.07

Location: All External Areas

Finding: Soil erosion

The external area exhibits significant soil erosion along the fence line, compromising structural integrity and potentially impacting drainage. This condition may lead to further destabilization of the fence and exacerbate water runoff issues. Remedial action involves regrading the affected area to promote proper water egress, and securing the fence with additional support to prevent future movement. It is advisable to consult a professional landscaping or structural expert to ensure the stability and longevity of the fence and surrounding terrain.

Minor Defect 2.08

Location: All Internal Areas

Finding: Cornice

The internal areas exhibit noticeable cracking at the ceiling joints, indicative of minor structural movement or settlement. This condition, observed across multiple sections, may lead to further deterioration if not addressed. It is recommended to engage a qualified building professional to assess the extent of the issue. Remedial action should include sealing the cracks with appropriate filler material followed by repainting. Continuous monitoring is advised to ensure no progression occurs, as well as to maintain the aesthetic and structural integrity of the property.



Minor Defect 2.09

Location: Laundry

Finding: Install raven seal

Recommended install raven seal





Minor Defect 2.10

Location: Laundry

Finding: Stuck and moisture damaged doors

The laundry door is observed to be stuck and exhibits visible damage, impairing its functionality and ease of use. This defect may lead to further wear if not addressed, potentially affecting the overall integrity and operation of the door. It is recommended that a qualified professional be engaged to assess the extent of the damage and perform necessary repairs or replacements to ensure the door functions properly and safely. Immediate attention to this issue will help maintain the utility and aesthetic appeal of the laundry area.



Minor Defect 2.11

Location: Bedroom 2

Finding: Plaster cracks

In Bedroom 2, minor cracking is evident on the wall adjacent to the window and on the ceiling near the ventilation unit. These cracks may be indicative of normal settlement or environmental factors affecting the property. It is recommended to monitor these cracks for any progression over time. As a remedial action, engaging a qualified builder to assess the structural integrity and, if necessary, performing minor cosmetic repairs such as filling and painting should be considered to prevent further issues.



Minor Defect 2.12

Location: All Internal Areas

Finding: Damaged/leak windows

Recommended improve the seals of windows for water leaks as water ingress makes conditions favourable for termites and further damage the structure.



Minor Defect 2.13

Location: All Internal Areas

Finding: Skirting cracks

The internal areas exhibit evidence of skirting board separation from the walls, as observed in multiple locations. This condition may be indicative of structural movement or poor installation practices. It is recommended that a qualified carpenter assesses the extent of the damage, reattaches the skirting boards with appropriate fixings, and applies caulking to seal any gaps to prevent further deterioration and maintain aesthetic integrity.

Minor Defect 2.14

Location: All Internal Areas

Finding: Damaged quads

The internal areas exhibit poorly fitted flooring with noticeable gaps and separation at the edges, indicating substandard installation or material contraction. This defect may lead to further deterioration and potential tripping hazards. It is recommended to engage a qualified contractor to refit and secure the flooring, ensuring appropriate expansion gaps are maintained to accommodate environmental changes and prevent future issues.

Additional comments

There are no additional comments

For your information

For your information 3.01

Location: All External Areas

Finding: ADDITIONAL EXTERNAL PHOTOS

These photos are an indication of the obstructions & limitations which impeded full inspection of the property at the time of inspection. The obstructions can hide an array of defects and should be removed to allow for a full inspection to be carried out. The inspection only covers readily accessible areas of the building and site. The inspection did not include inaccessible, not readily accessible and unsafe or obstructed areas. Obstructions are defined as any condition or physical limitation which inhabits or prevents inspection and may include but not limited to: bricks, hebel, render, claddings, paths, roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/ materials, thermal insulation, sarking, pipes, ducts, builders debris, vegetation, pavement, or earth.





Braemar





















Rinnai
B26

Rinnai
B26



For your information 3.02

Location: All Internal Areas

Finding: ADDITIONAL INTERNAL PHOTOS

These photos are an indication of the obstructions & limitations which impeded full inspection of the property at the time of inspection. The obstructions can hide an array of defects and should be removed to allow for a full inspection to be carried out. The inspection only covers readily accessible areas of the building and site. The inspection did not include inaccessible, not readily accessible and unsafe or obstructed areas. Obstructions are defined as any condition or physical limitation which inhabits or prevents inspection and may include but not limited to: bricks, hebel, render, claddings, paths, roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/ materials, thermal insulation, sarking, pipes, ducts, builders debris, vegetation, pavement, or earth.













Mondella
COLONIAL OAK
10 YEARS















































For your information 3.03

Location: Bedroom 1

Finding: ADDITIONAL BEDROOM 1 PHOTOS

These photos are an indication of the obstructions & limitations which impeded full inspection of the property at the time of inspection. The obstructions can hide an array of defects and should be removed to allow for a full inspection to be carried out. The inspection only covers readily accessible areas of the building and site. The inspection did not include inaccessible, not readily accessible and unsafe or obstructed areas. Obstructions are defined as any condition or physical limitation which inhabits or prevents inspection and may include but not limited to: bricks, hebel, render, claddings, paths, roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/ materials, thermal insulation, sarking, pipes, ducts, builders debris, vegetation, pavement, or earth.















For your information 3.04

Location: Bedroom 2

Finding: ADDITIONAL BEDROOM 2 PHOTOS

These photos are an indication of the obstructions & limitations which impeded full inspection of the property at the time of inspection. The obstructions can hide an array of defects and should be removed to allow for a full inspection to be carried out. The inspection only covers readily accessible areas of the building and site. The inspection did not include inaccessible, not readily accessible and unsafe or obstructed areas. Obstructions are defined as any condition or physical limitation which inhabits or prevents inspection and may include but not

limited to: bricks, hebel, render, claddings, paths, roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/ materials, thermal insulation, sarking, pipes, ducts, builders debris, vegetation, pavement, or earth.













For your information 3.05

Location: Bedroom 3

Finding: ADDITIONAL BEDROOM 3 PHOTOS

These photos are an indication of the obstructions & limitations which impeded full inspection of the property at the time of inspection. The obstructions can hide an array of defects and should be removed to allow for a full inspection to be carried out. The inspection only covers readily accessible areas of the building and site. The inspection did not include inaccessible, not readily accessible and unsafe or obstructed areas. Obstructions are defined as any condition or physical limitation which inhabits or prevents inspection and may include but not limited to: bricks, hebel, render, claddings, paths, roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/ materials, thermal insulation, sarking, pipes, ducts, builders debris, vegetation, pavement, or earth.



















For your information 3.06

Location: Bedroom 4

Finding: ADDITIONAL BEDROOM 4 PHOTOS

These photos are an indication of the obstructions & limitations which impeded full inspection of the property at the time of inspection. The obstructions can hide an array of defects and should be removed to allow for a full inspection to be carried out. The inspection only covers readily accessible areas of the building and site. The inspection did not include inaccessible, not readily accessible and unsafe or obstructed areas. Obstructions are defined as any condition or physical limitation which inhabits or prevents inspection and may include but not limited to: bricks, hebel, render, claddings, paths, roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/ materials, thermal insulation, sarking, pipes, ducts, builders debris, vegetation, pavement, or earth.











For your information 3.07

Location: All Internal Areas

Finding: Smoke Detectors and Alarms

Reporting on Smoke Detectors or Alarms, including hard wired smoke detection systems and their legislative requirements, is outside the Scope of this Report. Please note that this defect is highlighted as a caution only. We suspect, based on our experience in the building industry, that the absence of smoke detectors, or their poor condition, should be addressed as a matter of urgency to improve occupant safety. Additionally, it is advised that all smoke detectors be tested by the homeowner on a monthly basis. Please refer to AS3786 and state based legislation, which may also apply.



For your information 3.08

Location: Roofspace

Finding: ADDITIONAL ROOFSPACE PHOTOS

These photos are an indication of the obstructions & limitations which impeded full inspection of the property at the time of inspection. The obstructions can hide an array of defects and should be removed to allow for a full inspection to be carried out. The inspection only covers readily accessible areas of the building and site. The inspection did not include inaccessible, not readily accessible and unsafe or obstructed areas. Obstructions are defined as any condition or physical limitation which inhabits or prevents inspection and may include but not limited to: bricks, hebel, render, claddings, paths, roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/ materials, thermal insulation, sarking, pipes, ducts, builders debris, vegetation, pavement, or earth.



NATURAL GA


L GAS

Conclusion

Your attention is drawn to the advice contained in the Terms and Conditions of this Report including any special conditions or instructions that need to be considered in relation to this Report.

In the opinion of this Consultant:

The incidence of Major Defects in this property in comparison to the average condition of similar buildings of approximately the same age that have been reasonably well maintained was considered:

Average

The incidence of Minor Defects in this property in comparison to the average condition of similar buildings of approximately the same age that have been reasonably well maintained was considered:

Average

In conclusion, following the inspection of surface work in the readily accessible areas of the property, the overall condition of the building relative to the average condition of similar buildings of approximately the same age that have been reasonably well maintained was considered:

Average

Building consultant's summary

Structural movement in house
Recommended engineer

Recommended connect all exhausts to external air

Summary

SUMMARY INFORMATION: The summary below is used to give a brief overview of observations made in each inspection area. The items listed in the summary are noted in detail under the applicable sub headings within the body of the report. The summary is NEVER to be relied upon as a comprehensive report and the client MUST read the entire report and not rely solely on this summary. If there is a discrepancy between the information provided in this summary and that contained within the body of the Report, the information in the body of the Report shall override this summary. (See definitions & information below the summary to help understand the report)

Evidence of active (live) termites	**Not Found**
Evidence of termite activity (including workings) and/or damage	**Not Found**
Evidence of a possible previous termite management program	**Not Found**
Evidence of chemical delignification damage	**Not Found**
Evidence of fungal decay activity and/or damage	**Not Found**
Evidence of wood borer activity and/or damage	**Not Found**
Evidence of conditions conducive to timber pest attack	**Found**
Next inspection to help detect a future termite attack is recommended in	**1 Years**

Undetected timber pest defect risk assessment

Due to the level of accessibility for inspection including the presence of obstructions, the overall degree of risk of undetected timber pest attack and conditions conducive to timber pest attack was considered:

MODERATE - HIGH

A further inspection is strongly recommended of those areas that were not readily accessible and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This will involve a separate visit to the site, permission from the owner of the property and additional cost.

Unless stated otherwise, any recommendation or advice given in this Report should be implemented as a matter of urgency.

For further information including advice on how to help protect against financial loss due to timber pest attack.

Significant Items

The following items and matters were reported on in accordance with the Scope of Inspection. For building elements not identified in this Condition Report, monitoring and normal maintenance must be carried out.

Timber pest attack

ACTIVE (LIVE) TERMITES

Important Note. As a delay may exist between the time of an attack and the appearance of telltale signs associated with an attack, it is possible that termite activity and damage exists though not discernible at the time of inspection.

No evidence was found

TERMITE WORKINGS AND/OR DAMAGE

No evidence was found

CHEMICAL DELIGNIFICATION

No evidence was found

FUNGAL DECAY

No evidence was found

WOOD BORERS

No evidence was found

Conditions conducive to timber pest attack

LACK OF ADEQUATE SUBFLOOR VENTILATION

No evidence was found

THE PRESENCE OF EXCESSIVE MOISTURE

No evidence was found

BRIDGING OR BREACHING OF TERMITE MANAGEMENT SYSTEMS AND INSPECTION ZONES

No evidence was found

UNTREATED OR NON-DURABLE TIMBER USED IN A HAZARDOUS ENVIRONMENT

No evidence was found

OTHER CONDITIONS CONDUCIVE TO TIMBER PEST ATTACK

Conditions conducive to timber pest attack 4.01

Location: All External Areas

Finding: Timber fence bridging

In the course of inspecting all external areas, it was observed that the timber fence exhibits bridging, which may facilitate termite access and compromise structural integrity. Such bridging results from timber in direct contact with soil or other conducive conditions that promote pest infiltration. To mitigate the risk of termite infestation and ensure the longevity of the fence structure, it is recommended to create a physical barrier by elevating the timber components off the ground and maintaining a clear separation. Additionally, regular inspection and maintenance should be undertaken to monitor and address any future vulnerabilities.









Conditions conducive to timber pest attack 4.02

Location: All External Areas

Finding: DURABLE NOTICE FOUND IN ELECTRIC METER BOX

Yes, a durable notice was found in the electrical meter box during the inspection. there was visible evidence or a previous termite treatment was located at the property.
During inspection of the property, it was noted that termite protection work had previously been completed but looks out of warranty or check the warranty with builder.
Most chemical / termite management systems expire and require replenishment.
It is recommended to Always ask the Vendor and preferably get an answer in writing (because we on the day of the inspection don't know the property history), any information relating to past termite activity to the property prior to purchase. Has the property been subject to termite attack, is there any termite damage, has there been any termite treatment. Often termite damage is removed or concealed by renovations (if done skilfully even the best inspector cannot tell). If the owner gives you false and misleading answers, then in the event of discovery of defects you may have action for misrepresentation
CHECK ALL WARRANTIES WITH OWNER OR CALL THE COMPANY GIVEN ON STICKER.
IMPORTANT DO TERMITE TREATMENTS WITHIN 28 DAYS OF THE INSPECTION IF WARRANTY EXPIRED.





Conditions conducive to timber pest attack 4.03

Location: All External Areas

Finding: Conducive synthetic against the house

In the external areas of the property, the installation of synthetic grass is found to be conducive to termite activity due to its tendency to retain moisture. This environment creates conditions favorable for termites, increasing the risk of infestation. It is recommended that the synthetic grass be cut back by 500 mm from the building perimeter to mitigate this risk. Implementing this remedial action will help to reduce moisture levels near the structure, thereby decreasing the likelihood of termite colonization and safeguarding the structural integrity of the property.



Conditions conducive to timber pest attack 4.04

Location: All Internal Areas

Finding: Termite tapper used

During the course of the inspection, a termite tapper was used. The testing involved tapping accessible timber components to detect any hollowness that might indicate the presence of timber pests, such as termites. There were no signs of hollowness observed in any of the accessible areas, suggesting that there is no immediate evidence of termite activity within the internal environs of the premises.
While the current findings are correct at the time of inspection, it is recommended that as a precautionary measure,
regular inspections should be carried out at least annually, or more frequently in areas with a high risk of termite infestation. This will help in early detection and prevention of potential termite activity, which could lead to significant structural damage if left unchecked.
Furthermore, maintaining an environment that is not conducive to termite attraction, such as avoiding moisture accumulation near the foundation and ensuring that wood is not in direct contact with soil, will assist in reducing the risk of future termite problems. Additional measures might include professional application of termite prevention systems and treatments.





Serious Safety Hazards

No evidence of Serious Safety Hazards were found

For your information

SUBTERRANEAN TERMITE MANAGEMENT PROPOSAL

No evidence was found

PREVIOUS TERMITE MANAGEMENT PROGRAM

No evidence was found

Conclusion

Your attention is drawn to the advice contained in the Terms and Conditions of this Report including any special conditions or instructions that need to be considered in relation to this Report.

The following Timber Pest remediation actions are recommended:

1. No treatment of Timber Pest Attack is required.

2. In addition to this Report a Subterranean Termite Management Proposal to help manage the risk of future subterranean termite access to buildings and structures is recommended.

3. Yes - removal of Conditions Conducive to Timber Pest Attack is necessary.

4. Due to the susceptibility of the property to sustaining Timber Pest Attack the next inspection is recommended in 1 Years

Risk management options

To help protect against financial loss, it is essential that the building owner immediately control or rectify any evidence of destructive timber pest activity or damage identified in this Report. The Client should further investigate any high risk area where access was not gained. It is strongly advised that appropriate steps be taken to remove, rectify or monitor any evidence of conditions conducive to timber pest attack.

To help minimise the risk of any future loss, the Client should consider whether the following options to further protect their investment against timber pest infestation are appropriate for their circumstances:

Undertake thorough regular inspections at intervals not exceeding twelve months or more frequent inspections where the risk of timber pest attack is high or the building type is susceptible to attack. To further reduce the risk of subterranean termite attack, implement a management program in accordance with Australian Standard AS 3660. This may include the installation of a monitoring and/or baiting system, or chemical and/or physical management system. However, AS 3660 stresses that subterranean termites can bridge or breach management systems and inspection zones and that thorough regular inspections of the building are necessary.

If the Client has any queries or concerns regarding this Report, or the Client requires further information on a risk management program, please do not hesitate to contact the person who carried out this Inspection.

Definitions to help you better understand this report

——————— PROPERTY INSPECTION REPORT ———————

“Client” The person or persons, for whom the Inspection Report was carried out or their Principal (i.e. the person or persons for whom the report is being obtained).

“Building Consultant” A person, business or company who is qualified and experienced to undertake a pre-purchase inspection in accordance with Australian Standard AS 4349.1-2007 ‘Inspection of Buildings. Part 1: Pre-Purchase Inspections – Residential Buildings’. The consultant must also meet any Government licensing requirement, where applicable.

“Building and Site” The inspection of the nominated residence together with relevant features including any car accommodation, detached laundry, ablution facilities and garden sheds, retaining walls more than 700 mm high, paths and driveways, steps, fencing, earth, embankments, surface water drainage and stormwater run-off within 30 m of the building, but within the property boundaries.

“Readily Accessible Areas” Areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels or accessible from a 3.6 metre ladder, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. Or where these clearances are not available, areas within the consultant’s unobstructed line of sight and within arm’s length.

“Structure” The loadbearing part of the building, comprising the Primary Elements.

“Primary Elements” Those parts of the building providing the basic loadbearing capacity to the Structure, such as foundations, footings, floor framing, loadbearing walls, beams or columns. The term ‘Primary Elements’ also includes other structural building elements including: those that provide a level of personal protection such as handrails; floor-to-floor access such as stairways; and the structural flooring of the building such as floorboards.

“Structural Damage” A significant impairment to the integrity of the whole or part of the Structure falling into one or more of the following categories:

(a) Structural Cracking and Movement – major (full depth) cracking forming in Primary Elements resulting from differential movement between or within the elements of construction, such as foundations, footings, floors, walls and roofs.

(b) Deformation – an abnormal change of shape of Primary Elements resulting from the application of load(s).

(c) Dampness – the presence of moisture within the building, which is causing consequential damage to Primary Elements.

(d) Structural Timber Pest Damage – structural failure, i.e. an obvious weak spot, deformation or even collapse of timber Primary Elements resulting from attack by one or more of the following wood destroying agents: chemical delignification; fungal decay; wood borers; and termites.

“Conditions Conducive to Structural Damage” Noticeable building deficiencies or environmental factors that may contribute to the occurrence of Structural Damage.

“Secondary Elements” Those parts of the building not providing loadbearing capacity to the Structure, or those non-essential elements which, in the main, perform a completion role around openings in Primary Elements and the building in general such as non-loadbearing walls, partitions, wall linings, ceilings, chimneys, flashings, windows, glazing or doors.

“Finishing Elements” The fixtures, fittings and finishes applied or affixed to Primary Elements and Secondary Elements such as baths, water closets, vanity basins, kitchen cupboards, door furniture, window hardware, render, floor and wall tiles, trim or paint. The term ‘Finishing Elements’ does not include furniture or soft floor coverings such as carpet and

tiles, trim or paint. The term ‘Finishing Elements’ does not include furniture or soft floor coverings such as carpet and lino.

“Major Defect” A defect of significant magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.

“Minor Defect” A defect other than a Major Defect.

“Serious Safety Hazard” Any item that may constitute an immediate or imminent risk to life, health or property. Occupational, health and safety or any other consequence of these hazards has not been assessed.

“Tests” Where appropriate the carrying out of tests using the following procedures and instruments:
(a) Dampness Tests means additional attention to the visual examination was given to those accessible areas which the consultant’s experience has shown to be particularly susceptible to damp problems. Instrument testing using electronic moisture detecting meter of those areas and other visible accessible elements of construction showing evidence of dampness was performed.

(b) Physical Tests means the following physical actions undertaken by the consultant: opening and shutting of doors, windows and draws; operation of taps; water testing of shower recesses; and the tapping of tiles and wall plaster."

———————- TIMBER PEST INSPECTION REPORT ———————

“Timber Pest Attack” Timber Pest Activity and/or Timber Pest Damage.

“Timber Pest Activity” Telltale signs associated with ‘active’ (live) and/or ‘inactive’ (absence of live) Timber Pests at the time of inspection.

“Timber Pest Damage” Noticeable impairments to the integrity of timber and other susceptible materials resulting from attack by Timber Pests.

“Major Safety Hazard” Any item that may constitute an immediate or imminent risk to life, health or property resulting directly from Timber Pest Attack. Occupational, health and safety or any other consequence of these hazards has not been assessed.

“Conditions Conducive to Timber Pest Attack” Noticeable building deficiencies or environmental factors that may contribute to the presence of Timber Pests.

“Readily Accessible Areas” Areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels or accessible from a 3.6 metre ladder, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. The term ‘readily accessible’ also includes:
(a) accessible subfloor areas on a sloping site where the minimum clearance is not less than 150 mm high, provided that the area is not more than 2 metres from a point with conforming clearance (i.e. 400 mm high by 600 mm wide); and
(b) areas at the eaves of accessible roof spaces that are within the consultant’s unobstructed line of sight and within arm’s length from a point with conforming clearance (i.e. 600 mm high by 600 mm wide).

“Client” The person or persons for whom the Timber Pest Report was carried out or their Principal (i.e. the person or persons for whom the report was being obtained).

“Timber Pest Detection Consultant” A person who meets the minimum skills requirement set out in the current Australian Standard AS 4349.3 Inspections of Buildings. Part 3: Timber Pest Inspection Reports or state/territory legislation requirements beyond this Standard, where applicable.

“Building and Site” The main building (or main buildings in the case of a building complex) and all timber structures (such as outbuildings, landscaping, retaining walls, fences, bridges, trees and stumps with a diameter greater than 100 mm and timber embedded in soil) and the land within the property boundaries up to a distance of 50 metres from the main building(s).

“Timber Pests” One or more of the following wood destroying agents which attack timber in service and affect its

"Timber Pests" One or more of the following wood destroying agents which attack timber in service and affect its structural properties:
(a) Chemical Delignification - the breakdown of timber through chemical action
(b) Fungal Decay - the microbiological degradation of timber caused by soft rot fungi and decay fungi, but does not include mould, which is a type of fungus that does not structurally damage wood.
(c) Wood Borers - wood destroying insects belonging to the order 'Coleoptera' which commonly attack seasoned timber.
(d) Termites - wood destroying insects belonging to the order 'Isoptera' which commonly attack seasoned timber.

"Tests" Additional attention to the visual examination was given to those accessible areas which the consultant's experience has shown to be particularly susceptible to attack by Timber Pests. Instrument Testing of those areas and other visible accessible timbers/materials/areas showing evidence of attack was performed.

"Instrument Testing" Where appropriate the carrying out of Tests using the following techniques and instruments:
(a) electronic moisture detecting meter - an instrument used for assessing the moisture content of building elements;
(b) stethoscope - an instrument used to hear sounds made by termites within building elements;
(a) probing - a technique where timber and other materials/areas are penetrated with a sharp instrument (e.g. bradawl or pocket knife), but does not include probing of decorative timbers or finishes, or the drilling of timber and trees; and
(d) sounding - a technique where timber is tapped with a solid object.

"Subterranean Termite Management Proposal" A written proposal in accordance with Australian Standard AS 3660.2 to treat a known subterranean termite infestation and/or manage the risk of concealed subterranean termite access to buildings and structures.

Terms on which this report was prepared

———————- PROPERTY INSPECTION REPORT ———————

Service

1. This agreement is between the building consultant ("Inspector") and you ("Client"). You have requested the Inspector to carry out an inspection of your property for the purpose of preparing a Standard Property Report ("Report") to you outlining their findings and recommendation from the inspection.

2. The purpose of the inspection is to provide the Client with an overview of the Inspector's findings at the time of the inspection and advice as to the nature and extent of their findings.

3. This Report has been prepared at the direction of and exclusively for the Client. Details contained within this Report are tailored to the Pre-Inspection Agreement between the Inspector and the Client at the time of the Inspection and no other party can rely on the Report nor is the Report intended for any other party.

Scope of the Report

4. This Report is limited to the findings of the of the Inspector at the time of the inspection and any condition of the property which is not within the scope as set out herein or which occurs after the inspection is expressly excluded from this Report.

5. This Report expressly addresses only the following discernible to the Inspector at the time of inspection:
(a) Major Defects in the condition of Primary Elements including Structural Damage and Conditions Conducive to Structural Damage;
(b) any Major Defect in the condition of Secondary Elements and Finishing Elements and collective (but not individual) Minor Defects; and
(c) any Serious Safety Hazard.

6. This Report is limited to the observations and conclusions of the Inspector that were readily observable at the

6. This Report is limited to the observations and conclusions of the Inspector that were readily observable at the building or site and given the state of property at the time of the Inspection.

7. This Report does not include the inspection and assessment of items or matters that are beyond the Inspectors direct expertise.

Inspection Limitations

8. The Inspection is limited to Readily Accessible Areas of the Building & Site based on the Inspector's visual examination of surface work (excluding furniture and stored items) and the carrying out of Tests.

9. Where the Inspection is carried out on a strata or company title property, the Inspection is limited to the interior and the immediate exterior of the residence inspected. The Inspection does not extend to common property areas and the Inspector will not inspect common property areas.

10. The Inspector's findings do not extend to matters where the Inspector was restricted or prevented from assessing the building or site as a result of:
(a) possible concealment of defects, including but not limited to, defects concealed by lack of accessibility, obstructions such as furniture, wall linings and floor coverings, or by applied finishes such as render and paint;
(b) undetectable or latent defects, including but not limited to, defects that may not be apparent at the time of inspection due to seasonal changes, recent or prevailing weather conditions, and whether or not services have been used some time prior to the inspection being carried out; and
(c) areas of the building or site that were obstructed at the time of the inspection or not Readily Accessible Areas of the Building Site. An obstruction may include a condition or physical limitation which inhibits or prevents inspection and may include – but are not limited to – roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth.

Exclusions

11. This Report does not consider or deal with the following:
(a) any individual Minor Defect;
(b) solving or providing costs for any rectification or repair work;
(c) the structural design or adequacy of any element of construction;
(d) detection of wood destroying insects such as termites and wood borers;
(e) the operation of fireplaces and chimneys;
(f) any services including building, engineering (electronic), fire and smoke detection or mechanical;
(g) lighting or energy efficiency;
(h) any swimming pools and associated pool equipment or spa baths and spa equipment or the like;
(i) any appliances or white goods including dishwashers, refrigerators, ovens, stoves and ducted vacuum systems;
(j) a review of occupational, health or safety issues such as asbestos content, the provision of safety glass or the use of lead based paints;
(k) a review of environmental or health or biological risks such as toxic mould;
(l) whether the building complies with the provisions of any building Act, code, regulation(s) or by-laws;
(m) whether the ground on which the building rests has been filled, is liable to subside, swell or shrink, is subject to landslip or tidal inundation, or if it is flood prone; and
(n) in the case of strata and company title properties, the inspection of common property areas or strata/company records.

12. Should the Client seek information from the Inspector related to one of exclusions above, that information is to be provided by way of a Special-Purpose Inspection Report which is adequately specified and must be undertaken by an appropriately qualified inspector. Additional information requested by the Client is not included in this Report.

Workplace Safety

13. The Client warrants to the Inspector (including the Inspector's, agents, employees and other personnel) that the Building Site is, to the Client's reasonable knowledge, safe and free of hazardous materials and that no party of the Building site constitutes a dangerous environment or work place safety concern.

Acceptance Criteria

14. The Inspector may compare the building being inspected with a similar building, unless specified otherwise in the

14. The Inspector may compare the building being inspected with a similar building, unless specified otherwise in the Special Conditions or Instructions. The similar building which the Inspector may compare the current building to was, to the best of the Inspector's knowledge, constructed in accordance with ordinary building construction and maintenance practices at the time of construction and as such has not encountered significant loss or of strength or serviceability.

15. The Inspector assumes in their Report that the existing use of the building or site will continue unless specified otherwise in the Special Conditions or Instructions.

Acknowledgments

16. The Client Acknowledges that contents of the Report is subject to the Scope of the Report, Inspection Limitations, Exclusions and Acceptance Criteria. This Report does not include recommendations or advice about matters outside the scope of the requested inspection.

17. Should the Client have any queries or concerns about the purposes, scope or acceptance criteria on which this Report was prepared, all enquiries or concerns are to be discussed with the Inspector within a reasonable time upon receipt of this report.

18. The Client acknowledges that they will take all reasonable steps to implement any recommendation or advice provided by the Inspector in their Report as a matter of urgency specified otherwise.

19. Any further discussions the Inspector following the production of this Report addressing concerns will not be reflected in this Report and as such the Report may not contain all advice or information related to the building or site provided by the Inspector.

20. The Client acknowledges that a visual only inspection restricts the Inspectors capacity to inspect the building or site thoroughly and is not recommended by the Inspector unless an inspection of the Readily Accessible Areas and appropriate tests are also carried out.

21. The Client Acknowledges that in accordance with the Australian Standard AS4349.0 2007 Inspection of Buildings, this Report does not warrant or give insurance that the building or site from developing issues following the date of inspection.

22. The Client acknowledges that the Inspector is not affiliated with Hello Inspections Pty Ltd ACN 620 518 238 ("Hello Inspections") nor is Hello Inspections liable for the content of the Report prepared by the Inspector or any other third party and the Client hereby indemnifies Hello Inspections from all claims, losses and damage arising, either directly or indirectly, from the Report and the Client accepts this document can be presented to a court as a complete bar to any proceedings by the client or its agents or related parties against Hello Inspections. The Client further acknowledges the Inspector is the agent for Hello Inspections solely for the purposes of this clause.

23. The Client acknowledges that Hello Inspections may reproduce the content within this Report for any commercial purpose, including sale of the Report in whole or in part to third parties, provided personal details or information of the Client contained therein are excluded.

——————— TIMBER PEST INSPECTION REPORT ——————

Service

1. This agreement is between the Timber Pest Detection Consultant ("the Inspector") and you ("Client"). You have requested the Inspector to carry out an inspection of your property for the purpose of preparing a Pre-Purchase Standard Timber Pest Report ("Report") to you outlining their findings and recommendations from the inspection.

2. The purpose of the inspection is to provide the Client with an overview of the Inspector's findings at the time of inspection which includes whether the inspector has identified any Timber Pest issues and advice as to the nature and extent of those findings.

3. This Report has been prepared at the direction of and exclusively for the Client. Details contained within this Report are tailored to the Pre-Inspection Agreement between the Inspector and the Client at the time of the Inspection and no other party can rely on the Report nor is the Report intended for any other party.

Scope of this Report

other party can rely on the Report nor is the Report intended for any other party.

Scope of this Report

4. This Report is limited to the findings of the Inspector at the time of the inspection and any condition of the property which is not within the scope as set out herein or which occurs after the inspection is expressly excluded from this Report.

5. This Report expressly addresses only the detection or non-detection of Timber Pest Attack and Conditions Conducive to Timber Pest Attack discernible to the Inspector at the time of inspection.

6. This Report is limited to the observations and conclusions of the Inspector that were readily observable at the building or site and given the state of property at the time of the Inspection.

Inspection Limitations

7. The Inspection is limited to Readily Accessible Areas of the Building & Site based on the Inspector's visual examination of surface work (excluding furniture and stored items) and the carrying out of Tests.

8. Where the Inspection is carried out on a strata or company title property, the Inspection is limited to the interior and the immediate exterior of the residence inspected. The Inspection does not extend to common property areas and the Inspector will not inspect common property areas.

9. The Inspection is not in respect of a particular type of timber pest. Any analysis of a specific timber pest is to be at the request of the Client in which the Inspector would present their findings in a Special-Purpose Inspection Report separate from this Report.

10. The Inspector's findings do not extend to matters where the Inspector was restricted or prevented from assessing the building or site as a result of:
(a) possible concealment of timber pest attack, including but not limited to, timber pest attack concealed by lack of accessibility, obstructions such as furniture, wall linings and floor coverings, or by applied finishes such as render and paint;
(b) undetectable or latent timber pest attack, including but not limited to, timber pest attack that may not be apparent at the time of inspection due to seasonal changes, recent or prevailing weather conditions, and whether or not services have been used some time prior to the inspection being carried out;
(c) areas of the building or site that were obstructed at the time of the inspection or not Readily Accessible Areas of the Building Site. An obstructions may include a condition or physical limitation which inhibits or prevents inspection and may include – but are not limited to – roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth;

Exclusions

11. This Report does not consider or deal with the following:
(a) any information or advice related to timber pest preventative, treatment, rectification, or maintenance options for an attack by Timber Pests; and
(b) an environmental risk assessment or biological risk associated with Timber Pests (e.g. toxic mould), occupational health and safety issues.

12. Should the Client seek information from the Inspector related to one of exclusions above, that information is to be provided by way of a Special-Purpose Inspection Report or management proposal which is adequately specified and must be undertaken by an appropriately qualified inspector. Additional information requested by the Client is not included in this Report.

Workplace Safety

13. The Client warrants to the Inspector (including the Inspector's, agents, employees and other personnel) that the Building Site is, to the Client's reasonable knowledge, safe and free of hazardous materials and that no party of the Building site constitutes a dangerous environment or work place safety concern.

Acceptance Criteria

Acceptance Criteria

14. The Inspector may compare the building being inspected with a similar building, unless specified otherwise in the Special Conditions or Instructions. The similar building which the Inspector may compare the current building to was, to the best of the Inspectors knowledge, constructed in accordance with ordinary timber pest management and maintenance practices that ensure it does not attract or support a timber pest infestation during its life.

15. The Inspector assumes in their Report that the existing use of the building or site will continue unless specified otherwise in the Special Conditions or Instructions.

16. The Inspector does not guarantee or warrant the absence of Timber Pests in their Report. The Client acknowledges that certain species may be more difficult to identify than others or require regular inspection or testing to help monitor infestation of the species or susceptibility of the timber, including but not limited to the following species:
(a) Drywood termites. This species has extremely small colonies and is difficult to detect; and
(b) European House Borer (Hylotrupes bajulus). It is difficult to detect an attack or infestation of this species as the galleries of boring larvae rarely break through the affected timber surface.

Acknowledgements

17. The Client acknowledges that the contents of the Report is subject to the Scope of the Report, Inspection Limitations, Exclusions and Acceptance Criteria. This Report does not include recommendations or advice about matters outside the scope of the requested inspection.

18. The Client acknowledges that this Report does not assess the structural integrity of the building or site.

19. Should the Client have any queries or concerns about the purposes, scope or acceptance criteria on which this Report was prepared, all enquiries or concerns are to be discussed with the Inspector within a reasonable time upon receipt of this report.

20. The Client acknowledges that they will take all reasonable steps to implement any recommendation or advice provided by the Inspector in their Report as a matter of urgency unless specified otherwise.

21. Any further discussions the Inspector following the production of this Report addressing concerns will not be reflected in this Report and as such the Report may not contain all advice or information related to the building or site provided by the Inspector.

22. The Client acknowledges that the Inspector is not affiliated with Hello Inspections Pty Ltd ACN 620 518 238 (“Hello Inspections”) nor is Hello Inspections liable for the content of the Report prepared by the Inspector or any other third party and the Client hereby indemnifies Hello Inspections from all claims, losses and damage arising, either directly or indirectly, from the Report and the Client accepts this document can be presented to a court as a complete bar to any proceedings by the client or its agents or related parties against Hello Inspections. The Client further acknowledges the Inspector is the agent for Hello Inspections solely for the purposes of this clause.

23. The Client acknowledges that Hello Inspections may reproduce the content within this Report for any commercial purpose, including sale of the Report in whole or in part to third parties, provided personal details or information of the Client contained therein are excluded.