



Cut for input shaft hole: d(input) = 0.125in. 1in from the center y axis.




Big gear:


48	1"	1.04"	1/8"	0.63"	0.25"	Round Bore	1/4"	—	—	—	Brass


Small gear:

18	3/8"	0.42"	1/8"	0.28"	0.19"	Round Bore	1/8"	—	—	—	Brass


1.04" /2 + 0.42" /2 = **0.73 inches** R1 + R2 = distance of input shafts




Cut-Extrude1




In assembly, gears touching but not meshing




Adjusted the distance between centers of shafts by 0.03 to allow teeth to mesh.




Input and outshaft length = 5in
d(input) = ⅛”, d(output) = ¼”




Assembly with input shafts




Assembly with journal bearing and shafts attached.




Cover for gear box.



Full gear box



Bearing input shaft



Bearing output shaft