




6조 중간보고서 1

- 목표 - 온습도 센서의 하드웨어 연결과 온습도 값 받아오기

- 센서 연결에 필요한 핀



데이터핀 = ext_gpio0 = 핀번호 24

Dht22 센서에서 받은 온/습도 값을

Ext_gpio0 데이터핀을 통해 전송하여 2초마다 루프를 진행해 출력

- 실행 코드 - dht_display_1.py

```
dht_display_1.py X
C:\Users\82104 > OneDrive > 바탕 화면 > dht_display_1.py > ...

1  import adafruit_dht
2  import board
3  import time
4  import sys
5
6  sensor = adafruit_dht.DHT22(board.D14)
7
8  try:
9      while True:
10         try:
11             temperature = sensor.temperature
12             humidity = sensor.humidity
13
14             if temperature is not None and humidity is not None:
15                 print(f"Temp: {temperature:.1f}°C Humidity: {humidity:.1f}%")
16             else:
17                 print("Sensor returned None. Retrying...")
18
19         except RuntimeError as e:
20             print(f"Sensor error: {e}. Retrying...")
21
22         except OverflowError as e:
23             print(f"Overflow error: {e}. Resetting sensor...")
24             time.sleep(2)
25             continue
26
27         except Exception as e:
28             print(f"Unexpected error: {e}")
29             sensor.exit()
30             sys.exit(1)
31
32         time.sleep(2)
33
34 except KeyboardInterrupt:
35     print("Program stopped.")
36     sensor.exit()
37
```

- 실행화면

