



Jimmy Hu <jimmy.hu@gmail.com>

Fwd: From Hyundai Service

8 messages

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <JIMMY.HU@gmail.com>

Fri, Jan 9, 2026 at 5:55 PM

----- Forwarded message -----
From: <hyuservicescan@rt4cars.com>
Date: Fri, Jan 9, 2026 at 5:54 PM
Subject: From Hyundai Service
To: <cmavrianos@rt4cars.com>

 **SHyundai Se26010917440.pdf**
83K

Jimmy Hu <jimmy.hu@gmail.com>
To: Constantinos Mavrianos <cmavrianos@rt4cars.com>

Sun, Jan 18, 2026 at 10:41 PM

Dear Constantinos and Vivian,

Thank you for the clarification regarding the historical codes.

I understand your technician sees the **Active Radar Codes (C188186)** and suspects this damage is causing a parasitic drain on the 12V battery.

I am writing to streamline the repair plan for my vehicle (2024 Hyundai Ioniq 5, VIN ending in KM8KNDDF9RU253237) and avoid unnecessary diagnostic time.

Based on a separate inspection by Mizzoni's Auto Body, we have already identified that the **Right Headlamp Assembly (Part #92102GI050)** has physical damage to the housing. This damage is allowing environmental debris to obscure the sensors, which triggers the "Check Headlight" and "Forward Safety" warnings.

Because the root cause is a known physical defect (broken housing) rather than an electrical failure, I do not authorize further electrical diagnostics on the headlight system.

I propose two paths forward to resolve this immediately:

Option 1: Replacement Only (No Diagnostics) You proceed with replacing the Right Headlamp Assembly (Part #92102GI050) to resolve the safety sensor codes.

- **Condition:** We skip the "diagnostic" fees. I am instructing you to replace a broken part, not search for a problem.
- Once the broken part has been replaced, your technician can continue troubleshooting if the vehicle still has issues.

Option 2: Recall/Drivability Repair Only You focus solely on the **ICCU/12V Battery Recall (NHTSA 24V868000)** to ensure the vehicle is drivable and the 12V battery charges correctly.

- Once the vehicle is drivable, I will retrieve it and have the headlight assembly replaced at Mizzoni's Auto Body directly.
- **Note:** If the battery drain persists but the car can be jump-started or hold a charge long enough for transport, I am willing to take the vehicle in that condition to the body shop, and then bring it back for your technician to continue

troubleshooting if the vehicle still has issues.

My priority is the most expeditious and cost-efficient solution. Please let me know which option you can accommodate so we can move forward today.

Sincerely,

-Jimmy Y. Hu
jimmy.hu@gmail.com | 215-307-5492

[Quoted text hidden]

 **Headlight Estimate.pdf**
81K

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Mon, Jan 19, 2026 at 10:41 AM

I could just replace the headlight if that is what you want but we are not responsible if that does not fix your issue and also the price is not the same there labor rate is not the same. To replace the headlight you are looking at \$2590.10 plus taxes and shop charge. Let me know if you want us to move forward with the repair and if you do i will need the parts paid upfront in order to order them.

[Quoted text hidden]

Jimmy Hu <jimmy.hu@gmail.com>
To: Constantinos Mavrianos <cmavrianos@rt4cars.com>

Tue, Jan 20, 2026 at 2:01 PM

Progressive uses Mizsoni's Auto Body as their preferred repair shop in the area. Perhaps they have a lower contracted rate compared to the Hyundai parts?
If the car is now able to hold a charge long enough to drive 50 miles, I can bring it to Mizsoni's auto body shop tomorrow.

-Jimmy Y. Hu
jimmy.hu@gmail.com | 215-307-5492

[Quoted text hidden]

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Tue, Jan 20, 2026 at 2:07 PM

I can't tell you that i don't know what i would say call progressive and have them tow it.

[Quoted text hidden]

Jimmy Hu <jimmy.hu@gmail.com>
To: Constantinos Mavrianos <cmavrianos@rt4cars.com>

Wed, Jan 21, 2026 at 12:33 PM

If the radar is presumably draining the battery, the car would still charge, turn on and drive a short distance, correct?

-Jimmy Y. Hu
jimmy.hu@gmail.com | 215-307-5492

[Quoted text hidden]

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Wed, Jan 21, 2026 at 12:35 PM

like i said i can't tell you that it is i can't guarantee that not sure we were never in this situation.

[Quoted text hidden]

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Wed, Jan 21, 2026 at 12:36 PM

But i do need you to come to and pick up the vehicle if we are not doing the work i can't store the vehicle here.

[Quoted text hidden]



Jimmy Hu <jimmy.hu@gmail.com>

Fwd: From Hyundai Service

8 messages

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <JIMMY.HU@gmail.com>

Fri, Jan 9, 2026 at 5:55 PM

----- Forwarded message -----
From: <hyuservicescan@rt4cars.com>
Date: Fri, Jan 9, 2026 at 5:54 PM
Subject: From Hyundai Service
To: <cmavrianos@rt4cars.com>

 **SHyundai Se26010917440.pdf**
83K

Jimmy Hu <jimmy.hu@gmail.com>
To: Constantinos Mavrianos <cmavrianos@rt4cars.com>

Sun, Jan 18, 2026 at 10:41 PM

Dear Constantinos and Vivian,

Thank you for the clarification regarding the historical codes.

I understand your technician sees the **Active Radar Codes (C188186)** and suspects this damage is causing a parasitic drain on the 12V battery.

I am writing to streamline the repair plan for my vehicle (2024 Hyundai Ioniq 5, VIN ending in KM8KNDDF9RU253237) and avoid unnecessary diagnostic time.

Based on a separate inspection by Mizzoni's Auto Body, we have already identified that the **Right Headlamp Assembly (Part #92102GI050)** has physical damage to the housing. This damage is allowing environmental debris to obscure the sensors, which triggers the "Check Headlight" and "Forward Safety" warnings.

Because the root cause is a known physical defect (broken housing) rather than an electrical failure, I do not authorize further electrical diagnostics on the headlight system.

I propose two paths forward to resolve this immediately:

Option 1: Replacement Only (No Diagnostics) You proceed with replacing the Right Headlamp Assembly (Part #92102GI050) to resolve the safety sensor codes.

- **Condition:** We skip the "diagnostic" fees. I am instructing you to replace a broken part, not search for a problem.
- Once the broken part has been replaced, your technician can continue troubleshooting if the vehicle still has issues.

Option 2: Recall/Drivability Repair Only You focus solely on the **ICCU/12V Battery Recall (NHTSA 24V868000)** to ensure the vehicle is drivable and the 12V battery charges correctly.

- Once the vehicle is drivable, I will retrieve it and have the headlight assembly replaced at Mizzoni's Auto Body directly.
- **Note:** If the battery drain persists but the car can be jump-started or hold a charge long enough for transport, I am willing to take the vehicle in that condition to the body shop, and then bring it back for your technician to continue

troubleshooting if the vehicle still has issues.

My priority is the most expeditious and cost-efficient solution. Please let me know which option you can accommodate so we can move forward today.

Sincerely,

-Jimmy Y. Hu
jimmy.hu@gmail.com | 215-307-5492

[Quoted text hidden]

 **Headlight Estimate.pdf**
81K

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Mon, Jan 19, 2026 at 10:41 AM

I could just replace the headlight if that is what you want but we are not responsible if that does not fix your issue and also the price is not the same there labor rate is not the same. To replace the headlight you are looking at \$2590.10 plus taxes and shop charge. Let me know if you want us to move forward with the repair and if you do i will need the parts paid upfront in order to order them.

[Quoted text hidden]

Jimmy Hu <jimmy.hu@gmail.com>
To: Constantinos Mavrianos <cmavrianos@rt4cars.com>

Tue, Jan 20, 2026 at 2:01 PM

Progressive uses Mizzone's Auto Body as their preferred repair shop in the area. Perhaps they have a lower contracted rate compared to the Hyundai parts?
If the car is now able to hold a charge long enough to drive 50 miles, I can bring it to Mizzone's auto body shop tomorrow.

-Jimmy Y. Hu
jimmy.hu@gmail.com | 215-307-5492

[Quoted text hidden]

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Tue, Jan 20, 2026 at 2:07 PM

I can't tell you that i don't know what i would say call progressive and have them tow it.

[Quoted text hidden]

Jimmy Hu <jimmy.hu@gmail.com>
To: Constantinos Mavrianos <cmavrianos@rt4cars.com>

Wed, Jan 21, 2026 at 12:33 PM

If the radar is presumably draining the battery, the car would still charge, turn on and drive a short distance, correct?

-Jimmy Y. Hu
jimmy.hu@gmail.com | 215-307-5492

[Quoted text hidden]

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Wed, Jan 21, 2026 at 12:35 PM

like i said i can't tell you that it is i can't guarantee that not sure we were never in this situation.

[Quoted text hidden]

Constantinos Mavrianos <cmavrianos@rt4cars.com>
To: Jimmy Hu <jimmy.hu@gmail.com>

Wed, Jan 21, 2026 at 12:36 PM

But i do need you to come to and pick up the vehicle if we are not doing the work i can't store the vehicle here.

[Quoted text hidden]



KM8KNDDF9RU253237

BB8AANJ0332601080341

01/08/26 12:50



Smart Diagnosis



KM8KNDDF9RU253237
B28AANJ0332601080341

IONIQ 5 (NE EV)/2024/70KW+160KW



System Status

7

ECU Upgrade

Vehicle Information

Mapping Status



Not Supported

All DTC(5 System, 7 DTCs)

(See video)

Powertrain Chassis Body

SYSTEM / DTC CODE DESCRIPTION

State

VCMS | Vehicle Charging Management System
PIB4D92 Battery Charger Coupler Temperature too High

History

ABSESC | ABS/ESC
C110213 Battery Voltage Low


ADAS_DRV | ADAS Driving ECU
C188186 FR/RR_C_RDR Signal Error Fault

C_RADAR | Coupler Radar
C270754 Control Module Missing Calibration (Front Right)

ICU | Integrated Central Control Unit
B235300 Dedicated DRL RH SCG

ICU | Integrated Central Control Unit
B258A00 External Tail Lamp Front Right Circuit Short to Ground

ICU | Integrated Central Control Unit
C162800 CAN Time-Out CLU



These are the codes in the system we need 4 hours of diagnosis \$1040 of diagnose the vehicle IN order to see what else the vehicle needs.



Rescan



Erase all DTC



Report

S/W Ver.

NNH-02-0102

VCI Ver.

03.25

Res Ver.

NNH-02-000A

OS Ver.



KM8KND9F9RU253237

BB8AANJ0332601080341

01/08/26 12:50



Smart Diagnosis



KM8KND9F9RU253237
B28AANJ0332601080341

IONIQ 5 (NE EV)/2024/70KW+160KW



System Status

7

ECU Upgrade

Vehicle Information

Mapping Status

0



Not Supported

All DTC(5 System, 7 DTCs)

(See video)

Powertrain Chassis Body

SYSTEM / DTC CODE DESCRIPTION

State

VCMS | Vehicle Charging Management System
PIB4D92 Battery Charger Coupler Temperature too High

History

ABSESC | ABS/ESC
C110213 Battery Voltage Low


ADAS_DRV | ADAS Driving ECU
C188186 FR/RR_C_RDR Signal Error Fault

C_RADAR | Coupler Radar
C270754 Control Module Missing Calibration (Front Right)

ICU | Integrated Central Control Unit
B235300 Dedicated DRL RH SCG

ICU | Integrated Central Control Unit
B258A00 External Tail Lamp Front Right Circuit Short to Ground

ICU | Integrated Central Control Unit
C162800 CAN Time-Out CLU



These are the codes in the system we need 4 hours of diagnosis \$1040 of diagnose the vehicle IN order to see what else the vehicle needs.



Rescan



Erase all DTC



Report

S/W Ver.

NNH-02-0102

VCI Ver.

03.25

Res Ver.

NNH-02-000A

OS Ver.