Inspection Summary & Finding 01

Purpose: test report summarization, page/evidence tracking, defect extraction, unknown fields, negation handling and explicit review.

REPORT ID	REFERENCE DATE	DEMO CORRIDOR
DEMO-MR-26027-041	16 Oct 2026	Mumbai CSMT - Pune Jn (simulated)
DOCUMENT TYPE	**INPUT MODALITIES**	**INTENDED USE**
Multi-department inspection	Text + 3 supplied photos	AI-1 extraction testing

REPORT SUMMARY (SIMULATED TEXT)

This demonstration report contains three reported maintenance findings: a damaged rail joint, a track-tamping requirement, and an intermittent signalling/interlocking issue. It also records one explicitly negative observation and one unresolved vibration report. Three user-supplied photographs are included as reference attachments; their capture dates and locations have not been verified.

FINDING D-01 | WELD_FAILURE

REPORTED VALUES

DEPARTMENT	TMS
DEFECT TYPE	WELD_FAILURE (reported)
LOCATION	KM 67.5, DN
SEVERITY	84 / 100 (reported)
DUE DATE / OVERDUE	24 Sep 2026 / 22 days
ACTIVE TSR	Yes - 30 km/h (reported)
REPORTED DURATION	60 minutes (estimate)



ATTACHMENT A - USER-SUPPLIED RAIL-JOINT PHOTO

Photo shows battered/chipped rail ends at a joint. The source location and capture date are unverified; do not assume it depicts KM 67.5 DN. Confirm the link to D-01 during review.

Evidence excerpt: “A rail-joint defect is reported at KM 67.5 on DN. Reported category: WELD_FAILURE. Severity: 84/100. Due date: 24 September 2026. Reference date: 16 October 2026. Active TSR: yes, 30 km/h.”

Reported maintenance duration is evidence only; planner duration remains governed by existing DEFECT_TYPE_SPEC.

Finding 02 - Track Condition

Second positive finding. This record is deliberately close to D-01 in chainage but has a different defect type, so proximity alone must not delete it.

FINDING D-02 | TAMPING_REQUIRED

DEPARTMENT	TMS
DEFECT TYPE	TAMPING_REQUIRED (reported)
LOCATION	KM 68.2, DN
SEVERITY	58 / 100 (reported)
DUE DATE / OVERDUE	04 Oct 2026 / 12 days
ACTIVE TSR	No - explicitly recorded

Evidence excerpt

“Track surface irregularity reported at KM 68.2 on DN. Maintenance category recorded by the reporting officer: TAMPING_REQUIRED. Severity: 58/100. Due date: 4 October 2026. Reference date: 16 October 2026. TSR status: No.”

Reported duration: 120 minutes (estimate only; not a replacement for the planner specification).

ATTACHMENT B - USER-SUPPLIED TRACK / BALLAST PHOTO



Visible context: track, sleepers and ballast are shown, with areas that appear exposed or uneven. This is a visual description only, not an engineering diagnosis.

Source limitation: the photo was provided with this demo report, but its chainage and capture date are not verified. The report text supplies the simulated D-02 location and category; the photo must not independently establish those fields.

Finding 03 – Signalling / Interlocking

This finding intentionally has an unknown TSR status. AI-1 should keep it visible for review instead of assuming “No”.

FINDING D-03 | SIGNAL_INTERLOCK

DEPARTMENT	SMMS
DEFECT TYPE	SIGNAL_INTERLOCK (reported)
LOCATION	KM 9.4, UP_FAST
SEVERITY	63 / 100 (reported)
DUE DATE / OVERDUE	10 Oct 2026 / 6 days
ACTIVE TSR	NOT STATED - UNKNOWN

Evidence excerpt

“Intermittent signal interlocking indication reported at KM 9.4 on UP_FAST. Reported category: SIGNAL_INTERLOCK. Severity: 63/100. Due date: 10 October 2026. Reference date: 16 October 2026. The report does not state whether an active TSR is in force.”

ATTACHMENT C - USER-SUPPLIED CABLE-WORK PHOTO



The photo shows workers handling cables in a railway work area. The image does not, by itself, establish a signal/interlocking failure or confirm that the work occurred at KM 9.4 UP_FAST. Treat it as an unverified context attachment, not proof of the reported defect.

Review requirement: D-03 must remain NEEDS_REVIEW until the TSR field is explicitly confirmed by an authorized reviewer. No TSR value should be inferred from the photograph.

Additional Observations & Field Register

This page tests negation handling, uncertain language and the difference between a recorded finding and a confirmed schedulable defect.

OBSERVATION N-01 - EXPLICITLY NEGATIVE

“No rail fracture was observed at KM 67.1 on DN during the visual inspection. No fracture was recorded at this location in this observation.”

Recorded status: Negative finding. This statement must not create a positive RAIL_FRACTURE defect.

OBSERVATION A-01 - INCOMPLETE / AMBIGUOUS

“Vibration was reported near KM 69.0 on DN. The cause has not been determined. The report does not identify a confirmed defect type, numeric severity, due date, days overdue, or TSR status.”

Expected data handling: retain it as a NEEDS_REVIEW observation. Do not invent a defect type or numeric score; do not send it to the scheduler.

SIMULATED FIELD REGISTER

ID	REPORTED TYPE	LOCATION	SEVERITY	TSR	REVIEW NOTE
D-01	WELD_FAILURE	KM 67.5 DN	84/100	Yes, 30 km/h	Photo location unverified
D-02	TAMPING_REQUIRED	KM 68.2 DN	58/100	No	Different type from D-01
D-03	SIGNAL_INTERLOCK	KM 9.4 UP_FAST	63/100	Unknown	Needs review
N-01	Negative finding	KM 67.1 DN	Unknown	Unknown	Do not create defect
A-01	Not confirmed	Near KM 69.0 DN	Unknown	Unknown	Needs review

Important: all report identifiers, locations, dates, severity values and narrative findings are simulated data prepared for software testing. The three photographs were supplied by the user; their source, capture date, location and association with the simulated findings have not been independently verified. This is not a real railway inspection or an authorization to perform maintenance.