

OSHA Report **Arnie Bauer** **Chevrolet** **GMC**

Complete On: 8/26/2024

Report Created By:

Jim Perschke

847-975-2324

jperschke@autorisknow.com

Forklift Operators Certifications not available


Date of occurrence: August 26, 2024

No Certifications according to Mike

All secondary containers filled with chemicals are not properly labeled.

Date of occurrence: August 26, 2024

Found secondary containers with liquids un-labeled



The eye wash equipment is not readily accessible.

Date of occurrence: August 26, 2024

No eyewash stations

Fire Extinguisher missing or not properly mounted in dispensing area

Date of occurrence: August 26, 2024

Found Extinguishers not mounted and sitting on floor



The fire extinguisher signs above the unit are not posted properly.

Date of occurrence: August 26, 2024

All extinguishers need signage



There is not clear access of at least 36" to all electrical panels.

Date of occurrence: August 26, 2024

Main throw switch is blocked by refrigerator



All vacant holes are not properly sealed off on electrical panel box.

Date of occurrence: August 26, 2024

accounting office and service breaker panels need vacant holes sealed



The fluorescent tubes are not stored properly.

Date of occurrence: August 26, 2024

potential breaking of fluorescent tubes under weight of fender flairs



Storage Containers not capped and or sealed properly

Date of occurrence: August 26, 2024


found containers outside that will potentially fill with rainwater



Electrical Plugs Outlets not properly covered. Plate cover missing or broke

Date of occurrence: August 26, 2024

Found cover missing in attic storage area



Used Batteries not stored on acid resistant matts

Date of occurrence: August 26, 2024

need to place acid resistant mat under used batteries



Hoists are not being maintained within mfg. specs, and inspected and serviced AND documented under the mfg. suggested frequency. Usually annually.

Hoists are missing inspection sticker

There is no proper spacing on grinders; Tool rest 1/8" from grinding wheel. Tongue plate 1/4" from grinding wheel.

Date of occurrence: August 26, 2024

Grinders need tool rest adjustment



All tanks holding flammable material are not properly grounded.

Date of occurrence: August 26, 2024

Tanks holding flammable liquid should be grounded

