

OSHA Report Quality Chrysler Dodge Jeep Ram of Greenwood

Complete On: 9/04/2024

Report Created By:

Tom Dortch

815-404-8681

tomdortch@autorisknow.com

All electrical cords are not in good working order (none frayed, cracked, taped, or spliced or ground missing on 3 prong plugs).

Electrical cord on last lift on right side is frayed



All the Fire Extinguishers are not easily accessible.

Unable to get to fire extinguisher on right side of shop



All secondary containers filled with chemicals are not properly labeled.

Label not able to be read; must have labels on all secondary containers



There is no proper spacing on grinders; Tool rest 1/8” from grinding wheel. Tongue plate 1/4” from grinding wheel.

High Risk

All safeguards missing




All secondary containers filled with chemicals are not properly labeled.

Labeling missing on bottles in detail area; spoke with George



All electrical cords are not in good working order (none frayed, cracked, taped, or spliced or ground missing on 3 prong plugs).

Electrical cord on lift is frayed



All electrical cords are not in good working order (none frayed, cracked, taped, or spliced or ground missing on 3 prong plugs).

Even though not plugged in, can still be plugged in and cord is frayed

